

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

24 Centralizers run on Casing string at following points:
7646', 7601', 7561', 7521', 7481', 7437', 7397', 7353', 7312', 7271',
7230', 7189', 7147', 7106', 5679', 5601', 5562', 5521', 5480', 5440',
5401', 5361', 3655' and 3576'.

Cemented 5 1/2" Casing in 3 Stages.

1st Stage thru shoe at 7687' with 412.50 Cu.Ft. (250 sacks)
50-50 Poz, 6% Gel, 12 1/4# Gilsonite per sack followed by
118 Cu.Ft. (100 sacks) Neat Cement.
Plug down 1st Stage 11:42 PM 7-29-83

2nd Stage cemented thru Stage Tool set at 5600' with 412.50
Cu.Ft. (250 sacks) 50 50 Poz, 6% Gel, 12 1/4# Gilsonite per
sack followed by 118 Cu.Ft. (100 sacks) Neat Cement.
Plug down 2nd Stage 1:07 AM 7-30-83

3rd Stage cemented thru Stage Tool set at 3578' with 825
Cu.Ft. (500 sacks) 50-50 Poz, 6% Gel, 12 1/4# Gilsonite
per sack followed by 118 Cu.Ft. (100 sacks) Neat Cement.
Plug down 3rd Stage 2:51 AM 7-30-83

Cement circulated on all three Stages.

Approx 2 bbls. slurry on 1st Stage.
Approx 1 bbl. slurry on 2nd Stage.
Approx 5 bbls slurry on 3rd Stage.