

submitted in lieu of Form 3160-5

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED
BLM

99 MAY 26 AM 10:15

Sundry Notices and Reports on Wells

070 FARMINGTON, NM

1. Type of Well
GAS

5. Lease Number
SF-080671-A
6. If Indian, All. or
Tribe Name

2. Name of Operator

**BURLINGTON
RESOURCES** OIL & GAS COMPANY

RECEIVED
JUN 21 1999
OIL CON. DIV.
DIST. 3

7. Unit Agreement Name
San Juan 27-4 Unit

3. Address & Phone No. of Operator

PO Box 4289, Farmington, NM 87499 (505) 326-9700

8. Well Name & Number
San Juan 27-4 U #33

9. API Well No.
30-039-23710

4. Location of Well, Footage, Sec., T, R, M

1515'FSL, 910'FEL, Sec.11, T-27-N, R-4-W, NMPM

10. Field and Pool
Blanco Mesaverde

11. County and State
Rio Arriba County, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission	Type of Action	
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Abandonment	<input type="checkbox"/> Change of Plans
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion	<input type="checkbox"/> New Construction
<input type="checkbox"/> Final Abandonment	<input type="checkbox"/> Plugging Back	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> Water Shut off
	<input type="checkbox"/> Altering Casing	<input type="checkbox"/> Conversion to Injection
	<input checked="" type="checkbox"/> Other - Tubing Repair	

13. Describe Proposed or Completed Operations

It is intended to repair the tubing in the subject well according to the attached procedure.

14. I hereby certify that the foregoing is true and correct.

Signed [Signature] Title Regulatory Administrator Date 5/26/99
trc

(This space for Federal or State Office use)
APPROVED BY /s/ Duane W. Spencer Title Team Lead, Petroleum Management Date JUN 16 1999

CONDITION OF APPROVAL, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

NMOC

San Juan 27-4 Unit #33
Mesa Verde
1515' FSL and 910'FEL
Unit I, Section 11, T27N, R4W
Latitude / Longitude: 36° 35.0601' / 107° 12.8522'
DPNO: 5406501
Tubing Repair Procedure

Project Summary: The San Juan 27-4 Unit #33 was drilled in 1985 and is currently shut-in. The tubing was last pulled during a Cliffhouse pay-add in 1996. We propose to pull the tubing, check for fill, replace any worn or scaled tubing and add a plunger lift.

1. Hold safety meeting. Comply with all NMOCD, BLM and Burlington safety and environmental regulations. Test rig anchors and build blow pit prior to moving in rig. **Notify BROG Regulatory (Peggy Bradfield 326-9727) and the appropriate Regulatory Agency prior to pumping any cement job. If an unplanned cement job is required, approval is required before the job can be pumped. If verbal approval is obtained, document approval in DIMS/WIMS.** Allow as much time as possible prior to pump time in case the Agency decides to witness the cement job.
2. MOL and RU workover rig. Obtain and record all wellhead pressures. NU relief line. Blow well down and kill with 2% KCL water if necessary. NU BOP with stripping head. Test and record operation of BOP rams. Have wellhead and valves serviced as necessary. Test secondary seal and replace/install as necessary.
3. The Mesa Verde tubing is 2-3/8", 4.7#, J-55 set at 6260'. Release donut, pick up additional joints of tubing and tag bottom (record depth.) PBSD should be at +/- 6314'. TOOH with tubing. Visually inspect tubing for corrosion and replace any bad joints. Check tubing for scale build up and notify Operations Engineer.
4. If fill covers any perforations then TIH with 3-7/8" bit and a watermelon mill on 2-3/8" tubing to below perforations, cleaning out with air/mist. PU above the perforations and flow the well naturally, making short trips for clean up when necessary. TOOH with tubing. **NOTE: When using air/mist, minimum mist rate is 12 bph.**
5. TIH with one joint of 2-3/8" tubing with an expendable check on bottom and a seating nipple one joint off bottom. Run a broach on sandline to insure that the tubing is clear. Land tubing at approximately 6250'. ND BOP and NU WH. Pump off expendable check. Connect to casing and circulate air to assure that expendable check has pumped off. If well will not flow on it's own, make swab run to SN. RD and MOL. Return well to production.
6. Production operations will install the plunger lift.

Recommended: *T. Friesenhahn* 5-11-99
Operations Engineer

Approved: *Bruce W. Boye* 5-21-99
Drilling Superintendent

Tim Friesenhahn
Office - 326-9539
Pager - 324-7031