

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)

Form approved,
Budget Bureau No. 1004-C1
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL

NM-02901

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐
2. NAME OF OPERATOR
Southern Union Exploration Company
3. ADDRESS OF OPERATOR
P. O. Box 2179 Farmington, NM 87499
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
1830' FSL & 1000' FWL

14. PERMIT NO.
15. ELEVATIONS (Show whether DF, RT, GR, etc.)
6523' GR

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Foster

9. WELL NO.

#3

10. FIELD AND POOL OR WILDCAT

Basin Dakota
11. SEC., T., S., M., OR BLK. AND
SURVEY OR AREA

Sec 24-T26N-R8W

12. COUNTY OR PARISH 13. STATE

San Juan

NM

10. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.) *

8 5/8", 24#, J-55 @ 307'

4 1/2", 11.6#, J-55 @ 6970'

Perfed 6786'-6864', 6676'-6768'

1 1/2" EUE tbq @ 6828'

1. MIRU well servicing unit.

2. Pull tubing to 6500', spot 45 sks.

3. Perforate 4 holes at 3896' and squeeze with 25 sks of cement and place
15 sks cement plug inside casing from 3996' to 3796'.

4. Spot 15 sks cement plug at 2420'-2220'.

5. Spot 15 sks plug 1792'-1592'.

6. Pull tubing to 300', spot 25 sks plug 300' to surface.

7. Cut wellhead off. Install P & A marker as per BLM specifications.

8. Well Plugged and Abandoned.

Approved as to proposed work and
Liability under the Act
surface restoration is completed.

18. I hereby certify that the foregoing is true and correct

SIGNED

Walter B. Bagg

TITLE Drilling & Production Supt.

DATE Aug. 14, 1987

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

*See Instructions on Reverse Side