#### UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

	APPLICATIO	N FOR PERMIT TO DR	III D	EEPEN, OR	PLUG BACK
	TYPE OF WORK PLUG BACK TYPE OF WELL GAS	OCT1 7.1990.	6.	LEASE NUM USA-SF-07 IF INDIAN	
2.	OPERATOR MERIDIAN OIL INC.	OIL CON. DI		UNIT AGRE	EMENT NAME O UNIT
3.	ADDRESS & PHONE NO. OF P.O. BOX 4289 FARMINGTON, NM 87499 (505) 326-9700	F OPERATOR		FARM OR I	EASE NAME
4.	LOCATION OF WELL 1590' FNL; 880' FEL		ļ	BASIN FRU	OL, OR WILDCAT ITLAND COAL . M OR BLK. T26N, R09W
14.	DISTANCE IN MILES FROM	M NEAREST TOWN	12.	COUNTY SAN JUAN	13. STATE NM
15.	DISTANCE FROM PROPOSED LOCATION TO NEAREST PROPERTY OR LEASE LINE.	16. ACRES IN I	LEASE		RES ASSIGNED TO WELL
18.	DISTANCE FROM PROPOSED LOCATION TO NEAREST WELL DR. COMPL., OR APPLIED FOR ON THIS LEASE.	19. PROPOSED D	ЕРТН	20. RO	TARY OR CABLE TOOLS
21.	ELEVATIONS (DF, FT, GF 6198' DF	R, ETC.)	22	. APPROX.	DATE WORK WILL START
23.	PROPOSED CASING AND CEMENTING PROGRAM				
24.	AUTHORIZED BY: REGULATO	*SEE OPERATIONS P Malfiel (SHL) ORY AFFAIRS			<u>8-29-9</u> <b>DATE</b>
PERMI	TT NO.	APPROVAL DATE			
	OVED BY				
NOTE:		ED IN LIEU OF US BL WORK WILL BE REQUI	M FORI	M 3160-3.	
	OK	THE PARTY			AREA MANAGER

- Wells

Schmit to Asymptome District Office State Lease - 4 comes Fee Lease - 3 comes

# State of New Mexico. Energy, Minerais and Natural Resources Department

Form C-102 Reviews below

DISTRICT! P.O. Box 1980, Hobbs, NM 88340

#### OIL CONSERVATION DIVISION P.O. Box 2088

P.O. Drawer DD, Artesia, NM 88210

330 660 990 1320 1650 1900 2310 2640

Santa Fe, New Mexico: 87504-2088


WELL LOCATION AND ACREAGE DEDICATION PLAT 1000 Rio Brance Rd., Azzec, Ned. 87410 All Distances must be from the outer boundaries of the section Paso Natheri Company Gas Huerfanito Unit (SF-078388) Unit Later 66 Town 12 26 Morth 9 West Actual Footnes Location of Well: San Juan NMPM 1590 feet from the North 880 line and Catholic level Start. Produces Form feet from the East Pool 61881 Fruitland Coal Basin 1. Outline the acreege dedicated to the subject well by colored pencyl or hackure marks on the pist below. 320 2. If more than one tense is dedicated to the well, outline each and identify the ownership thereof (both as to working interest and royalty). 3. If store than one them of different ownership is dedicated to the well, have the interest of all owners been consolidated by communication. \_k Yee ☐ No If answer as "yes" type of consolidation unitization If manner is "so" list the coveres and tract descriptions which have actually been conncidened. (Use reverse ade of ngmed to the wed until all interests have been consolidated (by communication, unstables, forced-pooling, or otherwise) or ustal a non-standard test, eliminating such inte ist, has been approved by the Division. OPERATOR CERTIFICATION Note: not resurveyed I hereby certify that the informataken from plat by Ernest V. Echohawk DARI 8-26-54 Peggy Bradfield Regulatory Affairs **O** · Paso Natural Gas 880' SURVEYOR CERTIFICATION DECEINED I hereby certify that the-well locati on this plat was platted from field nates c actual surveyo made by me or unde ervison, and that the same is true on correct to the best of my knowledge an. WEIR 6857 

### RECOMPLETION PROCEDURE HUERFANITO UNIT #66


\*\*\*NO WORK IS TO BE PERFORMED OR EQUIPMENT TO BE LOCATED OFF APPROVED WELL PAD\*\*\*

- 1. Prepare location for workover. Install or replace anchors as necessary.
- 2. MOL with workover rig, hold safety meeting, install safety signs and proper fire equipment at strategic points. Comply with all BLM, NMOCD, and MOI regulations.
- 3. Rig up blow lines, record tubing and casing pressures and blow well down. NU 6" 3000 psi BOP and test. Load hole with water.
- 4. TOOH with 1" tubing.
- 5. RU wireline unit and set a CIBP near 1882'. Pressure test casing to 1000 psi for 15 minutes.
- 6. Run logs.
- 7. Perforate coal interval. Perforations to be picked from log.
- 3. TIH with tubing and swab wellbore dry. Check well for gas flow. Evaluate well overnight. Fracture stimulate if necessary. Check well for buildup pressure and gas flow. Land tubing. Swab well in. Record final 30, 45 and 60 minute gauges on morning report. ND BOP. NU tree. Rig down and release rig.
- 9. Shut well in for pressure build up. Obtain gas and water sample for analysis.

## HUERFANITO UNIT #66 WELLBORE DIAGRAMS



# WORKOVER / RECOMPLETION B.O.P. SCHEMATIC



MINIMUM: 6" 2000 PSI DOUBLE GATE B.O.P.

MAXIMUM ANTICIPATED SHUT-IN WELLHEAD

PRESSURE IS LESS THAN 2000 PSI