## State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division

	Sundry Notices and F	Reports on Wells		
		API	# (assigned by OCD) 30-045-06004	
1. Type of Well GAS		5.	Lease Number	
		- 6.	State Oil&Gas Lease # B-11122-2-NM	
2. Name of Operator		7.	Lease Name/Unit Name	
RESOURCES OIL &	GAS COMPANY	8.	Huerfanito Unit	
3. Address & Phone No. of Operat	or	_	17	
PO Box 4289, Farmington, NM	87499 (505) 326-9700	9.	Pool Name or Wildcat Ballard Pictured Clift	
4. Location of Well, Footage, Se			Elevation:	
990'FSL 1650'FWL, Sec.2, T-26	-N, R-9-W, NMPM, San	Juan County		
Type of Submission	Type of A			
_X_ Notice of Intent	_X_ Abandonment Recompletion	Change of Pl New Construc		
Subsequent Report	<del>-</del>	Non-Routine		
		Water Shut o		
Final Abandonment	Altering Casing Other -	Conversion C	o injection	
It is intended to plug and attached procedure	•	well according to the second s		
SIGNATURE JANG MICH A PRICE A			January 15, 1999	
(This space for State Use)			IANI SECONO	
DRIGINAL SIGNED BY ERN	TE BUSCHE TITLE	as inspector, dist. #	3 JAN 2 1 199	

## PLUG AND ABANDONMENT PROCEDURE

01/11/99

## Huerfanito Unit #17

Ballard Pictured Cliffs 990' FSL and 1650' FWL, Sec. 2, T26N, R9W San Juan County, New Mexico

Note: All cement volumes use 100% excess outside pipe and 50' excess inside pipe. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures.

- 1. Install and lest rig anchors. Prepare blow pit. Comply with all NMOCD, BLM and Burlington safety rules and regulations.
- 2. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on location. NU relief line to flow back tank. Blow well down; kill with water as necessary. ND wellhead and NU BOP and stripping head; test BOP.
- 3. POH and tally 52 joints 2.9# 1-1/2" EUE tubing (1725'); visually inspect the tubing. If necessary LD tubing and PU workstring.
- 4. Plug #1 (Pictured Cliffs open hole interval and Fruitland top, 2043' 1700'): Set 5-1/2" wireline cement retainer at 1750'. TIH with tubing and sting into retainer. Load casing with water and circulate clean. Pressure test casing to 500#. If casing does not test, spot or tag subsequent plug as appropriate. Sting into retainer then mix and pump 54 sxs Class B cement, squeeze 48 sxs below retainer into open hole to isolate PC interval and to cover Fruitland top; then spot 6 sxs above retainer. POH with tubing.
- 5. Plug #2 (Kirtland and Ojo Alamo tops, 1400' 1145'): Perforate 3 HSC squeeze holes at 1400'. Establish rate into squeeze holes if casing tested. Set 5-1/2" cement retainer at 1350'. Establish rate under retainer into squeeze holes. Mix 111 sxs Class B cement, squeeze 75 sxs cement outside 5-1/2" casing and leave 36 sxs cement inside casing to cover Ojo Alamo interval. POH and LD tubing.
- 6. Plug #3 (8-5/8" Casing Shoe at 102') Perforate 3 HSC squeeze holes at 152'. Establish circulation out bradenhead valve. Mix and pump approximately 50 sxs Class B cement down 5-1/2" casing from 152' to surface, circulate good cement out bradenhead valve. Shut in well and WOC.
- 7. ND BOP and cut off well head below surface casing flange. Install P&A marker with cement to comply with regulations. RD, MOL and cut off anchors. Restore location per BLM stipulations.

Recommended:

Approval:

perations Enginee

Drilling Superin

me . Doy