

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED
BLM

Sundry Notices and Reports 95 AUG 14 AM 9:03

1. Type of Well
GAS

2. Name of Operator
MERIDIAN OIL

3. Address & Phone No. of Operator
PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M
1850' FNL, 790' FWL, Sec.13, T-26-N, R-9-W, NMPM

070 FARMINGTON, NM

5. Lease Number
NM-09840
6. If Indian, All. or
Tribe Name
7. Unit Agreement Name
8. Well Name & Number
Tibbar Federal #1
9. API Well No.
30-045-11676
10. Field and Pool
Basin Dakota
11. County and State
San Juan Co, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

Type of Action

- | | | |
|--|---|--|
| <input checked="" type="checkbox"/> Notice of Intent | <input type="checkbox"/> Abandonment | <input type="checkbox"/> Change of Plans |
| <input type="checkbox"/> Subsequent Report | <input type="checkbox"/> Recompletion | <input type="checkbox"/> New Construction |
| <input type="checkbox"/> Final Abandonment | <input type="checkbox"/> Plugging Back | <input type="checkbox"/> Non-Routine Fracturing |
| | <input type="checkbox"/> Casing Repair | <input type="checkbox"/> Water Shut off |
| | <input type="checkbox"/> Altering Casing | <input type="checkbox"/> Conversion to Injection |
| | <input checked="" type="checkbox"/> Other - Bradenhead repair | |

13. Describe Proposed or Completed Operations

It is intended to repair the bradenhead of the subject well according to the attached procedure and wellbore diagram.

RECEIVED
AUG 23 1996
OIL CON. DIV.
DIST. 3

14. I hereby certify that the foregoing is true and correct.

Signed *Regina Bradenhead* (ROS1) Title Regulatory Administrator Date 8/12/96

(This space for Federal or State Office use)

APPROVED BY _____ Title _____ Date _____

CONDITION OF APPROVAL, if any:

APPROVED

AUG 19 1996

A
DISTRICT MANAGER

NMOCD

BRADENHEAD REPAIR PROCEDURE

8-1-96

Tibbar Federal #1
Basin Dakota
NW Section 13, T-26-N, R-9-W
San Juan Co., New Mexico
Latitude/Longitude: 36.490189 / 107.746658
DPNO 51580A

1. Comply with all NMOCD, BLM and Burlington safety and environmental regulations. Conduct daily safety meetings for all personnel on location.
2. Test location rig anchors and repair if necessary. Prepare blow pit. MOL and RU daylight pulling unit. Blow well down. NU 7-1/16" 3000 psi (6" 900 series) with stripping head. Test and record operation of BOP rams. Kill well with 1% KCL water only if necessary. Have wellhead inspected at A-1 Machine or WSI, if needed.
3. RIH, tag bottom and record depth. TOH and tally 207 joints 2-3/8", EUE, tubing @ 6563' (Bar collar on bottom). Note any buildup of scale and notify Operations Engineer.
4. PU 3-7/8" bit and 4-1/2" casing scraper and TIH with tubing to 6597', or below Dakota perforations. TOH w/bit and scraper. PU 4-1/2" RBP and RIH with 2-3/8" tubing, set at 6300'. Roll hole w/1% KCL water. Pressure test casing to 1000#. Spot 10' of sand on top of RBP. TOH.
5. RU wireline unit. Run CBL (with 1000# pressure) to determine TOC behind 4-1/2" casing. Contact Operations Engineer (Rob Stanfield 326-9715, Pager 324-2674) for design of cement squeeze procedure. **Notify BROG Regulatory (Peggy Bradfield 326-9727) and the appropriate Regulatory Agency prior to pumping any cement job. If an unplanned cement job is required, approval is required before the job can be pumped. If verbal approval is obtained, document the approval in DIMS/WIMS. As much time as possible to the pump time is needed for the Agency to be able to show up for the cement job.**
6. WOC 12 hrs. Clean out to below squeeze with 3-7/8" mill or bit. Pressure test to 750 psig. Re-squeeze as necessary.
7. TIH with 4-1/2" casing scraper to below squeeze. TOH. TIH with retrieving tool on 2-3/8" tubing blowing down with gas or air. Retrieve RBP and TOH.
8. TIH with 2-3/8" tubing with a notched expendable check valve on bottom and a seating nipple one joint off bottom. Clean out COTD @ 6624'. Take and record gauges.
9. Land tubing near bottom perforation at 6597'. ND BOP and NU wellhead. Pump off expendable check valve and record final gauges. RD rig and equipment and move off location. Return well to production.

Recommend:


Operation Engineer

Approve:

 8/9
Drilling Superintendent