

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 02874-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Huerfano Unit

8. FARM OR LEASE NAME

Huerfano Unit

9. WELL NO.

151-Y

10. FIELD AND POOL, OR WILDCAT

Undes. Gallup

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREASec. 35, T-26-N, R-10-W
NMPM

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6783'GL

12. COUNTY OR PARISH

San Juan

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☐
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐
☐

REPAIRING WELL

☐
☐
☐
☒

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

The Dakota perforations (6740-60') were plugged by setting a cement retainer at 6620' and squeezing with 75 sks. of cement. The well was then completed in the Gallup formation. Due to no production, it has now been permanently plugged in the following manner:

Gallup perforations from 5938-6066' were plugged by spotting a 75 sk. cement plug at 6100'. Tubing stuck in cement, found tubing free at 5000'. Could not get down inside tubing to cut off. Backed off tubing at 3000'.

Spotted 75 sk. cement plug from 1280-2250'.

Found free point of 4 1/2" casing, shot off and recovered 800' of casing.

Spotted a 25 sk. cement plug on the casing stub.

Spotted a 25 sk. cement plug at the base of the surface casing at 218'.

Placed a 15 sk. cement plug at the surface, installed dry hole marker.

Note: location has not been cleaned and leveled. Another subsequent report will be filed after this work has been done.

18. I hereby certify that the foregoing is true and correct

SIGNED

L.A. Amies

TITLE

Petroleum Engineer

DATE

October 9, 1973

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

OCT 11 1973