UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Notices and	Reports on Wel	ી ^s સ 2: 45		
1. Type of Well GAS		The state of the s	5. 6.	Lease Number SF-079658 If Indian, All. or Tribe Name
2. Name of Operator			7.	Unit Agreement Name Huerfano Unit
BURLINGTON RESOURCES OIL & GAS CO.	MPANY			
3. Address & Phone No. of Operator	(505) 226 0700	-	8.	Well Name & Number Huerfano Unit #211 API Well No.
PO Box 4289, Farmington, NM 87499 4. Location of Well, Footage, Sec., T, I		-		30-045-20778 Field and Pool
1550'FNL, 1500'FWL, Sec.10, T-26-N, I				Basin Dakota KL County and State San Juan Co, NM
12. CHECK APPROPRIATE BOX TO INDICATE N	ATURE OF NOTICE	REPORT,	OTHER	DATA
Subsequent Report Plu Cas Final Abandonment Al	completion _ ugging Back _ sing Repair _ tering Casing _ her	Water S	tine :	Fracturing
It is intended to recomplete the attached procedure and wellbore d	subject well to	o the Gallu	p for	mation according to th
	e <u>Regulatory A</u>	dministrato		
CONDITION OF ADDROVAL if any	'itle			11/20/39
ACTION OF APPROVAL, IT ally:	ruffe Callup 1	Assoi N	54	

District I PO Box 1980, Hobbs, NM 88241-1980 State of New Mexico
Energy, Minerals & Natural Resources Department

Form C-102 Revised February 21, 1994 Instructions on back

District II

OIL CONSERVATION DIVISION PO Box 2088 Santa Fe, NM 87504-2088

Submit to Appropriate District Office State Lease - 4 Copies

District III 1000 Rio Bruzos Rd., Aztec. NM 87410 District IV

PO Drawer OD, Artesia, NM 88211-0719

Fee Lease - 3 Copies

District IV PO Box 2088, San	ta Fe, NM	87504-2088			,						AMEI	NDED REPORT
		WEI	T T ()	CATION	IAND	ACR	EAGE DE	, Dica	TION PI	AT		
	Pl Numbe		T	Pool Code		T	LAGE DE	Dich) Pool Nu	me	-	
30-045	0-045-20778 2170/71599 Angels Peak Gallu						lup/Bas	sin Da	akota	;		
' Property 713		' Pro					ropeny Name erfano Unit				· Well Number 211	
OGRID No. Operator Num					ator Name			* Elevation				
1453	Burlington Resources Oil & Gas Compa						Company		672	1' GR		
					10 Sur	face	Location		·	,		,
UL or lot no.	Section	Township	Range	Lot Idn	Feet from	n the	North/South	ine Fo	et from the	East/Wes	t line	County
F	10	26N	10W		1550		North		500	West	<u> </u>	SJ
			11 Bot				f Different			East/We		I desired
UL or lot no.	Section	Township	Range	Lot Idn	Feet from	n the	North/South	Line F	eet from the	EASUWE	st une	County
Gal-W/32	20		onsolidatio		Order No.	N ETI	ON LINETH	ALL INT	TEDESTS H	LAVE RE	FN CO	NSOLIDATED
NO ALLO	WABLE	WILL BE A.	SSIGNE ION-ST	ANDARD	IS COME UNIT H	IAS B	EEN APPRO	VED B	Y THE DIV	ISION	LIV CO.	NOOLIDATED
15		,0357		Ori	ginal	pl Vi	at from lven 12-	-30-7	Signature Peggy Printed Nate Title Date 18 SURV I hereby cer was pioued or under my correct to the	Cole tory VEYOR Information of my	Admin Admin CER well location and that is belief.	CONTAINED THE STATE OF THE STRATE OF THE STR
									Certificate I	Number	· 	

HUERFANO UNIT #211 GALLUP

Recompletion Procedure F 10 26 10

San Juan County, N.M. Lat-Long: 36-30.34" - 107-53.21"

PROJECT SUMMARY: Plugback this 1971 depleted Dakota well to the Gallup Tocito and foam frac.

- 1. Comply to all NMOCD, BLM, and BROG rules and regulations. MOL and RU completion rig. NU BOP w/flow tee and stripping head. Test operation of rams. NU blooie line and 2-7/8" relief line.
- 2. Set blanking plug in S.N. of 2-3/8" tbg @ 6919' and pressure test tbg to 3000 psi. TOH w/2-3/8" tbg (228 Jts).
- 3. Run 4-1/2" csg scraper on 2-3/8" tbg to 6725'. TOH. Run 4-1/2" cmt retainer on 2-3/8" tbg and set @ 6725'. Sq DK perfs w/33 sx cl "G" cmt . This will fill inside the pipe from 6725' to 6942' w/100% excess cmt. Sting out of ret and spot 5 sx cmt on top of cmt ret @ 6700'. Reverse out cmt. Close pipe rams and pressure test 4-1/2" csg to 300 psi. TOH.
- 4. MI wireline. Set 4-1/2" top drillable BP @ 6300'. Run CBL from 6300' to top of cmt and from DV tool @ 5057' to top of cmt. **Do not pressure csg above 300 psi.**
- 5. Perf Tocito w/2 spf from 6168'-84'. Total 32 holes. Perf using 3-1/8" hollow steel carrier guns loaded w/Owen HSC 13 gm. charges phased at 180 degrees. Average perf dia. = 0.48". Average penetration is 18" in Berea.
- 6. Fill 3 400 bbl. frac tanks with 1% KCL water. If necessary, filter all water to 25 microns. Two tanks are for gel and one tank for breakdown water. Usable gel water required for frac is 403 bbls.
- 7. TIH w/4-1/2" pkr on 2-7/8" 6.5# N-80 w/shaved collars (3.5" O.D. 2.441" I.D.) rental frac string (run 2 jts 2-3/8" N-80 on top of pkr).and set @ 6000'. Prepare to frac.
- 8. W/300 psi on annulus, breakdown Tocito perfs w/1500 gal 15% HCL acid and frac down frac string w/55,000 gals. of 70 quality foam using 20# gel as the base fluid and 100,000# 20/40 Arizona sand. Pump at 25 BPM. Monitor bottom hole and surface treating pressures, rate, foam quality, and sand concentration with computer van. Sand to be tagged w/ 3 RA isotope tracers. Max. pressure is 6000 psi and estimated treating pressure is 5830 psi. Pipe friction @ 25 BPM is 4430 psi. Treat per the following schedule:

	Foam Vol.	Gel Vol.	Sand Vol.
Stage	<u>(Gals.)</u>	<u>(Gals.)</u>	<u>(lbs.)</u>
Acid - 1500 gal	15% HCL		
Pad	15,000	4,500	
1.0 ppg	10,000	3,000	10,000
2.0 ppg	10,000	3,000	20,000
3.0 ppg	10,000	3,000	30,000
4.0 ppg	10,000	3,000	40,000
Flush	(1,460)	(438)	0
Totals	55,000	16,500	100,000#

Treat frac fluid w/the following additives per 1000 gallons:

* 20# J-48

(Guar Gel mix in full tank - 16,000 gal)

* 1.0 gal. Agua Flow

(Non-ionic Surfactant mix in full tank)

* 1.0# GVW-3

(Enzyme Breaker mix on fly)

* 1.0# B - 5

(Breaker mix on fly)

* 3.0 gal Fracfoam I

(Foamer mix on fly)

* 0.38# FracCide 20

(Bacteriacide mix on full tank)

All acid on this well to contain the following additives per 1000 gal:

2 gal CI-22

corrosion inhibitor

5 gal Ferrotrol-300L

iron control

1 gal Flo-back 20

Surfactant

o Sarat Olara Marata

Sunactant

0.5 gal Clay Master-5C

clay control

- 9. Open well through choke manifold and monitor flow. Flow @ 20 bbl/hr. or less, if sand is observed. Take pitot gauges when possible. TOH w/pkr.
- 10. TIH w/notched collar on 2-3/8" tbg and C.O. to 6300' w/air/mist. Monitor gas and water returns and Take pitot gauges when possible.
- 11. When wellbore is sufficiently clean, TOH and run after frac gamma-ray log from 6300'-6000'.
- 12. TIH w/2-3/8" 4.7# J-55 EUE tbg w/standard seating nipple one joint off bottom and again cleanout to 6300'. When wellbore is sufficiently clean, land tbg @ 6180' KB. <u>Take final</u> water and gas rates.
- 13. ND BOP and NU wellhead and tree. Rig down and release rig.

Recommended:

Production Engineer

Approved:

Orilling Superintendent

Approved

Team Leader

VENDORS:

Wireline:

Basin

327-4472

Fracturing:

Howco

325-3575

RA Tag:

Pro-Technics

326-7133

PMP

HUERFANO UNIT #211 GALLUP

UNIT F SECTION 10 T26N R10W SAN JUAN COUNTY, NEW MEXICO

