

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☐ OIL WELL ☐ GAS WELL ☒ OTHER		5. LEASE DESIGNATION AND SERIAL NO. NM-0553884-A	
2. NAME OF OPERATOR Tenneco Oil Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR P.O. Box 3249, Englewood, CO 80155		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1180' FNL, 1500' FWL		8. FARM OR LEASE NAME Arroyo	
14. PERMIT NO.		9. WELL NO. 1	
15. ELEVATIONS (Show whether SP, ST, GR, etc.) 6089' GR		10. FIELD AND POOL, OR WILDCAT Wildcat	
		11. SEC., T., R., N., OR BLK. AND SUBSET OF AREA Sec. 25, T26N, R12W	
		12. COUNTY OR PARISH San Juan	
		13. STATE NM	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
(Other)

PLUG OR ALTER CASING
MULTIPLE COMPLETE
ABANDON*
CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF
FRACTURE TREATMENT
SHOOTING OR ACIDIZING
(Other)

REPAIRING WELL
ALTERING CASING
ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Tenneco requests permission to plug and abandon per the attached procedures.

the above referenced well

- * 1) Plug across Chacra 1750'-1650'
- 2) Bring Fractured Chacra / Furland plug up to 980'
- 3) Surface plug 674'-0'

RECEIVED
OIL CON. DIV.
88 FEB 23 PM 12:44
FARMINGTON RESOURCE AREA
FARMINGTON, NEW MEXICO

RECEIVED
MAR 03 1988
OIL CON. DIV.
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED

David Hiatt

TITLE Sr. Admin. Analyst

DATE 1/26/88

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE MAR 01 1988

AREA MANAGER

*See Instructions on Reverse Side

NMOCC

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

624

6779W/2/JWC

LEASE Arroyo Com

WELL NO. 1

CASING:

8-5/8 "OD, 24 LB, K-55 CSG W/ 350 SX

TOC @ surf . HOLE SIZE 12-1/4 DATE: 12/31/73

REMARKS _____

5-1/2 "OD, 15.5 LB, K-55 CSG W/ 185 SX

TOC @ 4500 . HOLE SIZE 7-7/8 DATE: 1/13/76

REMARKS temperature survey

"OD, _____ LB, _____ CSG W/ _____ SX

TOC @ _____ . HOLE SIZE _____ DATE: _____

REMARKS _____

TUBING:

2-7/8 "OD, 6.5 LB, J-55 GRADE, 8 RD, EUE CPLG

LANDED @ 4978' . SN, PACKER, ETC. _____

"OD, _____ LB, _____ GRADE, _____ RD, _____ CPLG

LANDED @ _____ . SN, PACKER, ETC. _____

PUMP 1-1/2" RODS yes ANCHOR no

DETAILED PROCEDURE:

1. MIRUSU. NDWH. NUBOP. POOH w/rods and pump, laying down rods.
2. POOH w/tbg.
3. RIH w/5-1/2" cmt retainer on tbg and set at $\pm$ 4850'. Load hole w/9.5 ppg brine. Squeeze perfs w/50 sx of Class B neat. POO retainer and spot 10 sx on top of retainer. POOH w/tbg.
4. Run freepoint in 5-1/2 csg. RIH w/chemical cutter and cut csg.
5. POOH w/5-1/2" csg, laying dn.
6. RIH w/tbg open ended. Spot cmt plugs as follows:

Depth	Sx	Zone
2645-4072	162	Cliffhouse/Menefee/Pt Lookout
5-1/2" csg		
cut	25	Csg stub
1188-1475	83	Pictured Cliffs
624-surface	190	Surface pipe

SQUEEZED

3609

+0

3671

W 1983 $\pm$ 84

TOTAL OF

200 SX

4922

4959

5120 PB

5154

6779W/3/JWC

PROCEDURE - PAGE 2

LEASE NAME: Arroyo Com WELL NUMBER: 1

7. NDBOP. Cut off csg and wellhead. Install P & A marker.

8. Restore surface location.