Form 3160-5 (November 1983) (Formerly 9-331) DEPART	UNITED STATES MENT OF THE INTER	SUBMIT IN TRIPLICATE OR (Other instructions on re	Form approved. Budget Bureau No. 1004-0135 Expires August 31, 1985  LEASE DESIGNATION AND SERIAL NO.
	AU OF LAND MANAGEMEN		NOO-C-14-20-2727
SUNDRY NOT  (Do not use this form for propo  Use "APPLIC	IICES AND REPORTS ( Deals to drill or to deepen or plug lation FOR PERMIT—" for such p	ON WELLS back to a different reservoir. proposals.)	6. IF INDIAN, ALLOTTEE OR TRIBE NAME  Navajo Tribe
oir 🛛 cya 🗀			7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR			
Texaco Inc.			8. FARM OR LEASE NAME
3. ADDRESS OF OPERATOR		BEATTIES.	Navajo Tribe "BP"
P. O. Box EF Cor	ttor 60 01201	RECEIVED	9. WELL NO.
P. O. BOX EE, COX  1. LOCATION OF WELL (Report location of See also space 17 below.)	clearly and in accordance with any	State requirements &	#7
See also space 17 below.) At surface		MAR 27 1987	Tocito Dome-Penn D
510' FNL & 1980'	FWL BUR	EAU OF LAND MANAGEMENT RMINGTON RESOURCE AREA	11. SHC., T., R., M., OR RUK. AND SURVEY OR ARMA
14. PERMIT NO.	15. ELEVATIONS (Show whether BF,	RT. GR. etc.)	Sec. 26, T26N, R.8W
	5603' GL		<u> </u>
6. Charle A.			<u>l San Juan   New Mexi</u> co
NOTICE OF INTEN	propriate Box To Indicate N	ature of Notice, Report, or C	Other Data
	rion to:	79EEEUR	JENT REPORT OF:
TRACTURE CO.	TULTIPLE COMPLETE	WATER SHUT-OFF FRACTURE TREATMENT	REPAIRING WELL
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ALTERING CASING
REPAIR WELL C	HANGE PLANS	(Other)	ABANDONMENT® X
(Other)		(Notz: Report results	of multiple completion on Well
<ol> <li>DESCRIBE PROPOSED OR COMPLETED OFFR proposed work. If well is direction nent to this work.)</li> </ol>	tations (Clearly state all pertinent analy drilled, give subsurface locati	ompretion of frecompt	etion Report and Log form.)  Including estimated date of starting any 1 depths for all markers and gones perti-
The subject well w following procedur  1) MIRUSU. TOOH  2) TIH open ended Spot 50 sx cla	vas completed as P re was carried out w/rods & Pump. N	lugged & Abandoned during the plugging ipple up BOPs. To tempt to circulate	

- n.
- TIH w/tubing to 6450'. No cement. Spot additional 50 sx Class B cement plug w/3% CaCl<sub>2</sub> and 1/4#/sak cellophane flakes from 6450'-6186'. No returns. Let cement set 2 1/2 hrs. TIH w/tubing and tagged cement at 6400' KB. Broke circulation and displaced hole w/9.2#/gal brine based mud. Spot 25 sx class B cement from 6400'-6288'. 4)
- Pull up to 6174'. Spot 25 sx Class B cement from 6174'-6042'. Pull up to 5622'. Spot 25 sx class B cement from 5622'-5490'.
- Pull up to 3790'. TIH w/thru tubing perf gun & shoot 4-way squeeze holes at 3800'. TOOH w/gun. Spot 35 sx class B cement from 3800'. Squeeze cement into formation leaving 100' inside 7" casing at 1 BFM
- 6) Pull tubing to 2215' KB. TIH w/thru tubing perf gun & shoot 4-way squeeze holes at 2220' KB. Squeeze cement into formation leaving 100' inside 7" casing at 1 BPM @ 500 psi.

Continued on page -2-	41	SU APPROVED
. I hereby certify that the foregoing in true and corre	*	
SIGNED Wen A ROLL	CUITLE AREA SUPTO	APRO2/95 DATE 3/23/87
(This space for Federal or State office use)	Approved as to stagging at the to	
· · · · · · · · · · · · · · · · · · ·	Liability under bond to with a surficient to design the surficients	DIST 9 DIVIDADES
BLM (6)- The Navajo Tribe	- JNH-LAA-AAK-MLK	the state of the s

\*See Instructions on Reverse Side

BLM Sundry Notice/Navajo Tribe BP #7 Page 2 of 2

- 7) Pull tubing to 1620' KB. TIH w/thru tubing perf gun & shoot 4-way squeeze holes at 1627' KB. TOOH w/perf gun. Spot 35 sx Class B cement from 1627' KB. Squeeze cement into formation leaving 100' inside 7" casing. Full returns up Bradenhead.
- 8) Pull tubing to 920' KB. TIH w/thru tubing perf gun & shoot 4-way squeeze holes at 925' KB. TOOH w/perf gun. Spot 35 sx Class B cement from 925' KB. Squeeze cement into formation leaving 100' inside 7" casing. Full returns up Bradenhead.
- 9) TOOH w/tubing. Shoot 4-way squeeze hole at 100' Pump 45 sx Class B cement down 7" casing & circulated cement to surface. Shut well in w/200 psi on casing for weekend.
- 10) Cut off wellhead. Cement to surface on both strings of pipe. Erect dry hole marker & clean location. Operations complete 3/9/87.

NOTE: Location will be seeded between July 1, and Sept. 1 with the prescribed seed mix.