

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Oil Instructions on Rev. 9-331)
VERS. 4113

For use by
Bureau of Land Management
5. CASE DESIGNATION AND SERIAL NO.

NOO-C-19-20-5431

6. IF FEDERAL, ALIQUOT OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
See INSTRUCTIONS FOR PERMIT on back of this form.)

NAVAJO TRIBE

7. LINE AGREEMENT NAME

8. FARM OR CUPARD NAME

NAVAJO TRIBE "BS"

9. WELL NO.

3

10. FIELD AND FOML OR WILCOX

TOCITO DOME FIELD

11. SEC. T. R. M. OR BLK. AND
SURVEY OR AREA

12. COUNTY OR PARISH 13. STATE

SAN JUAN

N.M.

1. OIL ☒ GAS ☐ OTHER ☐

2. NAME OF OPERATOR

TEXACO INC.

3. ADDRESS OF OPERATOR

P.O. BOX EE, CORTEZ, COLORADO 81321

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.)

At surface
1980' FSL, 510' FWL

L-23-T26N-R18W

14. PERMIT NO.

15. ELEVATION (Show whether BE, RT, GR, etc.)

5671' DF

16. Check Appropriate Box To Indicate Nature of Notice or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETION

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

(Other)

(Other)

(Note: Report results of multiple completion on Well Completion or Recombination Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Propose to abandon the well as follows: (collapsed at 3325')

1. Pull on the tubing.
2. If tubing doesn't come go to #3. If tubing comes, attempt casing repair.
3. Cut tubing above collapse and set packer at 3275'.
4. Pump 80 sacks thru packer (assume all the cement will cover the pay zone and up to the top of the Ismay at 6000'.
5. If can't get 80 sacks down, cut casing above collapse and place a 50 sack plug in and out of the casing stub and over the collapse zone. Go to #10.
6. If can pump 80 sacks down, assume covered pay zone and pump $\pm$ 600 ft.³ of mud thru packer.
7. Pump 50 sacks into collapse area of the Dechel y thru packer.
8. Cut casing above collapse and remove.
9. Place a 50 sack plug in and out of the casing stub.
10. Pump $\pm$ 600 ft.³ mud in hole and place 50 sack plug across the bottom of the surface casing at 1618'.
11. Fill the remaining hole with mud.
12. Place 10 sx. plug at surface, erect marker, and clean location.

18. I hereby certify that the foregoing is true and correct

SIGNED *Alvin B. May*

TITLE FIELD FOREMAN

DATE 4-20-76

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: