

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

NOV 25 1985

BUREAU OF LAND MANAGEMENT
FARMINGTON RESOURCE AREA

5. LEASE DESIGNATION AND SERIAL NO.

SF-079319

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Schwerdtfeger A

9. WELL NO.

3E

10. FIELD AND POOL, OR WILDCAT

Basin Dakota

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 6, T27N R8W

12. COUNTY OR PARISH 13. STATE

San Juan

NM

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Tenneco Oil Company

3. ADDRESS OF OPERATOR

P. O. Box 3249, Englewood, CO 80155

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1800' FSL, 800' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5921' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETION

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANE

(Other) Dual to PC

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Tenneco requests permission to dual to the Pictured Cliffs Formation according to the attached detailed procedure.

RECEIVED

DEC 02 1985

OIL CON. DIV.
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Senior Regulatory Analyst

DATE 11/20/85

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED

NOV 26 1985

DATE

FOR AREA MANAGER
FARMINGTON RESOURCE AREA

*See Instructions on Reverse Side

NMOCC

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

LEASE Schwerdtfeger
WELL NO. A3E

CASING:

9 5/8 "OD, 36 LB, K-55 CSG.W/ 250 SX
TOC @ surface HOLE SIZE 12 1/4 DATE: 2/13/81
REMARKS circ. cmt to surf.
7 "OD, 23 LB, K-55 CSG.W/ 550 SX
TOC @ . HOLE SIZE 8 3/4 DATE: 2/15/81
REMARKS Lost rtns 64 BBLS into displacement
 "OD, LB, CSG.W/ DATE: SX
TOC @ . HOLE SIZE DATE
REMARKS

TUBING:

2 3/8 "OD, 4.7 LB, J-55 GRADE, 8 RD, N/A CPLG
LANDED @ 6486 . SN, PACKER, ETC. N/A
 "OD, LB, GRADE, RD, CPLG
LANDED @ . SN, PACKER, ETC.

Liner

TOL: 2514', W/BOTTOM SET @ 6640'
4 1/2" OD, 10.5 LB, K-55 CSG. W/ 500 SXS.
TOC @ TOL, HOLE SIZE 6-1/4", DATE 2/20/81.
REMARKS: REVERSED OUT 10 bbls CMT FROM LINER
HANGER.

PUMP RODS ANCHOR

DETAILED PROCEDURE:

1. Check location for anchors, install if necessary. Lay blow dn lines to pit and start blowing well down.
2. MIRUSU. Kill w/1% KCL wtr if necessary, remove WH and install BOP.
3. RIH w/2-3/8" tbg and tag fill, CO to PBTD with nitrogen foam if necessary. POOH w/2-3/8" tbg.
4. RIH on WL W/A 7" Model "D" w/expendable plug in place and set at 2500'. Dump 2 sxs sand on pkr. Load hole w/2% KCL wtr and PT to 3500 psig

622

PT to 500psi, Change out well head then PT to 3500 psi.

266'

2514'

2680'

DAKOTA:
6479'-6500'
6536'-42'
6570'-80'

6486'

6600'

6640'

PROCEDURE - PAGE 2

LEASE NAME: Schwerdtfeger WELL NUMBER: A3E

5. NDBOP, and single csg head. Install a dual casing head and NDBOP. PT to 3500 -psig.
 6. MIRUWL. Run GR/CBL/CCL from 2500' to TOC. Run a GR-CCL log from 2500' up to 500' and telecopy results to Denver for perforation identification. -CNL
 7. RIH w/tbg to BOT perf, spot 500 gal of DI 7-1/2" HCL across the perfs and POOH w/2-3/8" tbg.
 8. Perforate the Pictured Cliffs intervals per Denver's instruction using 4" hollow carrier csg guns w/120 degree phasing and 2 JSPF. Displace spot acid.
 9. RIH w/a 7" fullbore pkr on 2-3/8" tbg and set pkr 150' above the top perforation. Load the annulus w/2% KCL wtr and PT to 1500 psig. Bleed off to 500 psig and monitor for communication during the acid job.
 10. Break down the perfs and establish and inj. rate and pressure using 2% KCL wtr. SD and record ISIP.
 11. Acidize w/20 gals of 25% weighted HCL per perf and 50% excess 7/8" 1.1 S.G. RCN ball slrs. Pump @ max rate w/max STP 3500 psig. Overdisplace acid 2 bbls past btm perf.
 12. Release the pkr and RIH past the perfs to knock the balls off. PUH w/the pkr 1 jt above the top perforation and blow hole dry w/nitrogen. POOH w/pkr and tbg.
 13. Foam fracture the Pictured Cliffs formation dn csg using 70% quality nitrogen foam and 20# Gel/1000. Rate to be specified w/ max STP 3500 psig.
1 gal. 2% KCL WATER.
- Design to be furnished by Denver Office based on net feet of P.C. pay encountered. See attached design graph for rate and volumes.
14. Shut in for 2 hrs and FTCU overnite through a 1/2" tapped bull plug.
 15. RIH w/ long stg of 2-3/8" tbg w/mule shoe jt on btm, SN 1 jt of bottom w/ exp check in place, blast jts across from P.C. and remainder of tbg.
 16. CO to Mod "D" packer, knock out plug and RIH w/remainder of 2-3/8" tbg, spacing out seal assbly and blast jts so the the tbg is landed \pm 6500'.
 17. PU short string of 1-1/4" tbg w/beveled collars, an orange peeled, perforated sub on btm, SN 1 jt off btm and pmp out plug in place, RIH and land btm of tbg at bottom of P.C. perfs.
 18. NDBOP and NUWH.
 19. Load long string half full w/2% KCL wtr, drop steel ball and pump out exp check w/ nitrogen. Swab in if necessary. FTCU.
 20. Pump out plug from short string. Kick around w/nitrogen and FTCU.
 21. RDMSU.