## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

	Sanary Notices	s and Reports on V	(errs		
			•	5.	Lease Number
. Type of Well		er e de la companya d		6.	_
2. Name of Operator		1 (1) (1) 2 (1) (1) 2 (1) (1) (1) (1) (1)	<u>.</u>	7.	Unit Agreement Nam
MERIDIAN ON	1	• '			
			ត្រូវ ដែលម៉ែល ក្រុមប្រ	0	Huerfano Unit
. Address & Phone No	. of Operator			8.	Well Name & Number Huerfano Unit #219
PO Box 4289, Farm.		7499 (505) 326-970	10	9.	
. Location of Well, 1490'FSL, 1600'FWL	Footage, Sec., , Sec.29, T-26	, <b>T, R, M</b> 5-N, R-10-W, NMPM		10.	Field and Pool Basin Dakota
				11.	County and State San Juan Co, NM
2. CHECK APPROPRIATE	BOX TO INDICA	TE NATURE OF NOTE	CIF DEBODE	OTHER	DAMA
Type of Submission		Type of		OIDER	DATA
Notice of		K_ Abandonment	Change	of Pla	ans
V C 1		Recompletion	New Con	nstruc	tion
_X_ Subsequent		Plugging Back	Non-Row Water		Fracturing
	,	Casing Repair	water :	onut of	L <b>L</b>
Final Aband	donment	Altering Casing			
Final Aband	donment	<pre>Altering Casing Other -</pre>			
		Altering Casing Other -			
		Altering Casing Other -			
Describe Propose 1-17-95 MIRU. POOH	ed or Complete	Altering Casing Other - ed Operations Plug #1: pump 44 WOC. SDON.	Convers	sion to	Injection  inside csg @ 5937-6
Describe Propose  1-17-95 MIRU. POOH 1-18-95 TIH, ta	ed or Complete  ND WH. NU BOP. to 4690'. SI. ag cmt @ 6002'	Altering Casing Other ed Operations Plug #1: pump 44 WOC. SDON. . POOH to 5970'.	Sx Class "H	3" cmt	Injection  inside csg @ 5937-6
Describe Propose  1-17-95 MIRU. 1 POOH  1-18-95 TIH, ta	ed or Complete ND WH. NU BOP. to 4690'. SI. ag cmt @ 6002' to 5481'. Plu	Altering Casing Other -  ed Operations  Plug #1: pump 44 WOC. SDON. POOH to 5970'. g #2: pump 13 sx	sx Class "I Load well w	3" cmt wtr. l	inside csg @ 5937-6 PT csg to 500 psi, O
Describe Propose  1-17-95 MIRU. N POOH  1-18-95 TIH, ta POOH POOH	nd or Complete ND WH. NU BOP. to 4690'. SI. ag cmt @ 6002' to 5481'. Plu to 3462'. Plu	Altering Casing Other -  ed Operations  Plug #1: pump 44 WOC. SDON POOH to 5970'. g #2: pump 13 sx g #3: pump 12 sx	sx Class "H Load well w Class "B" cm	3" cmt wtr. latinsi	inside csg @ 5937-6 PT csg to 500 psi, O de csg @ 5309-5481' de csg @ 3303-3462'
Describe Propose  1-17-95 MIRU. N POOH  1-18-95 TIH, ta POOH POOH POOH	nd or Complete ND WH. NU BOP. to 4690'. SI. ag cmt @ 6002' to 5481'. Plu to 3462'. Plu to 1926'. Plu	Altering Casing Other -  ed Operations  Plug #1: pump 44 WOC. SDON. POOH to 5970'. g #2: pump 13 sx g #3: pump 12 sx g #4: pump 25 sx	sx Class "I Load well w, Class "B" cm Class "B" cm	3" cmt wtr. Int insint insint insi	Injection  inside csg @ 5937-6 PT csg to 500 psi, O de csg @ 5309-5481' de csg @ 3303-3462' de csg @ 1596-1926'
Describe Propose  1-17-95 MIRU. N POOH 1-18-95 TIH, ta POOH POOH POOH POOH to 28	nd wh. NU BOP. to 4690'. SI. ag cmt @ 6002' to 5481'. Plu to 3462'. Plu to 1926'. Plu to 1152'. Plu 22'. Establish	Altering Casing Other -  ed Operations  Plug #1: pump 44 WOC. SDON. POOH to 5970'. g #2: pump 13 sx g #3: pump 12 sx g #4: pump 25 sx g #5: pump 31 sx circ out bradenh	SX Class "I Load well w, Class "B" cm Class "B" cm Class "B" cm Class "B" cm	3" cmt wtr. I nt insi nt insi nt insi nt insi nt insi	Injection  inside csg @ 5937-6  PT csg to 500 psi, O de csg @ 5309-5481' de csg @ 3303-3462' de csg @ 1596-1926' de csg @ 743-1152'.
1-17-95 MIRU. N POOH 1-18-95 TIH, ta POOH POOH POOH POOH to 28 down	nD WH. NU BOP. to 4690'. SI. ag cmt @ 6002' to 5481'. Plu to 3462'. Plu to 1926'. Plu to 1152'. Plu 22'. Establish csg and out 4	Altering Casing Other -  od Operations  Plug #1: pump 44 WOC. SDON. POOH to 5970'. g #2: pump 13 sx g #3: pump 12 sx g #4: pump 25 sx g #4: pump 31 sx circ out bradenh 1/2" csg. Circ 1	Sx Class "H  Load well wants Class "B" cm	3" cmt wtr. I nt insi	inside csg @ 5937-6 PT csg to 500 psi, O de csg @ 5309-5481' de csg @ 3303-3462' de csg @ 1596-1926' de csg @ 743-1152'. 16 sx Class "B" cm
1-17-95 MIRU. POOH 1-18-95 TIH, ta POOH POOH POOH POOH to 28 down WH. C	nD WH. NU BOP. to 4690'. SI. ag cmt @ 6002' to 5481'. Plu to 3462'. Plu to 1926'. Plu to 1152'. Plu 22'. Establish csg and out 4 cmt down 20' b	Altering Casing Other -  od Operations  Plug #1: pump 44 WOC. SDON. POOH to 5970'. g #2: pump 13 sx g #3: pump 12 sx g #4: pump 25 sx g #5: pump 31 sx circ out bradenh 1/2" csg. Circ 1 etween 5 1/2" and	Sx Class "H Load well wanter of the converse o	3" cmt wtr. I nt insi nt insi nt insi it insi it pump out 4 1 clus an	inside csg @ 5937-6  The csg to 500 psi, On the csg @ 5309-5481'. The csg @ 3303-3462'. The csg @ 1596-1926'. The csg @ 743-1152'. The
Describe Propose  1-17-95 MIRU. POOH  1-18-95 TIH, ta  POOH  POOH  POOH  POOH  to 28  down  WH. Cocsg.	nd or Complete ND WH. NU BOP. to 4690'. SI. ag cmt @ 6002' to 5481'. Plu to 3462'. Plu to 1926'. Plu to 1152'. Plu to 1152'. Plu 32'. Establish csg and out 4 Cmt down 20' b Fill csg and	Altering Casing Other -  od Operations  Plug #1: pump 44 WOC. SDON. POOH to 5970'. g #2: pump 13 sx g #3: pump 12 sx g #4: pump 25 sx g #5: pump 31 sx circ out bradenh 1/2" csg. Circ 1 etween 5 1/2" and annulus w/5 sx C1	Sx Class "H  Load well want of the control of the c	3" cmt wtr. I nt insi nt insi nt insi i: pump out 4 1 clus ar Insta	inside csg @ 5937-6 T csg to 500 psi, O de csg @ 5309-5481' de csg @ 3303-3462' de csg @ 1596-1926' de csg @ 743-1152'. O 16 sx Class "B" cm /2" csg. ND BOP. Cu d down 30' inside 4
Describe Propose  1-17-95 MIRU. POOH  1-18-95 TIH, ta  POOH  POOH  POOH  POOH  to 28  down  WH. Cocsg.	nd or Complete ND WH. NU BOP. to 4690'. SI. ag cmt @ 6002' to 5481'. Plu to 3462'. Plu to 1926'. Plu to 1152'. Plu to 1152'. Plu 32'. Establish csg and out 4 Cmt down 20' b Fill csg and	Altering Casing Other -  od Operations  Plug #1: pump 44 WOC. SDON. POOH to 5970'. g #2: pump 13 sx g #3: pump 12 sx g #4: pump 25 sx g #5: pump 31 sx circ out bradenh 1/2" csg. Circ 1 etween 5 1/2" and	Sx Class "H  Load well want of the control of the c	3" cmt wtr. I nt insi nt insi nt insi i: pump out 4 1 clus ar Insta	inside csg @ 5937-6 T csg to 500 psi, O de csg @ 5309-5481' de csg @ 3303-3462' de csg @ 1596-1926' de csg @ 743-1152'. O 16 sx Class "B" cm /2" csg. ND BOP. Cu d down 30' inside 4
Describe Propose  1-17-95 MIRU. POOH  1-18-95 TIH, ta  POOH  POOH  POOH  POOH  to 28  down  WH. Cocsg.	nd or Complete ND WH. NU BOP. to 4690'. SI. ag cmt @ 6002' to 5481'. Plu to 3462'. Plu to 1926'. Plu to 1152'. Plu to 1152'. Plu 32'. Establish csg and out 4 Cmt down 20' b Fill csg and	Altering Casing Other -  od Operations  Plug #1: pump 44 WOC. SDON. POOH to 5970'. g #2: pump 13 sx g #3: pump 12 sx g #4: pump 25 sx g #5: pump 31 sx circ out bradenh 1/2" csg. Circ 1 etween 5 1/2" and annulus w/5 sx C1	Sx Class "H  Load well want of the control of the c	3" cmt wtr. I nt insi nt insi nt insi i: pump out 4 1 clus ar Insta	inside csg @ 5937-6 T csg to 500 psi, O de csg @ 5309-5481' de csg @ 3303-3462' de csg @ 1596-1926' de csg @ 743-1152'. O 16 sx Class "B" cm /2" csg. ND BOP. Cu d down 30' inside 4
3. Describe Propose  1-17-95 MIRU. POOH  1-18-95 TIH, ta  POOH  POOH  POOH  POOH  to 28  down  WH. Cocsg.	nd or Complete ND WH. NU BOP. to 4690'. SI. ag cmt @ 6002' to 5481'. Plu to 3462'. Plu to 1926'. Plu to 1152'. Plu to 1152'. Plu 32'. Establish csg and out 4 Cmt down 20' b Fill csg and	Altering Casing Other -  od Operations  Plug #1: pump 44 WOC. SDON. POOH to 5970'. g #2: pump 13 sx g #3: pump 12 sx g #4: pump 25 sx g #5: pump 31 sx circ out bradenh 1/2" csg. Circ 1 etween 5 1/2" and annulus w/5 sx C1	Sx Class "H  Load well want of the control of the c	3" cmt wtr. I nt insi nt insi nt insi i: pump out 4 1 clus ar Insta	inside csg @ 5937-6 T csg to 500 psi, O de csg @ 5309-5481' de csg @ 3303-3462' de csg @ 1596-1926' de csg @ 743-1152'. O 16 sx Class "B" cm /2" csg. ND BOP. Cu d down 30' inside 4
1-17-95 MIRU. N POOH 1-18-95 TIH, ta POOH POOH POOH POOH to 28 down WH. C csg. sx Cl	nD WH. NU BOP. to 4690'. SI. ag cmt @ 6002' to 5481'. Plu to 3462'. Plu to 1926'. Plu to 1152'. Plu 22'. Establish csg and out 4 Cmt down 20' b Fill csg and ass "B" cmt.	Altering Casing Other -  ed Operations  Plug #1: pump 44 WOC. SDON. POOH to 5970'. g #2: pump 13 sx g #3: pump 12 sx g #4: pump 25 sx g #5: pump 31 sx circ out bradenh 1/2" csg. Circ 1 etween 5 1/2" and annulus w/5 sx Cl RD. Well plugged	Sx Class "H Load well w, Class "B" cm Class "B" cm Class "B" cm ead. Plug #6 /2 bbl cmt c 8 5/8" annu ass "B" cmt.	3" cmt wtr. I nt insi nt insi nt insi i: pump out 4 1 clus ar Insta	inside csg @ 5937-6 T csg to 500 psi, O de csg @ 5309-5481' de csg @ 3303-3462' de csg @ 1596-1926' de csg @ 743-1152'. O 16 sx Class "B" cm /2" csg. ND BOP. Cu d down 30' inside 4
1-17-95 MIRU. POOH 1-18-95 TIH, ta POOH POOH POOH POOH to 28 down WH. C csg. sx Cl	nd or Complete ND WH. NU BOP. to 4690'. SI. ag cmt @ 6002' to 5481'. Plu to 3462'. Plu to 1926'. Plu to 1152'. Plu 82'. Establish csg and out 4 Cmt down 20' b Fill csg and ass "B" cmt.	Altering Casing Other -  ed Operations  Plug #1: pump 44 WOC. SDON. POOH to 5970'. g #2: pump 13 sx g #3: pump 12 sx g #4: pump 25 sx g #5: pump 31 sx circ out bradenh 1/2" csg. Circ 1 etween 5 1/2" and annulus w/5 sx C1 RD. Well plugged	Sx Class "H  Load well ware Class "B" cm Class "B" cm Class "B" cm ead. Plug #6 /2 bbl cmt of 8 5/8" annuals "B" cmt. and abandone	Wtr. Int insint instant insint instant insint	inside csg @ 5937-6 PT csg to 500 psi, O de csg @ 5309-5481' de csg @ 3303-3462' de csg @ 1596-1926' de csg @ 743-1152'. O 16 sx Class "B" cm /2" csg. ND BOP. Cu dd down 30' inside 4 all dry hole marker i-95.
1-17-95 MIRU. POOH 1-18-95 TIH, ta POOH POOH POOH POOH to 28 down WH. C csg. sx Cl	ad or Complete ND WH. NU BOP. to 4690'. SI. ag cmt @ 6002' to 5481'. Plu to 3462'. Plu to 1926'. Plu to 1152'. Plu 22'. Establish csg and out 4 Cmt down 20' b Fill csg and ass "B" cmt.	Altering Casing Other -  cd Operations  Plug #1: pump 44 WOC. SDON. POOH to 5970'. g #2: pump 13 sx g #3: pump 12 sx g #4: pump 25 sx g #5: pump 31 sx circ out bradenh 1/2" csg. Circ 1 etween 5 1/2" and annulus w/5 sx Cl RD. Well plugged  regoing is true an  Title Regulatory	Sx Class "H  Load well ware Class "B" cm Class "B" cm Class "B" cm ead. Plug #6 /2 bbl cmt of 8 5/8" annuals "B" cmt. and abandone	Wtr. Int insint instant insint instant insint	inside csg @ 5937-6 PT csg to 500 psi, O de csg @ 5309-5481' de csg @ 3303-3462' de csg @ 1596-1926' de csg @ 743-1152'. O 16 sx Class "B" cm /2" csg. ND BOP. Cu dd down 30' inside 4 all dry hole marker i-95.
1-17-95 MIRU. POOH 1-18-95 TIH, ta POOH POOH POOH POOH to 28 down WH. C csg. sx Cl	ad or Complete ND WH. NU BOP. to 4690'. SI. ag cmt @ 6002' to 5481'. Plu to 3462'. Plu to 1926'. Plu to 1152'. Plu 22'. Establish csg and out 4 Cmt down 20' b Fill csg and ass "B" cmt.	Altering Casing Other -  cd Operations  Plug #1: pump 44 WOC. SDON. POOH to 5970'. g #2: pump 13 sx g #3: pump 12 sx g #4: pump 25 sx g #5: pump 31 sx circ out bradenh 1/2" csg. Circ 1 etween 5 1/2" and annulus w/5 sx Cl RD. Well plugged  regoing is true an  Title Regulatory	Sx Class "H  Load well ware Class "B" cm Class "B" cm Class "B" cm ead. Plug #6 /2 bbl cmt of 8 5/8" annuals "B" cmt. and abandone	Wtr. Int insint instant insint instant insint	inside csg @ 5937-6 PT csg to 500 psi, O de csg @ 5309-5481' de csg @ 3303-3462' de csg @ 1596-1926' de csg @ 743-1152'. O 16 sx Class "B" cm /2" csg. ND BOP. Cu dd down 30' inside 4 all dry hole marker

APPROVED

NMOCD

DISTRICT MANAGER