

Submit 3 Copies
to Appropriate
District Office

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-045-20708
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. VA-235
7. Lease Name or Unit Agreement Name CLOSAROUND 16
8. Well No. H 1 R
9. Pool name or Wildcat BASIN FRUITLAND COAL
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 6059 G.R.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☐ GAS WELL ☒ OTHER
2. Name of Operator NASSAU RESOURCES INC
3. Address of Operator P.O. Box 809 FARMINGTON, N.M. 87499-0809
4. Well Location Unit Letter A : 833 Feet From The NORTH Line and 955 Feet From The EAST Line Section 16 Township 26 N Range 12 W NMPM SAN JUAN County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ PULL OR ALTER CASING ☐ OTHER: ☐	SUBSEQUENT REPORT OF: REMEDIAL WORK ☐ ALTERING CASING ☐ COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐ CASING TEST AND CEMENT JOB ☐ OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. BOTH 9 5/8" SURFACE @ 124' G.L. AND 7" INTERMEDIATE CASING @ 1216' K.B. ARE CEMENTED BACK AND CIRCULATED TO SURFACE.

NOTICE OF INTENT TO PLUG AND ABANDON. PLUG OFF OPEN HOLE SECTION OF (6 1/4" HOLE FROM 1216-1257' K.B.) BY SETTING A 7" CEMENT RETAINER AT 1170'. PRESSURE TEST RETAINER AND TUBING TO SURFACE. SPOT 10 SACKS CLASS B CEMENT YIELD 12 FT 3 ON TOP OF RETAINER w/water. Pull up to 410' K.B. ESTABLISH CIRCULATION AND PRESSURE TEST CASING TO SURFACE. SET CEMENT PLUG FROM 410' K.B. TO SURFACE WITH 77 SCK CLB CEMENT YIELD 91 FT 3 ON TO ALONG @ 300' K.B. NIPPLE DOWN BOP - CUT OFF WELL HEAD BELOW GROUND INSTALL DRY HOLE MARKER LOCATION RESTORATION WILL BE PERFORM PRIOR TO 6-1-93 DUE TO INCLEMENT WINTER WEATHER CONDITIONS SEE ATTACHED P+ A PROCEDURE

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Andrew A. Bates TITLE OPERATOR REPRESENTATIVE DATE 1-26-93
TYPE OR PRINT NAME ANDREW A. BATES TELEPHONE NO. 325 3816

(This space for State Use)

APPROVED BY Steve Buel TITLE DEPUTY OIL & GAS INSPECTOR, DIST. #3 DATE JAN 26 1993

CONDITIONS OF APPROVAL, IF ANY:

Squeeze out, Below Retainer to fill open hole

NAAMM Resources
RESOURCE DEVELOPMENT
COWSAROUND 16 #1R
SEC. 16, T26, R12W
SAN JUAN COUNTY, NM
PLUG AND ABANDONMENT PROCEDURE

1. MOL and RUSU. Comply to all NMOCD rules and regulations. (24 hrs prior to plug and abandon)
2. Blow well down; kill with water if necessary. ND 2 1/16 master valve and NU BOP and stripping head;
3. PU 7" casing scraper and 2 3/8" work tubing: RIH with tubing to 1216' POH LD scraper.
4. PU 7" CMT RT and RIH to 1170' and set CMT retainer; pressure test tubing to 1000psi pull out CR and spot 15s class B cement on top.
5. Circulate hole with H₂O and pressure test casing to 500#. POH to 410' and establish circulation.
6. Plug# - from 410' to surface with 77 sxs cement; pump cement until good cement circulates out; POH and LD tubing.
7. ND BOP and cut off wellhead below ground level and install dry hole maker. RD and MOSU.
8. Restore location to OCD stipulations.

Respectfully,



Mike Adams

605 253 3816