

State of New Mexico  
Energy, Minerals and Natural Resources Department  
Oil Conservation Division

Sundry Notices and Reports on Wells

<p>1. Type of Well GAS</p> <hr/> <p>2. Name of Operator <b>BURLINGTON RESOURCES</b> OIL &amp; GAS COMPANY</p> <hr/> <p>3. Address &amp; Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700</p> <hr/> <p>4. Location of Well, Footage, Sec., T, R, M 1450' FNL, 1650' FEL, Sec.23, T-28-N, R-6-W, NMPM, San Juan County, NM</p>	<p>API # (assigned by OCD) 30-039-20044</p> <p>5. Lease Number Fee</p> <p>6. State Oil&amp;Gas Lease #</p> <p>7. Lease Name/Unit Name San Juan 28-6 Unit</p> <p>8. Well No. #138</p> <p>9. Pool Name or Wildcat Basin Dakota</p> <p>10. Elevation:</p>
--	--

Type of Submission	Type of Action
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Abandonment <input type="checkbox"/> Change of Plans
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion <input type="checkbox"/> New Construction
<input type="checkbox"/> Final Abandonment	<input type="checkbox"/> Plugging Back <input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Casing Repair <input type="checkbox"/> Water Shut off
	<input type="checkbox"/> Altering Casing <input type="checkbox"/> Conversion to Injection
	<input checked="" type="checkbox"/> Other - Tubing Repair

13. Describe Proposed or Completed Operations

It is intended to repair the tubing in the subject well according to the attached procedure.

**RECEIVED**  
JUN 15 1999

OIL CON. DIV.  
DIST. 3

SIGNATURE *John J. Hammond* Regulatory Administrator June 7, 1999

trc

(This space for State Use)

ORIGINAL SIGNED BY CHARLIE T. PERREN DEPUTY OIL & GAS INSPECTOR, DIST. 3

Approved by \_\_\_\_\_ Title \_\_\_\_\_ Date JUN 15 1999

**San Juan 28-6 Unit #138**  
**Basin Dakota**  
**Unit G, Sec. 23, T-28-N, R-6-W**  
**Latitude / Longitude: 36° 39.0024' / 107° 25.95336'**  
**Recommended Tubing Repair Procedure 5/24/99**

**Project Justification:** This well hasn't been pulled since its 1967 completion. At that time, the 2-3/8" tubing was landed 7' above the top perforation. Because the well is unable to achieve a critical velocity through the 4-1/2" casing, it is unable to lift liquids existing below the end of the tubing. As a result, an additional 47 psi of hydrostatic backpressure is being applied to the formation at the mid-perforation depth. Lowering the tubing will not only increase the production rate, it will also increase the well's reserves.

**NOTE: ALL DEPTHS ARE MEASURED FROM KB. KB to GL was 10'.**

1. Comply with all NMOCD, BLM and Burlington safety and environmental regulations. Prior to moving in rig, make one-call and then verify rig anchors and dig pit.
2. MIRU workover rig. NU relief line and blow well down (kill with 2% KCL water only if necessary). ND WH and NU BOP. Test and record operation of BOP rams. Replace any WH valves that do not operate properly. Test secondary seal and install or replace if necessary.
3. **NOTE: This well operates with a plunger lift system.** Dakota, 2-3/8", 4.7#, J-55 tubing set at **7585'** (242 jts). Broach tubing and set tubing plug in tubing as deep as possible to prevent the plunger from surfacing. Release donut, pick up additional joints of tubing and tag bottom, recording the depth. PBTD should be at +/- **7815'**. TOOH and stand back 2-3/8" tubing. Visually inspect tubing for corrosion, and replace any bad joints. Check tubing for scale and notify Operations Engineer and Drilling Superintendent if it is present.
4. PU 3-7/8" bit, bit sub, and watermelon mill on 2-3/8" tubing and round trip to PBTD, cleaning out with air/mist. **NOTE: When using air/mist, mist rate must not be less than 12 bph.** Speak with Operations Engineer and Drilling Superintendent, and if necessary, determine the best way to remove scale from the casing and perforations.
5. TIH with one joint of 2-3/8" tubing with expendable check, F-nipple (one joint off bottom), then 1/2 of the 2-3/8" production tubing. Run a broach on sandline to ensure that the tubing is clear. TIH with remaining 2-3/8" tubing. Replace any bad joints. CO to PBTD with air/mist.
6. PU above the top Dakota perforation at **7592'** and flow the well naturally, making short trips for clean-up when necessary. Discuss sand production with Operations Engineer and Drilling Superintendent to determine when clean-up is sufficient.
7. Land tubing at **7744'**. Obtain pitot gauge from casing and report this gauge. Broach the upper 1/2 of the production tubing. ND BOP and NU WH. Pump off expendable check. Connect to casing and circulate air to assure that expendable check has pumped off. If well will not flow on its own, make swab run to SN. RD and MOL. Return well to production.

Recommended: *L. Tom Loveland*  
Operations Engineer 5/26/99

Approved: *Bruce D. Bays* 6.3.99  
Drilling Superintendent

**Operations Engineer:** L. Tom Loveland

Office 326-9771  
Pager 324-2568  
Home 564-4418