

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

- | |
|--|
| |
| |
| |
| |
| |
| |
| |

JAN 1 1964 (NOTE: U. S. GEOLOGICAL SURVEY FARMINGTON, N. M.

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

15. ELEVATIONS (SHOW DF, KDB, AND WD)
D 6650' GL

- (This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: _____

***See Instructions on Reverse Side**

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

Run overshot, bumper sub and jars, and recover seal assembly and remaining tubing with lost tools inside.

Trip in hole with 2 3/8" tubing open ended and spot a 190 sk. cement plug from the bottom of the Dakota perforations to top of Gallup formation. Leave plug from 5851-7007'. Pull tubing out of cement. WOC 4 hours and tag plug. Load hole with mud and trip out of hole.

Pull and lay down 5 1/2" casing and liner hanger packer. Trip in hole with tubing.

Perforate squeeze holes at 4044' and spot a 55 sk. cement plug to cover Mesa Verde from top 50' above and below. Leave a 25 sk. plug inside casing from 4044-3944'. Tag plug after WOC 4 hours.

Spot a 75 sk. plug inside casing from 2426' to 2112' to cover 50' below Pictured Cliffs formation top to 50' above Fruitland formation. Tag plug with tubing after WOC 4 hours.

Perforate squeeze holes at 1461' and spot a 55 sk. cement plug to cover Ojo Alamo formation. Leave a 25 sk. plug inside casing from 1361' to 1461'. Tag plug after WOC 4 hours.

Perforate squeeze holes at 380' and pressure displace 90 sk. cement to cover surface casing shoe and fill 7 5/8" - 10 3/4" annulus to surface. Leave a 25 sk. plug inside casing from 380-280'. Tag plug after WOC 4 hours.

Spot a 30 sk. plug from 100' to surface. Install dry hole marker.

Clean and reseed location.