UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

	Sundry Not	ices and Reports on Wells	
			se Number
. Туре GA	of Well S		Indian, All. or oe Name
			. Agreement Nam
. Name	of Operator	107	riano Unit
RE	SOURCES OIL	E GAS COMPANY	
			l Name & Number
B. Addre	ess & Phone No. of Opera Box 4289, Farmington, NM	87499 (505) 326-9700 DITI (9. API	rfano Unit #105 Well No. 045-06210
Locat	ion of Well, Footage, S		ld and Pool
	FSL 680'FEL, Sec.29, T-2	7-N, R-10-W, NMPM Gal	lup/Dakota
			nty and State Juan Co, NM
		DICATE NATURE OF NOTICE, REPORT, OTHER DATA	<u> </u>
	of Submission	Type of Action Abandonment Change of Plans	
_,	<pre>Motice of Intent</pre>	Recompletion New Construction	
	Subsequent Report	Plugging Back Non-Routine Fract	uring
		Casing Repair Water Shut off Altering Casing Conversion to In-	iogtion
	Final Abandonment	Aftering casing conversion to inj _X_ Other - commingle	eccion
13. De	escribe Proposed or Comp	leted Operations	
It	t is intended to comming procedure.	rle the subject well according to the attack	ned
14. Z	hereby certify that the	e foregoing is true and correct.	
	\mathcal{X}	foregoing is true and correct. (KLM2) Title Regulatory Administrator Date	
Signed	Copy Shill price	(KLM2) Title <u>Requiatory Administrator</u> Date	_TLW
Signed (This s	pace for Federale W. Spe	(KLM2) Title <u>Requiatory Administrator</u> Date	

(3)



Huerfano Unit No. 105

Gallup / Dakota DPNO 53051A and 53051B 800' FSL & 680' FEL

Unit P, Sec. 29, T27N, R10W

Latitude / Longitude: 36° 32.47284'/ 107° 54.6936'

Recommended Commingle Procedure

Project Summary: The Huerfano Unit No. 105 is a dual Gallup / Dakota well completed in 1958. We plan to commingle this well, repair a potential casing failure, install a plunger lift and add a wellsite compressor in order to optimize production. This well has not been pulled since the original completion and has broken plunger equipment stuck in both strings of tubing. In addition, the Gallup side may be suffering from a potential casing failure. The decline curve looks somewhat indicative of a casing failure, however it may just be loading up with liquid. The fluid level is only at 4900° on the Gallup side which is low for a casing failure. The Dakota side is also experiencing liquid loading problems. Commingling the zones should allow both to stay unloaded. Note that after the well first delivered in 1958 the Gallup side was recorded as making sand. So it is likely that there is sand fill on top of the packer.

- Comply with all NMOCD, BLM and Burlington safety and environmental regulations. Test rig anchors and build blow pit prior to moving in rig. Notify BROG Regulatory (Peggy Bradfield 326-9727) and the appropriate Regulatory Agency prior to pumping any cement job. If an unplanned cement job is required, approval is required before the job can be pumped. If verbal approval is obtained, document approval in DIMS/WIMS. Allow as much time as possible prior to pump time in case the Agency decides to witness the cement job.
- 2. MOL and RU workover rig. Conduct safety meeting for all personnel on location. NU relief line. Blow down well and kill with 2% KCl water as necessary. ND wellhead and NU BOP. Test and record operation of BOP rams. Have wellhead and valves serviced at machine shop to convert to a single string wellhead (2-3/8"). Test secondary seal and replace/install as necessary.
- 3. Set a plug with wireline in the 2-3/8" Dakota tubing as deep as possible. Also set a plug in the 2-3/8" Gallup tubing as deep as possible to prevent the plunger pieces from traveling up hole. Pick up 2-3/8" tubing and RIH to the top of the Model D packer with the Gallup tubing to determine if any fill is present. If fill is present then round trip the Gallup tubing to remove the bull plug and the plunger trash and circulate any fill off of the packer. TOOH laying down the 2-3/8" 4.7# Gallup tubing.
- 4. Release Model G-22 (Assumed) seal assembly from the Model D Packer with straight pickup (no rotation required). If seal assembly will not come free, then cut 2-3/8" Dakota tubing above the packer and fish with overshot and jars. TOOH with 2-3/8" 4.7# Dakota (remember the rubber coated joint at 5644"). Visually inspect tubing for corrosion and replace any bad joints. Check tubing for scale build up and notify Operations Engineer.

:

- 5. TIH with Model HE packer retrieval spear (PRS, with holes drilled near rotary shoe), rotary shoe. drain sub, top bushing, bumper sub, jars, and 4-6 drill collars on 2-3/8". Mill out Model D packer at 5706' with air/mist. Note: when using air/mist, the minimum mist rate is 12 bph. Try to maintain air rate at 1,400 cfm. A hydrocarbon stable foamer should be utilized since this well makes significant amounts of condensate. After milling over the packer slips, POOH with tools and packer body.
- 6. RIH with RBP and Packer. Set RBP at 5610' (collars at 5598' and 5632'). Set packer immediately above RBP and test plug to 500 psi. Pressure test casing above packer to 500 psi. If casing fails test then isolate holes with the packer and establish a pump-in rate and pressure. Notify Operations Engineer for squeeze procedure. Spot sand on RBP and squeeze according to design. Drill out cement and resqueeze as necessary. Circulate sand off of RBP, release plug and POOH with RBP.
- with tubing.

TIH with 4-3/4" bit and cleanout to PBTD at +/- 6497' or at least below the perforations. TOOH

- TIH with one joint of 2-3/8" tubing with an expendable check on bottom and a seating nipple one joint off bottom. Broach all tubing and land at approximately 6370°. ND BOP and NU single string wellhead (2-1/16" master valve). Pump off expendable check and blow well in. Return well to production.
- 9. Production Operations will install plunger lift.

Recommended: Operations Engineer

7.

Approval:

Contacts: Operations Engineer Kevin Midkiff 326-9807 (Office)

564-1653 (Pager)

Production Foreman

Johnny Ellis 326-9822 (Office) 327-8144 (Pager)

