

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

5. Lease Designation and Serial No.
NM-03380

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.
Florance D LS #8

9. API Well No.
30-045-06398

10. Field and Pool, or Exploratory Area
South Blanco PC

11. County or Parish, State
San Juan, NM

SUBMIT IN TRIPLICATE

1. Type of Well

Oil Well Gas Well Other

2. Name of Operator

Amoco Production Company Attn: John Hampton

3. Address and Telephone No.

P.O. Box 800 Denver, Colorado 80201

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Sec. 20 T27N R8W
990' FNL, 1800' FWL

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Abandonment
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Plugging Back
	<input type="checkbox"/> Casing Repair
	<input type="checkbox"/> Altering Casing
	<input checked="" type="checkbox"/> Other <u>workover to eliminate bradenhead pressure</u>
	<input type="checkbox"/> Change of Plans
	<input type="checkbox"/> New Construction
	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Conversion to Injection
	<input type="checkbox"/> Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Please see attachment for procedures.

DEC 24 1991
AREA MANAGER

If you have any questions please contact Cindy Burton @ (303) 830-5119.

APPROVED
AS AMENDED

DEC 24 1991

AREA MANAGER

14. I hereby certify that the foregoing is true and correct

Signed

J. Hampton

Title

Sr. Staff Admin. Supv.

Date

12/17/91

(This space for Federal or State office use)

GOOD

Workover Procedure
Florance D LS #8
Sec.20-T27N-R08W
San Juan County, NM

1. Contact Federal or State agency prior to starting repair work.
 2. Catch gas and/or water sample off of bradenhead and casing, and have analyzed.
 3. Install and/or test anchors on location.
 4. MIRUSU. Check and record tubing, casing and bradenhead pressures.
 5. Blow down well and kill well, if necessary, with 2% KCL water.
 6. ND wellhead. NU and pressure test BOP's.
 7. TIH and tag PBTB, check for fill. Trip and tally out of hole with tubing, checking condition of tubing.
 8. TIH with bit and scraper to top of perforations. A seating nipple and standing valve may be run in order to pressure test tubing. TOH.
 9. TIH with RBP and packer. Set RBP 50-100 ft. above perforations. TOH one joint and set packer. Pressure test RBP to 1500 psi.
 10. Pressure test casing above packer. Isolate leak, if any, by moving packer up the hole and repeating pressure test. NOTE: If this can not be accomplished, contact Brent Miller in Denver at (303)830-4049. If no leak is found, it may be necessary to perforate the casing ~~below surface casing depth~~ above the top of cement in order to circulate cement to surface.
 11. Establish injection rate into leak, if found, and attempt to circulate to surface.
 12. Release packer, spot sand on RBP and TOH with packer.
 13. Run, if necessary, a CBL and CCL to determine cement top.
 14. Perforate casing above cement top, if necessary, with 4 JSPF and circulate dye to determine cement volume.
 15. Depending on depth of hole and circulating pressure, a packer or cement retainer may be needed.
-

16. Mix and pump sufficient cement (Class B or equivalent, with a setting time of 2 hours) to circulate to surface. Shut bradenhead valve and attempt to walk squeeze to obtain a 1000 psi squeeze pressure. WOC.
 17. TIH with bit and scraper and drill out cement. Pressure test casing. TOH with bit and scraper.
 18. TIH with retrieving head for RBP. Circulate sand off of RBP and TOH with RBP.
 19. TIH with sawtooth collar and/or bailer and clean out hole to PBTD, if fill was found in step 7. TOH.
 20. TIH with production string (1/2 mule shoe on bottom and seating nipple one joint off bottom) and land tubing to original depth. NDBOP. NU wellhead.
 21. Swab well in and put on production.
 22. RDMOSU.
-