

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Form approved  
Budget Bureau N-1004-1  
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL ☐ WELL GAS ☒ WELL OTHER ☐

2. NAME OF OPERATOR  
ARCO Oil and Gas Company

3. ADDRESS OF OPERATOR  
P. O. Box 1610, Midland, Texas 79702

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

14. PERMIT NO  
None

15. ELEVATIONS (Show whether OF, RT, GR, etc.)  
6210' GR

RECEIVED

DEC 15 1986

BUREAU OF LAND MANAGEMENT  
FARMINGTON RESOURCE AREA

5. LEASE DESIGNATION AND SERIAL NO.  
SF 078673

6. IF INDIAN, ALLOTTEE OR TRIBE NAME  
NA

7. UNIT AGREEMENT NAME  
NA

8. FARM OR LEASE NAME  
Federal Schlosser WN

9. WELL NO.  
2

10. FIELD AND POOL OR WILDCAT  
Basin Dakota

11. SEC., T., R., E., OR BLK. AND  
SURVEY OR AREA  
Sec. 3 - 27N - 11W

12. COUNTY OR PARISH  
San Juan

13. STATE  
NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐ PULL OR ALTER CASING ☐  
FRACTURE TREAT ☐ MULTIPLE COMPLETE ☐  
SHOOT OR ACIDIZE ☐ ABANDON\* ☐  
REPAIR WELL ☐ CHANGE PLANS ☐  
(Other) ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐ REPAIRING WELL ☐  
FRACTURE TREATMENT ☐ ALTERING CASING ☐  
SHOOTING OR ACIDIZING ☐ ABANDONMENT\* ☒  
(Other) ☐

(Note: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

This well P&A'd 4/10/85 as follows:

| Plug | Interval  | Cmt                                                                                                 |
|------|-----------|-----------------------------------------------------------------------------------------------------|
| 1    | 6238-6616 | 70 sx - Squeezed & spotted 70 sx cmt to abandon Dakota perfs f/6586-6616'                           |
| 2    | 6094-5478 | 70 sx - Spotted 70 sx cmt to abandon Gallup perfs 5942-5952' & 6012-6032'                           |
| 3    | 2847-3000 | 35 sx - Sqz'd 4 holes @ 3000' through retainer @ 2889' to isolate Mesaverde. Dumped 5 sx cmt on top |
| 4    | 1940-2073 | 15 sx - Spotted 15 sx inside casing to isolate the Pictured Cliffs formation                        |
| 5    | 1748-1880 | 15 sx - Spotted 15 sx cmt inside casing to isolate the Fruitland formation                          |
| 6    | 800-1015  | 50 sx - Sqz'd 50 sx through 4 holes @ 1015' to isolate Ojo Alamo. Left 215' plug inside casing      |
| 7    | 145-275   | 27 sx - Sqz'd 27 sx through 4 holes @ 275' to isolate the surface casing shoe @ 220'.               |
| 8    | 0-60      | 5 sx - Spotted 60' plug @ surface.                                                                  |

Filled remainder of hole w/mud & installed a dry hole marker.

18. I hereby certify that the foregoing is true and correct

SIGNED Ken W. Gosnell

915-688-5672  
TITLE Engr. Tech. Spec.

DATE 12-8-86

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

TITLE \_\_\_\_\_

DATE \_\_\_\_\_

Approved by \_\_\_\_\_  
Librarian \_\_\_\_\_  
Surface \_\_\_\_\_

\*See Instructions on Reverse Side