Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

RECEIVED

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: Merch 31, 1993

	2 % apr 10 m	
	OTICES AND REPORTS ON WELLS possels to drill or to deepen or reentry to a different reserve CATION FOR PERMIT - " for such proposals"	
	U/O Freinn	MAS VAN, If Unit or CA, Agreement Designation
1. Type of Well Oil Ges Well Other		8. Well Name and No.
2. Name of Operator	Attention:	Bolack 3E
Amoco Production Company	Patty Haefele	9. API Well No.
3. Address and Telephone No. P.O. Box 800, Denver, Colorac	o 80201 (303) 830-4988	3004525552
4. Location of Well (Footage, Sec., T., R., M., o		10. Field and Pool, or Exploratory Area Basin Dakota
790' FSL 2045' FE		11. County or Parish, State
		San Juan New Mexico
12. CHECK APPROPR	ATE BOX(s) TO INDICATE NATURE OF NO	OTICE , REPORT, OR OTHER DATA
TYPE OF SUBMISSION		ACTION
Notice of Intent	Abandonment Recompletion Plugging Back	Change of Plans New Construction

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work . If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*


Other Bradenhead Repair

Casing Repair

Altering Casing

Amoco Production Company intends to do a bradenhead repair per the attached procedure.

Please call Mark Rothenberg (303) 830-5612 with any technical questions and Patty Haefele (303) 830-4988 for any other questions.



(Note: Report results of multiple completion on Well Completion or Recompletior Report and Log form.)

Water Shut-Off

OIL COM. DIV.

		- Company of the Comp
14. I hereby certify that the foregoing is true and correct Signed Patty Haefele	Title	Staff Assistant DDROVED
This space for Federal or State office use)		
Approved by Conditions of approval, if any:	Title	MAY 5 1995
tle 18 U.S.C. Section 1001, makes it a crime for any person knowingly and w presentations as to any matter within its jurisdiction.	illfully to make to any department or	r agency of the United States any false, f

SJOET Well Work Procedure



Wellname:

Bolack 3 E

#1

Version: Date:

May 1, 1995

Budget:

DRA

Workover Type:

Bradenhead repair

UTU Transmission Use Paul

SERAY 11 PH 2: 40

Objectives:

Recently failed a bradenhead test (flowed water).

- CBL will be run to locate TOC.
- 2. Bradenhead and any casing leaks will be repaired.
- Tubing will be lowered to 6550' and well returned to production.

Pertinent Information:

Location:

790' FSL, 2045' FEL, O20-28N-8W

Horizon:

DK

County:

San Juan

API #:

30-045-25552

State:

New Mexico

Federal # SF080101

Engr: Phone:

Mark Rothenberg W--(303)830-5612

Lease: Well Flac:

H--(303)696-7309

Economic Information:

APC WI:

92.5%

DK Prod. Before Repair:

64 MCFD

Estimated Cost:

\$42,500

DK Anticipated Prod.:

64 MCFD

48 months

Max Cost -12 Mo. P.O.

\$16,289

PV15:

Payout:

\$M

Max Cost PV15:

\$M

*Note:

Economics run based upon 64 MCFD production vs 0 MCFD.

*Note:

Because this is a BH repair and payout will occur within life of well, work will be

performed.

Formation Tops: (Estimated formation tops)

Nacimento:

1180

Menefee:

3776

Oio Alamo:

Point Lookout:

Kirtland Shale:

1250

4343

Fruitland:

1700

Mancos Shale: Gallup:

4728

Pictured Cliffs:

2100

Greenhorn:

5537 6285

Lewis Shale:

2150

Graneros:

6350

Chacra:

2700

Dakota:

6388

Cliffhouse:

3723

Morrison:

Casing:

Bradenhead Test Information:

Test Date:

1/17/95 **Tubing:**

CSG

245psi

390psi

BH: 10psi

Time

BH

CSG

5 min

10 min 15 min

Comments:

Blew down in 1 sec. - after 30 min. started to flow clear, salty water, 1/2 test flange plug had too much press to pull.

Wellname: Bolack 3 E

Page 2 5/10/95

Suggested Procedures:

- 1. Contact Federal or State agency prior to starting repair work.
- 2. Catch gas and/or water sample off of bradenhead and casing, and have analyzed.
- 3. Install and/or test anchors.
- 4. MIRUSU. Check and record tubing, casing and bradenhead pressures.
- 5. Blow well down, kill well if necessary with 2% KCL.
- 6. Nipple down well head, nipple up and pressure test BOP's.
- 7. Trip in the hole and tag PBTD, check for fill, trip and tally out of hole with tubing checking condition of tubing.
- 8. Trip in the hole with bit and scraper for the intermediate casing and trip in to the top of the liner. Trip out of the hole with bit and scraper. Trip in hole with second bit and scraper and run from the top of the liner to the top of the perforations. A seating nipple and standing valve may be run in order to pressure test the tubing.
- 9. Trip in the hole with RBP and PKR. Set RBP 50-100 ft. above perforations. Trip out of hole one joint and set PKR and pressure test RBP to 1500 psi. Release PKR, spot sand on RBP and pressure test csg to 1000 psi. If no leak is found, trip out of hole with PKR and skip to step 11.
- 10. Trip out of hole isolating leak in liner, if any. If a liner leak is found, establish injection rate and check for circulation around liner top. Also, determine if there is a leak above the top of the liner. Trip out of hole with PKR.
- 11. Run CBL from 1500' to surface under 1000 psi and fax results to Denver attn: Mark Rothenberg (303-830-9262).
- 12. If there are no casing leaks, skip to step 14.
- 13. If there is a leak in the liner and a leak above the top of the liner, trip in hole with a RBP that fits the liner and a PKR that fits the intermediate casing. Set RBP 30-60' below the top of the liner. Release PKR and trip out of hole isolating leak in the intermediate casing.
- 14. Based on the location of the leak, if any, and the results of the CBL, perforate casing if necessary with 4 JSPF and circulate dye if possible to determine cement volume. Depending on the depth of the hole and circulating pressure, a PKR or a cement retainer may be needed.
- 15. Mix and pump sufficient cement (class B or equivalent with two hour setting time) to circulate to surface, if circulation to surface is possible. Shut bradenhead valve and attempt to obtain a squeeze pressure and WOC.
- 16. Trip out of hole. Trip in the hole with bit and scraper and drill out cement and pressure test casing. Re-squeeze leaks if casing fails pressure test.
- 17. If cement is not circulated to the surface, it may be necessary to run another CBL (and/or temperature survey 8-10 hours after cementing) and repeat steps 14 thru 16.
- 18. Trip in the hole with retrieving head for RBP, circulate sand off of RBP and trip out of hole with plug.

Wellname: Bolack 3 E

Page 3 5/10/95

- 19. If there is a leak in the liner top, trip in hole with a PKR. If there is no leak in the liner top, skip to step 22.
- 20. Mix and pump sufficient cement (class B or equivalent with two hour setting time) to squeeze liner top. Attempt to obtain a squeeze pressure and WOC.
- 21. Trip in the hole with bit and scraper and drill out cement and pressure test casing. Re-squeeze leak if liner top fails pressure test.
- 22. If there is a second RBP in the liner, trip in the hole with a retrieving head, circulate sand off of the RBP and trip out of hole with the plug.
- 23. If there is a leak in the liner or squeeze work is required based on the CBL, perforate casing, if necessary with 4 JSPF. Trip in hole with a cement retainer and set above the leak or perforations.
- 24. Mix and pump sufficient cement (class B or equivalent with two hour setting time) and attempt to obtain a squeeze pressure and WOC.
- 25. Trip in the hole with bit and scraper and drill out cement and pressure test casing. Re-squeeze leaks if casing fails pressure test.
- 26. Trip in the hole with retrieving head for RBP set in the liner, circulate sand off of RBP with 2% KCL and trip out of hole with plug.
- 27. Trip in hole with a sawtooth collar and/or bailer and clean out to PBTD and trip out of hole.
- 28. Trip in the hole with the production string (1/2 mule shoe on bottom and a seating nipple one joint off bottom), adding joints to land tubing at 6550'. Nipple down BOP's, nipple up well head.
- 29. Swab well in and put well on production.
- 30. Rig down move off service unit.

If problems are encountered, please contact:

MARK ROTHENBERG (W) (303) 830-5708 (H) (303) 343-3973

Amoco Production Company ENGINEERING CHART SUBJECT Bolack 3E Date 4/25/95 LEASE: FEDERAL SF080101 790 FSL, 2045 FEL 020,28N,8W (Non Standard Location, approved 11/24/82) Il Frimmer Was, Introvished Drig 2/18/83 Defort 193 (124" hole to 255") 25 958" 36# C56 @ 248" NOTE: BH flowed water 200 IN '85, 88, Had steddy flow of gas 400 WELL NEVER BEEN WORKED ON 800 1000 050 ALAMO - 1250 1180 1400 (8 34" hole to 2650" × 1600 1800 2000' FRUITLAND 2000 2150 2400 TOL-@ 2500' (May be @ 2484' 2600 , 23# K-55 LSG @ 2653 LEWIS 2800 3000 3100 3600 2800 4000' -4400 POINT LOOKUUT 4800 5000' MANLOS 5400 5000 5800 6000'-6200 GRANGROS PERFS 238' Tbg, SN, POP @ 6440' 6400 6480-6501 4%", 10.5" K-55 LSG @ 6608 DAKOTA 6600 6548 (275PF) PBTD @ 6595'

6800



STATE OF NEW MEXICO

ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 95 May 11 PH 2: 40

1000 RIO BRAZOS ROAD


1000 RIO BRAZOS ROAD

AZTEC, NEW MEXICO 87410

[505] 334-6178

BRADENHEAD TEST REPORT (Submit 2 copies to above address)

Date of	Test01/17/95	Operator	Amoco Producti	ion Company			
Lease N	Bolack	Well No.#3E	_ Location: Unit _	_Section 020	Township 28	N Range 8	W
	•	Tubing 245					
. 0	PEN BRADENHEAD /	AND INTERMEDIATE T	O ATMOSPHERE	INDIVIDUALLY	Y FOR 15 MI	NUTES EACH	
<u> </u>	PR	ESSURES:		BRA	DENHEAD		
TIME				F.	LOWED	FLOWED	,
5 min.	N/A	390	Steady Flow		X		
10 min.	. N/A	390	Surges				
min.	N/A	390	Down to Nothi	ng			
20 min.	N/A	390	Nothing	•			
25 min.	N/A	390	Gas			<u> </u>	
30 min.	N/A	390	Gas & Water _				
				·			
		•					
	enhead flowed water, ch						
CLE	EAR X	FRESH	SALTY X	SULFUR_		BLACK	<u></u> :
REMA	RKS: Pulled 1" plug	Had 10 lb. on braden	hand Dlaw day	en in 1 assessed	Carrat de la lat		
1/2" tes	st plug had too much	pressure to pull out of	f bottom flange of	of tubing head.	Andreas	Terope Min	nau
	· · · · · · · · · · · · · · · · · · ·		•	····			
By	Joe Schrock		w	itness			
		amont Division Form					



Engr: zalc14