UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

ype of Well GAS			FII 1: 16 5. TON, NY 6.	SF-077084
				Tribe Name
			7.	Unit Agreement Na
ame of Operator				
ddress & Phone No. of Opera PO Box 4289, Farmington, NM		3 E-97 0 L	L 2000	Well Name & Numbe Lackey Hubbell #2 API Well No. 30-045-07209
ocation of Well, Footage, S 90'FNL, 990'FEL, Sec.29, T-		NMPNC S &	11	Field and Pool Fulcher Kutz PC/ Basin Fruitland C County and State San Juan Co, NM
CHECK APPROPRIATE BOX TO IN				ER DATA
ype of Submission		Type of Act		D1
X Notice of Intent	_X_ Abandon		_ Change of I New Constru	
Cub somet Deport	Recomple Plugging			e Fracturing
Subsequent Report	Casing R		Water Shut	
Final Abandonment				to Injection
Describe Proposed or Comp			ell according	to the attached
procedure.				
I hereby certify that the				
		Regulator	v Supervisor	Date 5/31/00
ned Julius Cali	Title	Regulacol		TLW
ned filial Cali is space for Federal or State ROVED BY	te Office use)			7/14/6

Lackey-Hubbell 2

DPNO 4205102
Basin Fruitland Coal
990' FNL & 990' FEL, Section 29, T28N, R10W
San Juan County, New Mexico

Note: All cement volumes use 100% excess outside pipe and 50' excess inside. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures.

- Prepare blow pit. Comply with all NMOCD, BLM, and Burlington safety regulations. Conduct safety
 meeting for all personnel on location. MOL and RU daylight pulling unit. Conduct safety meeting for
 all personnel on location. NU relief line to blow well down. Kill well with water as necessary. ND
 wellhead and NU BOP and stripping head; test BOP.
- 2. TOH and tally 65 joints 2-3/8" tubing (2087'). Inspect tubing, if necessary LD and PU workstring.
- 3. Plug #1 (Pictured Cliffs top and Fruitland perforations, 2104' 1768'): TIH with open ended tubing workstring and tag CIBP, or as deep as possible. Pump 40 bbls water down tubing. Mix 51 sxs Class B cement and spot above the existing CIBP to isolate PC top and to fill the Fruitland perforations. PUH to 1000' and WOC. TIH and tag cement. Load casing and pressure test to 500#, if casing does not test, then spot or tag subsequent plug as appropriate.
- 4. Plug #2 (Kirtland and Ojo Alamo tops, 1225' 955'): Round-trip 4-1/2" gauge ring or casing scraper to 1225'. Perforate 6 HSC squeeze holes through both 4-1/2" and 7" casings at 1225'. If casing tested establish rate into squeeze holes. Also attempt to pump into 4-1/2" x 7" annulus valve. TIH and set a 4-1/2" cement retainer at 1175'. Pressure test tubing 1000#. If casing did not test then test above CR. Mix 94 sxs Class B cement, squeeze 69 sxs outside 7" casing and leave 25 sxs inside 4-1/2" casing to cover Ojo Alamo top. TOH and LD tubing.
- 5. Plug #3 (15" casing shoe at 70'): Perforate 4 HSC squeeze noles through 4-1/2" and 7" casings at 120'. Establish circulation down 4-1/2" casing and out bradenhead valve if present. Mix approximately 120 sxs Class B cement and pump down the 4-1/2" casing from 120' to surface, circulate good cement out bradenhead. If the 7" x 15" annulus is not full then cement. Shut in well and WOC.

6. ND BOP and cut off wellhead below surface casing. Install P&A marker to comply with regulations. RD, MQL, cut off anchors, and restore location.

Recommended

Approval:

Orilling Superintendent

Operations Engineer

Joe Michetti

Office - 326-9764

Pager - 564-7187

Sundry Required

pproved. / regard

Regulatory Approval