

**Walsh Engineering and Production**

**Plug and Abandon Procedure for  
Parker and Parsley  
Day "J" #3**

Location: SE/4 Sec 8 T28N R10W  
San Juan County, NM


Date: June 29, 1992

Field: Basin Fruitland Coal  
Surface: BLM  
Minerals: BLM SF 047039 "B"

Elev: GL 5821

**Procedure:**

1. MOL and RU P&A. Hold safety meeting.
2. Blow well down and ND tubing head and NU BOP. Lay 2-3/8" flow lines to pit. Pressure test BOP.
3. Release Baker Model AD-1 packer and TOH with 61 joints of 1-1/2" tubing and packer.
4. Spot 20 sx (23.6 cu. ft.) of cement from 1993' to 1893' (50' above and below top of PC with 100% excess).
5. WOC. TIH and tag cement. Spot 9.0# mud from top of cement to 1010' (approx. 22 bbls.) TOH and pressure test to 500#.
6. Perforate two holes at 1010' and establish circulation. Set 5-1/2" cement retainer at 960'.
7. Cement with 108 sx (127.4 cu. ft.) from 1010' to 780' (50' above and below Ojo Alamo with 100% excess outside casing.) Pick up to 650' and spot 9.0# mud from 650' to 156' (approx. 12 bbls.) TOH and lay down tubing.
8. Perforate 2 holes at 156'. Establish circulation through bradenhead valve and circulate cement to surface ( approx. 45 sx - 53.1 cu. ft.)
9. ND BOP and cut off wellhead below surface casing. Install P&A marker. Rig down and release rig.
10. Clean location and restore as per BLM requirements.



Paul C. Thompson, P.E.