Form 3160-5 (December 1989)

## UNITED STATES DEPARTMENT OF THE INTERIOR RUREAU OF LAND MANAGEMENT

FORM APPROVED Budget Bureau No. 1004-0135 Expires: September 30, 1990

14. I hereby certify that the foregoing is true and correct Signed Mulliman Title (This space for Federal or State office use)  Approved by /s/ Charlie Baechara  Title	Permitting Assistant  Team Lead, Patroleum Management	Date 04/04/00
Signed Mellosa (Mallikuce Title	Permitting Assistant	Date 04/04/00
Mala a lillaigable	Permitting Assistant	Date 04/04/00
14. I hereby certify that the foregoing is true and correct		
	Per s	
	MAY 2000 RECEIVED	
	56789	102
Amoco Production Company request permision procedure.	on to plug and abandon the subject well	as per the attached well work
13. Describe Proposed or Completed Operations. (Clearly state all work. If well is directionally drilled, give subsurface locations	pertinent details, and give pertinent dates, including	estimated date of starting any proposed
	(Note: Report results of multiple co Recompletion Report and Log form	ompletion on Well Completion or
	Other BLM Letter 1/25/2000	Conversion to injection
☐ Final Abandonment Notice	_   Casing Repair	Water Shut-Off Conversion to Injection
Subsequent Report		Non-Routine Fracturing
	<u> </u>	Change of Plans New Construction
	7	
TYPE OF SUBMISSION	TYPE OF ACTION	
12. CHECK APPROPRIATE BOX(s) TO INI	<u> </u>	
1190' FSL 1850' FWL Sec 25 T28	\$ <sup>J</sup> R9W	San Juan New Mexico
4. Location of Well (Footage, Sec., T., R., M., or Survey Descriptio	n)	11. County or Parish, State
P.O. Box 3092 Houston, TX 77253	(281) 366-2548	Basin Bakota/Fruntian drea Coal
3. Address and Telephone No.		30-045-11612
Amoco Production Company Melissa Velasco-Price		9. API Well No.
2. Name of Operator		Warren 1
OIL GAS WELL OTHER		8. Well Name and No.
SUBMIT IN TRIPL  1. Type of Well	ICATE U.O MAMARACA, NA	7. If Unit or CA, Agreement Designation
Do not use this form for proposals to drill or to dee	epen or reentry to a different reservoir	6. If Indian, Allottee or Tribe Name
SUNDRY NOTICES AND REF	PORTS ON WELLS	<ol> <li>Lease Designation and Serial No.</li> <li>SF - 077112</li> </ol>
BUREAU OF LAND MA	NAGEMENT	Expires: September 30, 1990

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Warren 1 (DK)
Original Completion 1/66
TD = 6,776' PBTD = 6,734'
Page 2 of 2

- 1. Notify regulatory agencies (BLM, NMOCD, FIMO) 24 hours in advance of plugging activity. Contact BLM and indicate well is allotted (FIMO regulations effective April 1, 1997).
- 2. Check location for anchors. Install if necessary. Test anchors.
- 3. MIRUSU. Blow down well. Kill if necessary with fresh water. NDWH. NUBOP.
- 4. TOH with 2 3/8" tubing. RIH in hole with 2 3/8" tubing workstring and CIBP, set CIBP at 6,470'. Spot cement plug from 6,470' to 6,370' (Dakota). TOH to 5,620', spot cement plug from 5,620' to 5,520' (Gallup). TOH to 3,740', spot cement plug from 3,740' to 3,640' (Cliff House). TOH to 3,130', spot cement plug from 3,130' to 3,030' (Chacra). TOH to 2,170', spot cement plug from 2,170' to 1,930' (Pictured Cliffs, Fruitland). TOH to 1,340', spot cement plug from 1,340' to 1,020' (Kirtland Shale, Ojo Alamo). TOH, rig up wireline. Perforate squeeze holes at 260', pump down casing and establish circulation to surface. Circulate cement to surface leaving casing full of cement.
- 5. NDBOP. Cut off casing and wellhead. Install PXA marker according to BLM or State requirements.
- 6. Contact FMC and ship surface equipment to yard or other location per instructions.
- 7. Provide workorder to Buddy Shaw for reclamation.
- 8. Rehabilitate location according to BLM or State requirements.

## Warren 1 (DK)

## N25 T28N-R9W, 1190 FSL, 1850 FWL API 3004511612 SF-077112

## **Proposed PXA Wellbore Schematic**

