Form 3160-5 (June 1990)

or representations as to any matter within its jurisdiction.

## **UNITED STATES**

## DEPARTMENT OF THE INTERIOR

Budget Burezu No. 1004-0135

SUNDRY NOTICES  Do not use this form for proposals to d  Use "APPLICATION FO		Expires: March 31, 1993  5. Lease Designation and Serial No.  SF-077111  6. If Indian, Allottee or Tribe Name  7. If Unit or CA, Agreement Designation  8. Well Name and No.  Storey C LS #10R  9. API Well No.  3004511896  10. Field and Pool, or Exploratory Area  Basin Mesaverde  11. County or Parish, State
	ec. 35-T28N-R9W Uni M	San Juan, New Mexico
CHECK APPROPRIATE BOX	s) TO INDICATE NATURE OF NOTICE, REPOR	
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent  Subsequent Report  Final Abandonment Notice	Abandonment Recompletion Plugging Back Casing Repair Altering Casing Other	Change of Plans  New Construction  Non-Routine Fracturing  Water Shut-Off  Conversion to Injection  Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
Amoco Production Company requ per attached procedures.	uests permission to plug and abandon t	his well
If you have any questions co	ONL COM. DIV.	RECEIVED BLM 96 JUL 18 AM 10: 08 070 FARIMINGTON, NM
14. I hereby certify that the foregoing is true and correct	and the second s	
Signed Las Acheleta	Tide Clerk	Date7-16-96
(This space for Federal or State office use)		_ <del></del>
Approved by		
Title 18 II S.C. Section 1001, makes it a crime for any person	knowingly and willfully to make to any denartment or agency of the United	Crates are Phase Paus or fraudulant statements

\*See Instruction on Reverse Side

Storey C LS 10R Orig. Comp. 9/65 TD = 6962, Page 2 of 2

- 1. Check location for anchors. Install if necessary. Test anchors.
- 2. MIRUSU. Blow down well. Kill if necessary with fresh water. NDWH. NUBOP.
- 3. POOH with 1 1/4"" tbg. POOH. Run in hole with tbg and CIBP, set CIBP at 3930'. Test csg integrity to 500#. Spot 100' cement plug on top. (13 cuft cement) Pull up hole and spot 100' cement plug as follows: 3184' to 3284' CK, 2258' to 2358'PC, 1964' to 2064' FT, 1264' to 1364' OJ and 321 to surface with 69 cuft cement.
- 4. NDBOP. Cut off casing and wellhead. Install PXA marker according to BLM or State requirements.
- 5. Contact FMC and ship surface equipment to yard or other location per instructions.
- 6. Turn over to John Schwartz for reclamation.
- 7. Rehabilitate location according to BLM or State requirements.



To: Carolanne Wyeth

From: Chip Harraden Geologist - ELM 505-599-6361

Date FAX Sent: 4/26/96 303-830-4777

		aka/Storey C#Z 1175 FSL, 890 FWL Sec. 35, Z8N-9W
Carolonne		Sec. 35, 28N-9W GL 6203 KB 621
Santose	SucF	TD 6962' P8706
Nacimiento	≈ 185 <sup>'</sup>	(Behind S.C.@ 268')
Ojo Alamo	1304	
Kirtland	1445'	
Fruitland _	2014'	
Pictured Cliffs	2308,	
Lewis	20021	
Chacra	3234	
Cliff House	3955'	
Menefee	3989'	
Point Lookout	46001	
Mancos	4810'	
Gallup	5756'	
Dakota	6644'	to PBTD
	will need	1 Chacra plug due to Chacra gas
	in this	section
		Thanks
		Cip Harrood