147

## **UNITED STATES DEPARTME**

GE

TO ALID DEDODES OLI WELLS	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
OLOGICAL SURVEY	M 09979
INT OF THE INTERIOR (Verse side)	

SUNDRY NOTICES A	AND	REPORTS	ON	WELLS
------------------	-----	---------	----	-------

	PPLICATION FOR PERMIT—" for such proposals.)				
		7. UNIT AGREEMENT N.	AME		
OIL X GAS OT	THER	S. E. Cha Cha			
NAME OF OPERATOR		8. FARM OR LEASE NA	8. FARM OR LEASE NAME		
Suburban Propane Ga	s Company	S. E. Cha Cha			
3. ADDRESS OF OPERATOR		9. WELL NO.	9. WELL NO.		
P.O. Drawer 1980 Fa	rmington New Mexico	24	24		
4. LOCATION OF WELL (Report loc See also space 17 below.) At surface	cation clearly and in accordance with any State requirements.*	Gallup	R WILDCAT		
	on Court line and 2120 ft from Each line	11. SEC., T., B., M., OR	RLK. AND		
Located 1920 Ft. Ir	om South line and 2120 ft. from East line	SURVEY OR AREA			
Sec. 15 NW/4 Section 15, T-28N R-13W, N.M.P.H.		Sec. 15, T-28	Sec. 15, T-28N-R-13W		
		N.M.P.	Н.		
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISI	H 13. STATE		
	6080 GL	San Jaun	N.M.		


Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBBRQUENT REPORT OF:
PULL OR ALTER CASING FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL WX CHANGE PLANS (Other)	WATER SHUT-OFF  FRACTURE TREATMENT SHOOTING OR ACIDIZING  (Other)  (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

In order to increase production on the above well, we propose to workover this well as follows:

- Move in pulling unit. Pull tubing and packer.
- Set Bridge Plug at 5710.
- Run Baker packer, and look for holes in casing.
- After finding hole, Squeeze bad casing.
- Drill out test casing, if okay drill out bridge plug clear out to T.D.
- Run tubing with packer and acidize perf. swab test.
- Pull packer, run production tubing, Pump and rods, and put back on production.



AUG 10 1977

