

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☐ other ☐
well well

2. NAME OF OPERATOR

CONOCO INC.

3. ADDRESS OF OPERATOR

PO Box 46, Hobbs, NM 88240

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 1720/S + 1510/W

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☒
(other) ☐

☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐

5. LEASE

NM 13125

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

CONOCO 29-4

9. WELL NO.

1

10. FIELD OR WILDCAT NAME

PC / MESAR#06

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

SEC 22-29N-4W

12. COUNTY OR PARISH 13. STATE

RIO ARIZONA

NM

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)

7130'GL

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

It is proposed to plug and abandon
subject using the revised
procedure at right.

RECOMMENDED PROCEDURE

NOTE: All cement should be class "B" w/2% CaCl₂ mixed @ 15 # PPG.
Have cement company bring out 350 sacks.

- 1.) Kill well w/produced water if necessary.
- 2.) Lower tubing (tubing is set @ 3808' KB) and spot 25 sacks of cement across interval from top of bridge plug @ 3857' to 3867'.
- 3.) PUGH w/tubing and WOC 18 hours.
- 4.) Run free point test on 5 1/2" casing.
- 5.) If free point is below 3100', cut and pull casing. Spot 10 sacks of cement inside casing stub and 25 sacks outside casing stub. Spot 150 sacks of cement across interval from 3300'-3600' (Ojo Alamo fresh water sand is @ 3140'-3290'). If free point is above 3100', run a 4" casing gun, 90° phasing, and perforate 4 JSEF @ 3300'. Establish pump in rate and squeeze Ojo Alamo fresh water sand w/150 sacks of cement using a squeeze packer. Spot 30 sacks in casing across interval from 3150'-3100'. WOC 18 hours.
- 6.) Re-run free point test. Cut and pull casing. Spot 10 sacks inside casing stub and 25 sacks outside casing stub.
- 7.) Spot 10 sack surface plug from 0-30'.
- 8.) Erect PSA marker and clean up location.

Subsurface Safety Valve: Manu. and Type

18. I hereby certify that the foregoing is true and correct

SIGNED

Wes A. Hunter

TITLE Administrative Supervisor

DATE 7-6-79

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL IF ANY:

USGS DURANGO 5

BGA

MJL

FILG

*See Instructions on Reverse Side

JUL 13 1979