Form 3160-5 (June 1990)	UNI DEPARTMEÌ BUREAU OF	FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993  5. Lease Designation and Serial No.	
Do not us	SUNDRY NOTICES e this form for proposals to di Use "APPLICATION FO	6. If Indian, Allottee or Tribe Name	
	SUBMIT	7. If Unit or CA, Agreement Designation	
1. Type of Well Oil Well 2. Name of Ope	X Gas Well Other	San Juan 29-6 Unit  8. Well Name and No. 228	
3. Address and 5525 Hv 4. Location of W Unit Le	Telephone No.		30-039-24683  10. Field and Pool, or Exploratory Area  Basin Fruitland Coal  11. County or Parish. State  Rio Arriba, NM
12. C	HECK APPROPRIATE BOX(	s) TO INDICATE NATURE OF NOTICE, REPOR	T, OR OTHER DATA
T	YPE OF SUBMISSION	TYPE OF ACTION	
[3	Notice of Intent  Subsequent Report  Final Abandonment Notice	Abandonment Recompletion Plugging Back Casing Repair Altering Casing X Other Drill Bridge Plug Out	Change of Plans  New Construction  Non-Routine Fracturing  Water Shut-Off  Conversion to Injection  Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form)
give subs	surface locations and measured and true vertice	pertinent details, and give pertinent dates, including estimated date of starting and depths for all markers and zones pertinent to this work.)*  es to drill the bridge plug from the all feet to drill the	
		DIST. 3	

			*See Instruction on Reverse Side	BY Z
de 18 U.: represent	S.C. Section 1001, makes it a crimitations as to any matter within its	ne for any person knowing jurisdiction.	ly and willfully to make to any department or ago	ency of the United States any false fictulous of the United States and false fiction of the United St
				FEB 0 8 1994
Approv Conditi	ved byions of approval, if any:		Title	Date
(This s	pace for Federal or State office use	e)		ACCEPTED FOR RECORD
I hereb	by certify that the foregoing is true  Hasely	and correct Ed Haselv		neer

## San Juan 29-6 #228 Workover

## 1-17-94

MIRU Drake #28. Blew well down. Circulated the & csq full of Produced H2O. Installed BPV in tbg hanger. ND WH & NU BOP's. Tested to 3000 psi (OK). Pulled tbg hanger and BPV. Drained up, secured equip. COOH w/tbg. PU, straped in hole w/6-1/4" bit, bit sub, 6 - 4-3/8" DC, X-O sub. RIH w/tbg tagged fill 3472'. swivel circ hole w/H2O. Drilled fill. Circ w/H2O. Circ. hole clean. Tagged fill (bridge) @ 3520. Drilled out to 3626' (PBTD) circ. hole clean. POOH w/tbg, layed down BHA. PU RIH w/6-1/4" bit, bit sub, X-O and 2-7/8" N-80 tbg workstring. Circulated hole with 750 MCFD air-recovering H2O. RIH w/tbg 3520' tag bridge drilled out and circulated w/air to PBTD # 3626'. POOH w/2-7/8" workstring, laying down. RIH w/2-3/8" expendable check, 1 jt 2-3/8" tbg 1.81" profile "F" Nipple and 108 jts 2-3/8" J-55 Tbg. EOT @ 3450, "F" nipple @ 3417. ND BOPs, NU WH tested well head to 2900 psi (OK). Drop ball, unable to pump off check w/2200 psi, drain up. Pressure up on tbg to 2500 psi unable to pump off check. RU H&H wireline. RIH with slickline, unable to beat ball out of expendable check. ND WH & NU BOPs tested BOP to 3000 psi (OK). POOH w/tbq & BHA. Expendable check had 1' coal fines between ball and check. Removed check-replace with notch collar. RIH w/notch collar, 1 jt tbg, 1.81" profile "F" nipple & 108 jts 2-3/8" J-55 8rd tbg. EOT 3450', "F" nipple @ 3417'. ND BOP & NU WH. Test WH to 3000 psi (OK) RD and released rig 1-24-94. Turned well back over to production.