

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division

Sundry Notices and Reports on Wells

1. Type of Well
GAS

2. Name of Operator

**BURLINGTON
RESOURCES**

OIL & GAS COMPANY

3. Address & Phone No. of Operator

PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M

825' FNL, 1145' FEL, Sec.36, T-29-N, R-7-W, NMPM, Rio Arriba County

API # (assigned by OCD)

30-039-20616

5. Lease Number

6. State Oil&Gas Lease #
E-5111-7-NM

7. Lease Name/Unit Name

San Juan 29-7 Unit

8. Well No.

#105

9. Pool Name or Wildcat
Basin Dakota

10. Elevation:

Type of Submission

☒ Notice of Intent

☐ Subsequent Report

☐ Final Abandonment

Type of Action

☐ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☒ Other - Tubing repair

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut off

☐ Conversion to Injection

13. Describe Proposed or Completed Operations

It is intended to repair the tubing on the subject well according to the attached procedure.

SIGNATURE

Regulatory Administrator June 3, 1998

VKH

(This space for State Use)

Approved by

Title

DEPUTY OIL & GAS INSPECTOR, DIST. #3

Date

JUN

8 1998

San Juan 29-7 Unit #105
Basin Dakota
Unit A, Sec. 36, T-29-N, R-07-W
Latitude / Longitude: 36° 41.23080' / 107° 31.00068'
Recommended Tubing Repair Procedure 5/22/98

NOTE: ALL DEPTHS ARE MEASURED FROM KB. KB to GL was 12'.

1. Comply with all NMOCD, BLM and Burlington safety and environmental regulations. Prior to moving in rig, make one-call and then verify rig anchors and dig pit.
2. MIRU workover rig. NU relief line and blow well down (kill with 2% KCL water only if necessary). ND WH and NU BOP. Test and record operation of BOP rams. Replace any WH valves that do not operate properly. Test secondary seal and install or replace if necessary.
3. **Dakota, 1-1/2", 2.9#, 10 rd Vinson tubing set at 7743' (241 jts).** Broach tubing and set tubing plug in nipple at **7709'**. Fill tubing with half of its volume of 2% KCL to insure the tubing plug will be held in place. Release donut, pick up additional joints of tubing and tag bottom, recording the depth. PBTD should be at +/- **7769'**. TOOH and LD 1-1/2" tubing. Visually inspect tubing for corrosion and scale, and notify Operations Engineer if they are present.
4. TIH with 3-7/8" bit, bit sub, and watermelon mill on 2-3/8" tubing and round trip to PBTD, cleaning out with air/mist. **NOTE: When using air/mist, mist rate must not be less than 12 bph.** Speak with Operations Engineer, and if necessary, determine the best way to remove scale from the casing and perforations.
5. TIH with one joint of 2-3/8" tubing with expendable check, F-nipple (one joint off bottom), then 1/2 of the 2-3/8" production tubing. Run a broach on sandline to insure that the tubing is clear. TIH with remaining 2-3/8" tubing and then broach this tubing. Replace any bad joints. CO to PBTD with air/mist.
6. PU above the top Dakota perforation at **7526'** and flow the well naturally, making short trips for clean-up when necessary. Obtain pitot gauge from casing and report this gauge after final clean-up.
7. Land tubing at **7710'**. ND BOP and NU WH. Pump off expendable check. Connect to casing and circulate air to assure that expendable check has pumped off. If well will not flow on its own, make swab run to SN. RD and MOL. Return well to production.

Recommended: *L. Tom Loveland* Operations Engineer **5/22/98** Approved: *Bruce W. Boyer* **6-1-98**
Drilling Superintendent

Contact:

L. Tom Loveland

Office 326-9771
Pager 324-2568
Home 564-4418