State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division

	Sundry Notices and R	Reports on Wells	
			# (assigned by OCD) 30-039-24843
1. Type of Well		5.	Lease Number Fee
GAS		6.	State Oil&Gas Lease
		-	
2. Name of Operator		7.	Lease Name/Unit Name
-			
BURLINGTON RESOURCES OIL &	GAS COMPANY		San Juan 29-7 Unit N
Val. 2		8.	
3. Address & Phone No. of Operato	or	<u>-</u>	551
PO Box 4289, Farmington, NM		9.	Pool Name or Wildcat
		_	Basin Fruitland Coal
4. Location of Well, Footage, Sec	c., T, R, M		Elevation:
1625'FSL, 1500'FWL, Sec.11, T-	-29-N, R-7-W, NMPM, Ri	lo Arriba County	
	Type of Ac	tion	
Type of Submission X Notice of Intent	_X_ Abandonment _	Change of Pl	ans
X Notice of Intent	Recompletion -	New Construc	
Subsequent Report	Plugging Back	Non-Routine	
	Casing Repair	Water Shut o	
Final Abandonment	Altering Casing	Conversion t	o Injection
,	Other -		
13. Describe Proposed or Comple	atad Onemations		
It is intended to plug and procedure.		well according t	o the attached
It is intended to plug and		well according t	o the attached
It is intended to plug and	abandon the subject volume (BB7) Regulatory	Supervisor	November 15, 2001
It is intended to plug and procedure. SIGNATURE MAN (all no	abandon the subject volume (BB7) Regulatory		November 15, 2001

San Juan 29-7 Unit NP #551

10/25/01

AIN # 498001

Basin Fruitland Coal

1625' FSL and 1500' FWL, Section 11, T29N, R7W Rio Arriba County, New Mexico, API #30-039-24843 Lat 36° 44.2608' / Long 107° 32.6538'

PLUG AND ABANDONMENT PROCEDURE

All cement volumes use 100% excess outside pipe and 50' excess inside pipe. The stabilizing wellbore Note: fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be ASTM Type II, mixed at 15.6 ppg with a 1.18 cf/sx yield.

- Install and test rig anchors. Prepare blow pit. Comply with all NMOCD, BLM and Burlington safety rules 1. and regulations. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on location. Blow well down; kill with water as necessary. ND wellhead and NU BOP and stripping head; test BOP.
- TOH and tally 99 joints 2-3/8" tubing (3110'); visually inspect the tubing. If necessary LD tubing and PU 2. workstring. Round-trip 4-1/2" gauge ring to 2850'.
- Plug #1 (Fruitland Coal perforations, 7" casing shoe and 4-1/2" liner top, 2850' 2649'): Set 4-1/2" 3. wireline CIBP or CR at 2850'. TIH with tubing and tag. Load casing with water and circulate well clean. Pressure test casing to 500#. If casing does not test, then spot or tag subsequent plugs as appropriate. Mix 31 sxs cement inside and spot a balanced plug inside the casing to isolate the Fruitland perforations and to cover the 7" casing shoe and 4-1/2" liner top. PUH to 2415'.
- Plug #2 (Kirtland and Ojo Alamo tops, 2415' 2081'): Mix 72 sxs cement and spot balanced plug inside 4. the casing to cover Kirtland and Ojo Alamo tops. PUH to 870'.
- Plug #3 (Nacimiento top, 870' 770'): Mix 28 sxs cement and spot balanced plug inside casing to cover 5. Nacimiento top. PUH to 279'.
- Plug #4 (Surface, 279' Surface): Mix 60 sxs cement and spot a balanced plug inside casing to surface, 6. circulate good cement out casing valve. TOH and LD tubing. Shut in well and WOC.
- ND BOP and cut off wellhead below surface casing flange. Install P&A marker with cement to comply 7. with regulations. RD, MOL and cut off anchors. Restore location per BLM stipulations.

Recommended: Zett AZell 11-12-01
Operations Engineer

Approval: Bouch 11-14-01
Drilling Manager

Sundry Required: YES NO
Approval: Regulatory

Approval: Regulatory

Brett Bradford

Office 326-9577 Pager 324-6906

Cell: 320-2631 Pager: 324-7546 Lease Operator: Jim Jones Gabe Archibeque Cell: 320-2478 Pager: 326-8256 Specialist: Cell: 320-2448 Pager: 327-8937 Bruce Voiles Foreman: