UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

_ maa 1 5 18 _ maa 1 5 18 _ Disti. 3 _ o _	8. W 9. A	ribe Name	, All. or e ement Nam
_ mag 1 5 18 _L COAN, [_ DIST. 3 _	27 U 8. W H 9. A	ribe Name Unit Agree	e ement Nam
_ mag 1 5 18 _L COAN, [_ DIST. 3 _	27 U 8. W H 9. A	ribe Name Unit Agree	e ement Nam
IL CON. [DIT. 3	8. W H 9. A	ell Name	
DITI. I	8. W H		& Number
	н 9. А		& Number
0	9. A	owell C #	~ 14 mm GT
0			‡1A
- 	•	PI Well N 0-045-217	
800'FSL 1655'FEL, Sec.1, T-29-N, R-8-W, NMPM		ield and	Pool
		Blanco Mesaverde County and State San Juan Co, NM	
	THER DA	ATA	_
Non-Rout	ine Fra		
Conversi	on to 1	Injection	
ject well acc	cording		
			• •
		-	127
		= i	• •
		and the	
		()	
d correct.		····	_
ory Administ	<u>rator</u> Da		
Team Lead at	e3	 3/11/99	·· <u></u>
	Action Change of New Consequence Non-Route Water Shade Conversion of Conversion o	CCE, REPORT, OTHER DA Action Change of Plans New Construction Non-Routine Fra Water Shut off Conversion to Deject well according according according according according according according according	CCE, REPORT, OTHER DATA Action Change of Plans New Construction Non-Routine Fracturing Water Shut off Conversion to Injection oject well according

Howell C #1A

Mesaverde 800'FSL, 1655' FEL

Unit O, Section 1, T-29-N, R-8-W

Latitude / Longitude: 36° 44.9450' / 107° 37.4313'

DPNO: 4795601 MV **Tubing Repair Procedure**

- Hold safety meeting. Comply with all NMOCD, BLM and Burlington safety and environmental 1. regulations. Test rig anchors and build blow pit prior to moving in rig. Notify BROG Regulatory (Peggy Bradfield 326-9727) and the appropriate Regulatory Agency prior to pumping any cement job. If an unplanned cement job is required, approval is required before the job can be pumped. If verbal approval is obtained, document approval in DIMS/WIMS. Allow as much time as possible prior to pump time in case the Agency decides to witness the cement job.
- MOL and RU workover rig. Obtain and record all wellhead pressures. NU relief line. Blow 2. well down and kill with 2% KCL water if necessary. ND WH and NU BOP with stripping head. Test and record operation of BOP rams. Have wellhead and valves serviced as necessary. Test secondary seal and replace/install as necessary.
- Mesaverde. 2-3/8", 4.7# tubing is set at 5529'. Release donut, pick up additional joints of tubing 3. and tag bottom. (Record depth.) PBTD should be at +/-5549'. TOOH with tubing. Visually inspect tubing for corrosion and replace any bad joints. Check tubing for scale build up and notify Operations Engineer.
- If fill is encountered, TIH with 3-7/8" bit, bit sub and watermelon mill on 2-3/8" tubing and ۷. round trip to below perforations, cleaning out with air/mist. NOTE: When using air/mist, minimum mist rate is 12 bph. If scale is present, contact Operations Engineer to determine methodology for removing scale from casing and perforations.
- 5. TIH with one joint of 2-3/8" tubing with an expendable check on bottom and a seating nipple one joint off bottom then ½ of the 2-3/8" production tubing. Run a broach on sandline to insure that the tubing is clear. TIH with remaining 2-3/8" tubing and then broach this tubing. Replace any bad joints. CO to PBTD with air/mist. PU above the perforations and flow the well naturally, making short trips for clean up when necessary.
- Land tubing at ±5437'. ND BOP and NU WH. Pump off expendable check. Connect to casing 6. and circulate air to assure that expendable check has pumped off. Obtain pitot gauge up the tubing. If well will not flow up the tubing, make swab run to SN. RD and MOL. Return well to production.

Recommended: M.E. Autus
Operations Engineer

Approved:

Bruce Days 23.99 Drilling Superintendent

Operations Engineer: Mary Ellen Lutey

Office - (599-4052) Home - (325-9387) Pager - (324-2671)

MEL/klg