UNITED		STATES	
DEPARTMENT	OF	THE	INTERIOR
BURRAU OF	T.AN	то ма	NACEMENT

Sundry Notices and Reports on Wells Type of Well GAS Name of Operator BURLINGTON RESOURCES Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700 Location of Well, Footage, Sec., T, R, M 1808'FSL, 1500'W, Sec. 14, T-29-N, R-8-W		Lease Number SF 078415 A If Indian, All. or Tribe Name
GAS . Name of Operator BURLINGTON RESOURCES . Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700 . Location of Well, Footage, Sec., T, R, M 1808'FSL, 1500'W, Sec. 14, T-29-N, R-8-W		
BURLINGTON RESOURCES 2. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700 3. Location of Well, Footage, Sec., T, R, M 1808'FSL, 1500'W, Sec. 14, T-29-N, R-8-W 2. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT,	7.	
BURLINGTON RESOURCES 2. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700 3. Location of Well, Footage, Sec., T, R, M 1808'FSL, 1500'W, Sec. 14, T-29-N, R-8-W 2. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT,		Unit Agreement Nam
PO Box 4289, Farmington, NM 87499 (505) 326-9700 Location of Well, Footage, Sec., T, R, M 1808'FSL, 1500'W, Sec. 14, T-29-N, R-8-W CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT,		
PO Box 4289, Farmington, NM 87499 (505) 326-9700 Location of Well, Footage, Sec., T, R, M 1808'FSL, 1500'W, Sec. 14, T-29-N, R-8-W CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT,	8.	Well Name & Number Roelofs A #2R
1808'FSL, 1500'W, Sec. K14, T-29-N, R-8-W 2. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT,	9.	API Well No. 30- 0 45-22374
2. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT,	10.	Field and Pool Blanco MV
	11.	County and State San Juan Co., NM
	OTHER	DATA
Type of Submission Type of Action _x_ Notice of Intent Abandonment Change	of Di	
x Notice of Intent Abandonment Change Recompletion New Co		
Subsequent Report Plugging Back Non-Ro		
Casing Repair Water		
Final Abandonment Altering Casing Conver		
X Other -tubing repair		
3. Describe Proposed or Completed Operations It is intended to repair tubing on the subject well accordance procedure.		o the attached
	_	
		ECEIVED JAN 1 3 1953
	@[[[GOM. DIV
· ·	management (management)	DIEL 3
4. I hereby certify that the foregoing is true and correct.		
igned May May hald (MEL6) Title Regulatory Admin.	1	Date 12/30/97
This space for Federal or State Office use) PPROVED BY Name W. Security Title Day		

Roelofs A #2R Mesaverde 1808'S 1500'W

Unit K. Section 14, T-20-N, R-68-W Latitude / Longitude: 36° 43.38° / 107° 38.93°

DPNO: 48343A
Tubing Repair Procedure

- Hold safety meeting. Comply with all NMOCD, BLM and Burlington safety and environmental regulations. Test rig anchors and build blow pit prior to moving in rig. Notify BROG Regulatory (Peggy Bradfield 326-9727) and the appropriate Regulatory Agency prior to pumping any cement job. If an unplanned cement job is required, approval is required before the job can be pumped. If verbal approval is obtained, document approval in DIMS/WIMS. Allow as much time as possible prior to pump time in case the Agency decides to witness the cement job.
- 2. MOL and RU workover rig. Obtain and record all wellhead pressures. NU relief line. Blow well down and kill with 2% KCL water if necessary. NU BOP with stripping head. Test and record operation of BOP rams. Have wellhead and valves serviced as necessary. Test secondary seal and replace/install as necessary.
- 3. Release donut, pick up additional joints of tubing and tag bottom. (Record depth.) TOOH with tubing. Visually inspect tubing for corrosion and replace any bad joints. Check tubing for scale build up and notify Operations Engineer.
- 4. If casing requires clean out, TIH with bit and bit sub and CO to PBTD prior to running casing scraper. Roundtrip casing scraper and bit to below preforations. (Do not clean out with casing scraper.) PU above perforations and flow the well naturally, making short trips for clean up when necessary. TOOH.
- 5. TIH with 2-3/8" tubing with an expendable check on bottom and a seating nipple one joint off bottom. Rabbit all tubing. CO to PBTD.
- 6. Land tubing near 5860'. ND BOP and NU wellhead. Pump off expendable check. Obtain final pitot gauge up the tubing. If well will not flow on it's own, make swab run to seating nipple. If a swab run is not necessary, run a broach on slickline to ensure that the tubing is clear. RD and MOL. Return well to production.

Recommended: ME fuctor	Approved:	
Operations Engineer		Drilling Superintendent
Mary Ellen Lutey		g
Office - (599-4052)		
Home - (325-9387)		
Pager - (324-2671)		

MEL/mel