submitted in lieu of Form 3160-5

UNITED STATES DEPARTMENT OF THE INTERIOR

DEPARTME	ITED STATES NT OF THE INTERIOR OF LAND MANAGEMENT	SB MOV 21
Sundry Not	ices and Reports on Wells	070 ELT PH 2: 17
		5. Lease Number
1. Type of Well		SF_0799347A 6. If Indian, All. or
GAS		Tribe Name
2. Name of Operator		7. Unit Agreement Nam
_		
RESOURCES AND	& GAS COMPANY	
OLE	& GAS COMPANI	8. Well Name & Number
3. Address & Phone No. of Opera	tor	Bolin #1A
PO Box 4289, Farmington, NM	87499 (505) 326-9700	9. API Well No.
4 Taggin of Wall David		30-045-23373
 Location of Well, Footage, S 1700'FSL 1480'FEL, Sec.30, T 		10. Field and Pool
1700 FBE 1400 FEE, 560.30, 1	-29-N, R-8-W, NMPM	Blanco Mesaverde
		11. County and State San Juan Co, NM
12. CHECK APPROPRIATE BOX TO IN		ORT, OTHER DATA
Type of Submission	Type of Action	
X Notice of Intent	AbandonmentCha	ange of Plans
Subsequent Report		V Construction
Subsequent Report		n-Routine Fracturing eer Shut off
Final Abandonment	Altering Casing Con	
_	_X_ Other -	1.022201 00 111,0001011
13. Describe Proposed or Comp.	leted Operations	
It is intended to repair t attached procedure	the tubing on the subject wel	l according to the
Signed Signey Stathice	foregoing is true and correct	
(This space for Federal or State APPROVED BY INDIAN W. Space	e Office use)	Data DEC 1 1998
APPROVED BY 13/ LAURING VV. 3 POR SALE	Title	Date DEC 1990

CONDITION OF APPROVAL, if any:

Bolin #1A Mesaverde

1700'FSL. 1480' FEL

Unit J, Section 30, T-29-N, R-8-W Latitude / Longitude: 36° 41.6473' / 107° 42.7999' DPNO: 48563.

Tubing Repair Procedure

- Hold safety meeting. Comply with all NMOCD, BLM and Burlington safety and environmental 1. regulations. Test rig anchors and build blow pit prior to moving in rig. Notify DROG Restrictory (Paggy Bradfield 326-9727) and the appropriate Regulatory Agency prior to pumping any cement job. If an unplanned cement job is required, approval is required before the job can be pumped. If verbal approval is obtained, document approval in DIMS/WIMS. Allow as much time as possible prior to pump time in case the Agency ascides to witness the cement job.
- MOL and RU workever rig. Obtain and record ail wellhead pressures. NU relief line. Blow 2. well down and kill with 2% KCL water if necessary. ND wellhead and NU BOP with stripping head. Test and record operation of BOP rams. Have wellhead and valves serviced as necessary. Test secondary seal and replace/install as necessary.
- Mesaverde, 2-3 8", 4.7# J-55 tubing is set at 5636'. Release donut, pick up additional joints of 3. tubing and tag bottom. (Record depth.) PBTD should be at +/- 5675'. TOOH with tubing. Visually inspect tubing for corrosion and replace any bad joints. Check tubing for scale build up and notify Operations Engineer.
- If fill. TIH with 3-7/8" bit, bit sub and watermelon mill on 2-3/8" tubing and round trip to below 4. perforations, cleaning out with air/mist. NOTE: When using air/mist, minimum mist rate is 12 bph. If scale is present, contact Operations Engineer to determine methodology for removing scale from easing anc perforations.
- TIH with one joint of 2-3/8" tubing with an expendable check on bottom and a seating nipple one 5. joint off bottom then ½ of the 2-3/8" production tubing. Run a broach on sandline to insure that the tubing is clear. TIH with remaining 2-3/8" tubing and then broach this tubing. Replace any bac joints. CO to PBTD with air/mist. PU above the perforations and flow the well naturally. making short trips for clean up when necessary.
- 6. Land tubing at ±555C'. ND BOP and NU WH. Pump off expendable check. Connect to casing and circulate air to assure that expendable check has pumped off. Obtain pitot gauge up the tubing. If well will not flow up the tubing, make swab run to SN. RD and MOL. Return well to production.

Recommended: M.E. Huttey
Operations Engineer

Approved: Drug () Bong 10 79.42

Drilling Superintendent

Operations Engineer:

Mary Ellen Lutey

Office - (599-4052) Home - (325-9387) Pager - (324-2671)