State of New Mexico Form C-103 Submit 3 Copies Revised 1-1-89 Energy, Minerals and Natural Resources Department to Appropriate District Office OIL CONSERVATION DIVISION DISTRICT I P.O. Box 1980, Hobbs, NM 88240 WELL API NO. P.O.Box 2088 3004508429 Santa Fe, New Mexico 87504-2088 DISTRICT II P.O. Drawer DD, Artesia, NM 88210 5. Indicate Type of Lease FEE M STATE __ DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410 6. State Oil & Gas Lease No. SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) Sammons Gas Com C 1. Type of Well: OIL WELL OTHER 8. Well No. Attention: 2. Name of Operator Dallas Kalahar **Amoco Production Company** 9. Pool name or Wildcat 3. Address of Operator 80201 Basin Dakota Colorado P.O. Box 800 Denver 4. Well Location 1450 Feet From The 270 Feet From The South Line Line and San Juan 29N 9W **NMPM** County Range Township Section 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 5802 RDB Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data SUBSEQUENT REPORT OF: **NOTICE OF INTENTION TO:** ALTERING CASING × REMEDIAL WORK PLUG AND ABANDON PERFORM REMEDIAL WORK PLUG AND ABANDONMENT COMMENCE DRILLING OPNS. **CHANGE PLANS** TEMPORARILY ABANDON CASING TEST AND CEMENT JOB PULL OR ALTER CASING **P&A Revisions** OTHER:_ OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Amoco Production Company intends to Plug and Abandon the Subject well. See Attached for revised procedure. This superceds the sundry dated 5-12-93. JUL2 6 1993 OIL CON. DIV. If you have any questions, please contact Dallas Kalahar at 303-830-5129. DIST. 3 I hereby certify that the information above is true and complete to the best of my knowledge and belief. **Business Analyst** DATE ______07-22-1993 SIGNATURE TELEPHONE NO. (303) 830-5129 Dallas Kalahar TYPE OR PRINT NAME (This space for State Use) TITLE DEPUTY OIL & GAS INSPECTOR, DIST. #3

CONDITIONS OF APPROVAL, IF ANY:

REVISED 7-22-93

Sammons Gas Com C #1 PXA Procedures

- Check location for anchors. Install if necessary. Test anchors.
- 2. MIRUSU. Blow down well. Kill if necessary with fresh water.
- 3. POOH with 2 3/8" tbg. RIH with tbg and cement retainer. Set retainer at 6575'. Test casing integrity to #1000. Squeeze perfs at 6612' and 6740' with 52.39 cuft cement. Pull out of retainer and spot a cement plug to 4950'. (218.15 cuft cement)
- Run free point on 4 1/2" casing. Back off casing below the PC and Fruitland (deeper the better). Run CBL to determine top of cement.
- 5. RIH with perf gun and shoot squeeze holes to isolate MV, PC, FT, and OJ. RIH with retainers where needed and set above squeeze holes and attempt to circulate to surface. Pull out of retainer and displace cement to surface. WOC and add more cement as need to fill to surface.
- 6. NUBOPE. Cut off casing and wellhead. Install PXA maker according to BLM or State requirements.
- 7. Rehabilitate location according to BLM or state requirements.

SAMMONS GAS COM C #1 LOCATION, NO7 29N 09W SINGLE BASIN DATOTA ORIGINAL COMPLETION 08/64 LAST FILE UPDATE 5/93 BY CSW

