

APPROVED
AUG 14 1953
ACTING DISTRICT ENGINEER

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office New Mexico
Lease No. 04139
Unit Phillips
14-02-001-538

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 13, 1953

Well No. 5-35 is located 990 ft. from S line and 1650 ft. from W line of sec. 35

35 Section 35 30N 6W N. M. P. M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Blanco El Arriba New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6552 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

This well is committed to the San Juan 30-6 Unit, henceforth El
Paso Natural Gas Company is assuming the operation of this well.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company EL PASO NATURAL GAS COMPANY

Address BOX 997

FARMINGTON, NEW MEXICO

By S. Schulman


Title Petroleum Engineer.

Age Group	1970	1980	1990	2000	2010	2020
0-14	20	18	15	12	10	10
15-24	15	14	13	12	11	10
25-34	12	11	10	9	8	7
35-44	10	9	8	7	6	5
45-54	8	7	6	5	4	3
55-64	6	5	4	3	2	1
65-74	4	3	2	1	0	0
75+	5	6	7	8	10	20

1. The first step in the process of the investigation is the identification of the problem. This is done by the investigator who is responsible for the investigation. The investigator must identify the problem and the scope of the investigation. The investigator must also identify the objectives of the investigation and the methods to be used. The investigator must also identify the resources available for the investigation.

ALL INFORMATION CONTAINED HEREIN IS UNCLASSIFIED
DATE 02-01-2001 BY 60322 UCBAW

1. The following information is being furnished to you for your information only. It is not intended to be used for any other purpose.



OIL CONSERVATION COMMISSION		
AZTEC DISTRICT OFFICE		
No. Copies Forwarded	5	
DISTRIBUTION		
Operator	2	
Supervisor	1	
Engineering Office	1	
State Land Office		
U. S. G. S.		
Training Center		
File	1	✓