## UNITED STATES

## DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells		
	53 JUL 13 PH 2:	Lease Number SF-080714-A
1. Type of Well GAS	070 FALLER CH, (	
2. Name of Operator		7. <b>Unit Agreement Name</b> San Juan 30-6 Unit
OIL & GAS COMPANY  3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9	<del></del>	8. Well Name & Number San Juan 30-6 Unit#45 9. API Well No.
4. Location of Well, Footage, Sec., T, R, M 1600'FNL 1600'FEL, Sec. 15, T-30-N, R-6-W, NMPM		30-039-07852  10. Field and Pool Blanco Mesaverde  11. County and State Rio Arriba Co, NM
X Notice of Intent Abandonment Recompletion Subsequent Report Plugging Back	f Action  Change of New Const Non-Routi	Plans ruction ne Fracturing
Casing Repair Final Abandonment Z Other - tubin	ng Conversion	
13. Describe Proposed or Completed Operations  It is intended to repair the tubing on the sattached procedure.	ubject well, acco	ording to the
	N'E	CEIVED
		CON. DIV. DIST. 3
14. I hereby certify that the foregoing is true a		
(This space for Federal or State Office use) APPROVED #\$/ Duane W. Spencer	Date	JUL 17 1998

San Juan 30-6 Unit # 45

Mesa Verde 1600'N, 1600'E

Unit G, Section 15, T-30N-N, R-06-W

Latitude / Longitude: 36° 48.92' / 107° 26.77'

**DPNO: 69767 Tubing Repair Procedure** 

- Hold safety meeting. Comply with all NMOCD, BLM and Burlington safety and environmental 1. regulations. Test rig anchors and build blow pit prior to moving in rig. Notify BROG Regulatory (Peggy Bradfield 326-9727) and the appropriate Regulatory Agency prior to pumping any cement job. If an unplanned cement job is required, approval is required before the job can be pumped. If verbal approval is obtained, document approval in DIMS/WIMS. Allow as much time as possible prior to pump time in case the Agency decides to witness the cement job.
- MOL and RU workover rig. Obtain and record all wellhead pressures. NU relief line. Blow well 2. down and kill with 2% KCL water if necessary. NU BOP with stripping head. Test and record operation of BOP rams. Have wellhead and valves serviced as necessary. Test secondary seal and replace/install as necessary.
- Mesa Verde, 2 3/8", 4.7#, J-55 tubing is set at 5541'. Release donut, pick up additional joints of 3. tubing and tag bottom. (Record depth.) PBTD should be at +/- 5627. TOOH with tubing. Visually inspect tubing for corrosion and replace any bad joints. Check tubing for scale build up and notify Operations Engineer.
- If fill, TIH with 4-3/4" bit and bit sub on 2 3/8" tubing and round trip to below perforations, 4. cleaning out with air/mist. NOTE: When using air/mist, minimum mist rate is 12 bph. If scale is present, TIH with mill through perforations. TOOH with mill.
- TIH with one joint of 2 3/8" tubing with an expendable check on bottom and a seating nipple one 5. joint off bottom then ½ of the 2 3/8" production tubing. Run a broach on sandline to insure that the tubing is clear. TIH with remaining 2 3/8" tubing and then broach this tubing. Replace any bad joints. CO to PBTD with air/mist. PU above the perforations and flow the well naturally, making short trips for clean up when necessary.

Land tubing at 5490'. ND BOP and NU WH. Pump off expendable check. Connect to casing 6. and circulate air to assure that expendable check has pumped off. Obtain pitot gauge up the tubing. If well will not flow on it's own, make swab run to SN. RD and MOL. Return well to production.

Recommended: M

Operations Engineer

Approved:

Buce D. Borre 5-20-98
Drilling Superintendent

Mike Haddenham

Office - (326-9577)

Home - (326-3102)

Pager - (327-8427)

Production Foreman - Bruce Voiles

Office - (326-9571)

Pager - (326-8842)

MDH/ssv