UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

	#ECFIN	/Elle	
Sundry N	otices and Reports on Well		
	93 JUL 13 1	PM 2: 07 5.	Lease Number SF-080713
1. Type of Well GAS	070 Fremis	TON, NM 6.	•
2. Name of Operator		7.	Unit Agreement Name San Juan 30-6 Unit
BURLINGTON	IL & GAS COMPANY		
3. Address & Phone No. of Ope		8.	Well Name & Number San Juan 30-6 Unit#40X
PO Box 4289, Farmington,		9.	API Well No. 30-039-07874
4. Location of Well, Footage, 990'FSL 1010'FWL, Sec. 12,			Field and Pool Blanco Mesaverde
		11.	County and State Rio Arriba Co, NM
12. CHECK APPROPRIATE BOX TO			DATA
Type of Submission X Notice of Intent	Type of Act Abandonment	<pre>con Change of Pl</pre>	ans
		New Construc	
Subsequent Report		Non-Routine	
		_ _ Water Shut o	
Final Abandonment	Altering Casing _X_ Other - tubing rep		o Injection
13. Describe Proposed or Co	ompleted Operations		····
It is intended to repai attached proced	r the tubing on the subjecure.	t well, accord	ing to the
		וח	E de la company
		(E) (T.C.)	JUL 20 1998
		900	
			The state of the s
14. I hereby certify that t	the foregoing is true and c	orrect.	
Signed Mill Mill full	(MH) Title Requlatory A	<u>dministrator</u> D	ate 7/6/98 TLW
(This space for Federal or St APPROVED BY /S/ Duane W. Spence	Title	Date J	
CONDITION OF APPROVAL, if any	<i>t</i> :		

San Juan 30-6 Unit #40X

Mesa Verde 990'S, 1010'W

Unit M, Section 12, T-30N-N, R-06-W Latitude / Longitude: 36° 49.34' / 107° 25.15'

> DPNO: 69762 Tubing Repair Procedure

- 1. Hold safety meeting. Comply with all NMOCD, BLM and Burlington safety and environmental regulations. Test rig anchors and build blow pit prior to moving in rig. Notify BROG Regulatory (Peggy Bradfield 326-9727) and the appropriate Regulatory Agency prior to pumping any cement job. If an unplanned cement job is required, approval is required before the job can be pumped. If verbal approval is obtained, document approval in DIMS/WIMS. Allow as much time as possible prior to pump time in case the Agency decides to witness the cement job.
- 2. MOL and RU workover rig. Obtain and record all wellhead pressures. NU relief line. Blow well down and kill with 2% KCL water if necessary. NU BOP with stripping head. Test and record operation of BOP rams. Have wellhead and valves serviced as necessary. Test secondary seal and replace/install as necessary.
- Mesa Verde, 2 3/8", 4.7#, J-55 tubing is set at 5519'. Release donut, pick up additional joints of tubing and tag bottom. (Record depth.) PBTD should be at +/- 5520'. TOOH with tubing. Visually inspect tubing for corrosion and replace any bad joints. Check tubing for scale build up and notify Operations Engineer.
- 4. If fill, TH with 4-3/4" bit and bit sub on 2-3/8" tubing and round trip to below perforations, cleaning out with air/mist. NOTE: When using air/mist, minimum mist rate is 12 bph. If f scale is present, TIH with mill through perforations. TOOH with mill.
- 5. TIH with one joint of 2-3/8" tubing with an expendable check on bottom and a seating nipple one joint off bottom then ½ of the 2-3/8" production tubing. Run a broach on sandline to insure that the tubing is clear. TIH with remaining 2-3/8" tubing and then broach this tubing. Replace any bad joints. CO to PBTD with air/mist. PU above the perforations and flow the well naturally, making short trips for clean up when necessary

6. Land tubing at 5490'. ND BOP and NU WH. Pump off expendable check. Connect to casing and circulate air to assure that expendable check has pumped off. Obtain pitot gauge up the tubing. If well will not flow on it's own, make swab run to SN. RD and MOL. Return well to production.

Recommended: ///.

Operations Engineer

Approved:

Drilling Superintendent

Mike Haddenham

Office - (326-9577)

Home - (326-3102)

Pager - (327-8427)

Production Foreman - Bruce Voiles

Office - (326-9571)

Pager - (326-8842)

MDH/ssv