UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wel	ls	
	5.	Lease Number
	5.	SF-079002
1. Type of Well GAS	6.	If Indian, All. or Tribe Name
	7.	Unit Agreement Name
2. Name of Operator		
RESOURCES OIL & GAS COMPANY		San Juan 30-6 Unit
3. Address & Phone No. of Operator	8.	Well Name & Number
PO Box 4289, Farmington, NM 87499 (505) 326-9700	9.	San Juan 30-6 U #32 API Well No. 30-039-07887
4. Location of Well, Footage, Sec., T, R, M	10.	Field and Pool
1650'FNL, 1150'FEL, Sec.7, T-30-N, R-6-W, NMPM		Blanco Mesaverde
•	11.	County and State Rio Arriba Co, NM
Subsequent Report Plugging Back		Fracturing off
13. Describe Proposed or Completed Operations		
It is intended to repair the tubing in the subjection procedure.	ct well accordi	ng to the attached
	and the total participation of the contract of	
DECE N jul 1	1997 D	
	ON. DIV. St. 3	
e e e e e e e e e e e e e e e e e e e		
14. I hereby certify that the foregoing is true and		
Signed May Dadhud (ROS7) Title Regulator		or Date 6/16/97
$^{\prime}$		

San Juan 30-6 Unit #32 Blanco Mesaverde 1650' FNL, 1150' FEL NE Section 7, T-30-N, R-6-W

Latitude / Longitude: 36°49.7873' / 107°29.9222'
Recommended Tubing Repair Procedure

- 1. Comply with all NMOCD, BLM and Burlington safety and environmental regulations. Test rig anchors and build blow pit prior to moving in rig. Notify BROG Regulatory (Peggy Bradfield 326-9727) and the appropriate Regulatory Agency prior to pumping any cement job. If an unplanned cement job is required, approval is required before the job can be pumped. If verbal approval is obtained, document approval in DIMS/WIMS. As much time as possible to the pump time is needed for the Agency to be able to show up for the cement job.
- MOL and RU workover rig. Blow well down. NU 7-1/16" 3000 psi (6" 900 series) BOP with stripping head. Test and record operation of BOP rams. Kill well with 1% KCL water only if necessary. Have christmas tree serviced as needed.
- Release donut, pick up additional joints of tubing and tag bottom (record depth). TOOH
 with tubing. Visually inspect tbg for corrosion, and replace any bad joints. LD bull plug
 and perf joint. Check tbg for scale and notify Operations Engineer.
- 4. TIH with casing scraper, bit and bit sub, and round trip to below perforations. TOOH. TIH with RBP on tubing and set at approximately 50' above top perf. Pressure test the casing to 500 psig. If pressure test fails, isolate leak and contact Operations Engineer for cement squeeze procedure.
- 5. Unload casing with air prior to releasing RBP. Release RBP and TOOH. TIH with tubing with an expendable check on bottom and a seating nipple one jt off bottom. Rabbit all tubing. CO to PBTD with air.
- 6. Land tubing near bottom perforation. ND BOP and NU wellhead. Pump off expendable check and record final gauges. Return well to production.

Recommended:

Rob Stanfield Phone 326-9715

Pager 324-2674