

submitted in lieu of Form 3160-5

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells

1. Type of Well  
GAS

2. Name of Operator  
SOUTHLAND ROYALTY COMPANY

3. Address & Phone No. of Operator  
PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M  
1040'FSL, 1040'FWL, Sec.4, T-30-N, R-5-W, NMPM

5. Lease Number  
NM-4456

6. If Indian, All. or  
Tribe Name

7. Unit Agreement Name

8. Well Name & Number  
Cat Draw #1

9. API Well No.  
30-039-20121

10. Field and Pool  
Basin Dakota

11. County and State  
Rio Arriba Co, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

☒ Notice of Intent

☐ Subsequent Report

☐ Final Abandonment

Type of Action

☒ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☐ Other -

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut off

☐ Conversion to Injection

13. Describe Proposed or Completed Operations

It is intended to plug and abandon the subject well according to the attached procedure and wellbore diagram.

RECEIVED  
FEB - 6 1995

OIL CON. DIV.  
DIST. 3

14. I hereby certify that the foregoing is true and correct.

Signed [Signature] (ROS7) Title Regulatory Affairs Date 1/16/95

(This space for Federal or State Office use)

APPROVED BY \_\_\_\_\_ Title \_\_\_\_\_

CONDITION OF APPROVAL, if any:

APPROVED  
AS AMENDED

FEB 01 1995  
DISTRICT MANAGER

NMOC

# PERTINENT DATA SHEET

<b>WELLNAME:</b> Cat Draw #1	<b>DP NUMBER:</b> 7920 <b>PROP. NUMBER:</b> 0020618																																								
<b>WELL TYPE:</b> Basin Dakota	<b>ELEVATION:</b> GL: 6380' KB: 6393'																																								
<b>LOCATION:</b> 1040' FSL 1040' FWL SW Sec. 4, T30N, R5W Rio Arriba County, New Mexico	<b>INITIAL POTENTIAL:</b> AOF 792 MCF/D  <b>SICP:</b> May, 1993 1661 PSIG																																								
<b>OWNERSHIP:</b> GWI: 25.000000% NRI: 21.875000%	<b>DRILLING:</b> SPUD DATE: 07-19-68 COMPLETED: 08-19-68 TOTAL DEPTH: 8025' PBDT: 7890' COTD: 7890'																																								
<b>CASING RECORD:</b> <table border="1" style="width: 100%; border-collapse: collapse; margin-top: 10px;"> <thead> <tr> <th>HOLE SIZE</th> <th>SIZE</th> <th>WEIGHT</th> <th>GRADE</th> <th>DEPTH</th> <th>EQUIP.</th> <th>CEMENT</th> <th>TOC</th> </tr> </thead> <tbody> <tr> <td>15-1/4"</td> <td>13-3/8"</td> <td>48.0#</td> <td></td> <td>306'</td> <td>-</td> <td>300 sx</td> <td>surface</td> </tr> <tr> <td>12-1/4"</td> <td>9-5/8"</td> <td>36.0#</td> <td></td> <td>3425'</td> <td>-</td> <td>300 sx</td> <td>2405' (75%)</td> </tr> <tr> <td>8-3/4" &amp; 7-7/8"</td> <td>4-1/2"</td> <td>11.6#</td> <td></td> <td>8024'</td> <td>DV Tool @ 5705' Float Collar @ 8001'</td> <td>200 sx 175 sx</td> <td>4950' (75%) 7780' (CBL)</td> </tr> <tr> <td>Tubing</td> <td>2-3/8" EUE</td> <td>4.7#</td> <td>J-55</td> <td>7863'</td> <td></td> <td></td> <td></td> </tr> </tbody> </table> <p style="text-align: center; margin-top: 5px;">254 jts 2-3/8" EUE, 4.7#, J-55, tbq set at 7863'.</p>		HOLE SIZE	SIZE	WEIGHT	GRADE	DEPTH	EQUIP.	CEMENT	TOC	15-1/4"	13-3/8"	48.0#		306'	-	300 sx	surface	12-1/4"	9-5/8"	36.0#		3425'	-	300 sx	2405' (75%)	8-3/4" & 7-7/8"	4-1/2"	11.6#		8024'	DV Tool @ 5705' Float Collar @ 8001'	200 sx 175 sx	4950' (75%) 7780' (CBL)	Tubing	2-3/8" EUE	4.7#	J-55	7863'			
HOLE SIZE	SIZE	WEIGHT	GRADE	DEPTH	EQUIP.	CEMENT	TOC																																		
15-1/4"	13-3/8"	48.0#		306'	-	300 sx	surface																																		
12-1/4"	9-5/8"	36.0#		3425'	-	300 sx	2405' (75%)																																		
8-3/4" & 7-7/8"	4-1/2"	11.6#		8024'	DV Tool @ 5705' Float Collar @ 8001'	200 sx 175 sx	4950' (75%) 7780' (CBL)																																		
Tubing	2-3/8" EUE	4.7#	J-55	7863'																																					
<b>FORMATION TOPS:</b> <table style="width: 100%; margin-top: 10px;"> <tr> <td style="width: 40%;">Nacimiento</td> <td style="width: 20%;">1205'</td> <td style="width: 20%;">Mesaverde</td> <td style="width: 20%;">5293'</td> </tr> <tr> <td>Ojo Alamo</td> <td>2395'</td> <td>Gallup</td> <td>6666'</td> </tr> <tr> <td>Kirtland</td> <td>2610'</td> <td>Dakota</td> <td>7751'</td> </tr> <tr> <td>Fruitland</td> <td>3028'</td> <td></td> <td></td> </tr> <tr> <td>Pictured Cliffs</td> <td>3178'</td> <td></td> <td></td> </tr> </table>		Nacimiento	1205'	Mesaverde	5293'	Ojo Alamo	2395'	Gallup	6666'	Kirtland	2610'	Dakota	7751'	Fruitland	3028'			Pictured Cliffs	3178'																						
Nacimiento	1205'	Mesaverde	5293'																																						
Ojo Alamo	2395'	Gallup	6666'																																						
Kirtland	2610'	Dakota	7751'																																						
Fruitland	3028'																																								
Pictured Cliffs	3178'																																								
<b>LOGGING:</b> CBL, TL, I-GR, FDC																																									
<b>PERFORATIONS</b> 7780' - 98', w/4 SPF, 7844' - 50', 7860' - 66', w/2 SPF, 7900' - 30', w/4 SPF, Total 216 holes.																																									
<b>STIMULATION:</b> 7780' - 7866': Treated w/64,170 gal of treated wtr and 40,000# 40/60 sand.  7900' - 7930': Treated w/55,070 gal of wtr and 40,000# 40/60 sand, tailed w/4,000# 20/40 sand.																																									
<b>WORKOVER HISTORY:</b> Nov. 1982: LD production string. TIH w/2-3/8" wrk string & csg scraper. CO to 7890'. Set pkr @ 4650' and pressure tested backside to 1500 psi. Reset pkr @ 7765' & pressure backside to 550 psi. Reset pkr below perms @ 7889'. Swab tbq to 3500', wouldn't swab down. Backside flowing. Set drillable BP @ 7890'. Pressure tested to 1500 psi below pkr. Land 254 jts 2-3/8" EUE, 8rd, tbq @ 7863'. Swabbed fluid to 7855'. Shut-in for pressure build up.																																									
<table style="width: 100%;"> <tr> <td style="width: 50%; vertical-align: top;"> <b>PRODUCTION HISTORY:</b>            Cumulative as of Oct. 94: <u>Gas</u> 321.1 MMcf    <u>Oil</u> 0 MBbl            Current Rate:        <u>0 Mcfd</u>        <u>0 Bopd</u> </td> <td style="width: 50%; vertical-align: top;"> <b>DATE OF LAST PRODUCTION:</b>            Sept., 1992        <u>Gas</u> 0.43 Mcf/D    <u>Oil</u> 0 bbl/D         </td> </tr> </table>		<b>PRODUCTION HISTORY:</b> Cumulative as of Oct. 94: <u>Gas</u> 321.1 MMcf <u>Oil</u> 0 MBbl Current Rate: <u>0 Mcfd</u> <u>0 Bopd</u>	<b>DATE OF LAST PRODUCTION:</b> Sept., 1992 <u>Gas</u> 0.43 Mcf/D <u>Oil</u> 0 bbl/D																																						
<b>PRODUCTION HISTORY:</b> Cumulative as of Oct. 94: <u>Gas</u> 321.1 MMcf <u>Oil</u> 0 MBbl Current Rate: <u>0 Mcfd</u> <u>0 Bopd</u>	<b>DATE OF LAST PRODUCTION:</b> Sept., 1992 <u>Gas</u> 0.43 Mcf/D <u>Oil</u> 0 bbl/D																																								
<b>PIPELINE:</b> NWPC																																									

## PLUG & ABANDONMENT PROCEDURE

1-11-95

Cat Draw #1  
Basin Dakota  
SW Section 4, T-30-N, R-05-W  
Rio Arriba Co., New Mexico

Note: All cement volumes use 100% excess outside pipe and 50' excess inside pipe. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures.

1. Install and/or test rig anchors. Prepare blow pit. Comply to all NMOCD, BLM and Meridian safety rules and regulations.
2. MOL and RU daylight pulling unit. Blow well down; kill with water if necessary. ND wellhead and NU BOP and stripping head; test BOP.
3. POH and tally 2-3/8", 4.7#, tubing (254 jts at 7863', SN @ 7863'), visually inspect. If necessary, PU 2" workstring. PU 4-1/2" casing scraper or wireline gauge ring and round trip to 7730'.
4. **Plug #1 (Dakota Perforations, 7890' - 7701')**: PU and RIH with a 4-1/2" cement retainer and set at 7730'; pressure test tubing to 1000#. Establish rate into Dakota perfs. Mix and pump 30 sx Class B cement, squeeze 24 sx below retainer into Dakota perforations and spot 6 sx above the retainer to 7701'. POH to 6800'. Load well with water and circulate clean. Pressure test 4-1/2" casing to 500#. POH with setting tool.
5. **Plug #2 (Gallup top, 6716' - 6616')**: Perforate 4 squeeze holes at 6716'. If casing pressure tested, then establish rate into squeeze holes. PU 4-1/2" cement retainer and RIH; set at 6666'. Establish rate into squeeze holes. Mix and pump 64 sx Class B cement, squeeze 52 sx cement outside casing and leave 12 sx cement inside 4-1/2" casing from 6716' to 6616'. POH to 5343'.
6. **Plug #3 (Mesaverde top, 5343' - 5243')**: Mix 12 sx Class B cement and spot a balanced plug inside casing from 5343' to 5243' over Mesaverde top. POH with tubing. Pressure test casing to 500#.
7. **Casing Cut**: RIH with wireline and locate casing collars from 3450' to 3300'. Perforate 4-1/2" casing at 3475'. Establish circulation to surface out 9-5/8" intermediate valve; circulate annulus clean. ND BOP and tubing head. Weld slip on collar on 4-1/2" casing. RIH with casing shot and shoot off 4-1/2" casing at approximately 3400'. NU 10" BOP and RU casing crew. POH and LD 4-1/2" casing.
8. **Plug #4 (4-1/2" Casing stub & 9-5/8" casing shoe, 3475' - 3340')**: PU 9-5/8" cement retainer and RIH; set at 3390' or 10' above casing stub. Mix and pump 70 sxs Class B cement, squeeze 51 sx cement below retainer over 4-1/2" casing stub and leave 19 sx cement above retainer. POH with tubing and LD setting tool. Pressure test 9-5/8" casing to 500#.

## PLUG & ABANDONMENT PROCEDURE

1-11-95

Page 2

Cat Draw #1  
Basin Dakota  
SW Section 4, T-30-N, R-05-W  
Rio Arriba Co., New Mexico

9. **Plug #5 (Pictured Cliffs and Fruitland tops, 3228' - 2978')**: RIH with open ended tubing to 3228'. Mix 111 sx Class B cement and spot a balanced plug inside casing from 3228' to 2978' over Pictured Cliffs and Fruitland tops. POH to 2660'.
10. **Plug #6 (Kirtland top, 2660' - 2560')**: Mix 56 sx Class B cement and spot a balanced plug inside casing from 2660' to 2560' over Kirtland top. POH with tubing. Pressure test 9-5/8" casing to 500#.
11. **Plug #7 (Ojo Alamo top, 2445' - 2345')**: Perforate 6 squeeze holes at 2445' through 9-5/8" casing. If casing tested, establish rate into squeeze holes, then RIH with open ended tubing to below squeeze holes. Mix and spot 109 sx Class B cement inside casing; POH above cement and squeeze 53 sx cement outside casing. If casing did not test then PU 9-5/8" packer or cement retainer and do an inside/outside squeeze over the Ojo Alamo top. POH; WOC and tag cement if necessary. POH with tubing and LD packer or setting tool. Pressure test casing to 500#.
12. **Plug #8 (Nacimiento top, 1255' - 1155')**: Perforate 6 squeeze holes at 1255' through 9-5/8" casing. If casing tested, establish rate into squeeze holes, then RIH with open ended tubing to below squeeze holes. Mix and spot 109 sx Class B cement inside casing; POH above cement and squeeze 53 sx cement outside casing. If casing did not test then PU 9-5/8" packer or cement retainer and do an inside/outside squeeze over the Ojo Alamo top. POH; WOC and tag cement if necessary. POH and LD tubing.
13. **Plug #8 (Surface)**: Perforate 4 squeeze holes at 356'. Establish circulation out bradenhead valve. Mix approximately 245 sx Class B cement and pump down 9-5/8" casing, circulate good cement out bradenhead valve. Shut in well and WOC.
14. ND BOP and cut off casing below surface casing flange. Install P&A marker with cement to comply with regulations. RD, Move off location, cut off anchors and restore location.

Recommended:

  
Operations Engineer

Approval:

\_\_\_\_\_  
Production Superintendent

# CAT DRAW #1

PROPOSED P & A

Basin Dakota

SW Sec. 4, T-30-N, R-5-W, Rio Arriba County, NM

Today's Date: 1/11/95


Spud: 7/19/68

Completed: 8/19/68

58 JUL 17 11:05

09 JUL 1968 11:05

Plug #9: 356' - Surface',  
Cmt w/245 sx Class B cmt



# CAT DRAW #1

CURRENT  
Basin Dakota

SW Sec. 4, T-30-N, R-5-W, Rio Arriba County, NM

97-11-17 11:30:55

070 11-17-95, NM

Today's Date: 1/11/95  
Spud: 7/19/68  
Completed: 8/19/68

