UNITED STATES

DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT	RECEIVED	
Sundry Notices and Reports on We	ells	
98	JUL 13 PM 2: G7	Lease Number SF-080712-A
1. Type of Well GAS) Multerou, (4	If Indian, All. or Tribe Name
2. Name of Operator	7.	Unit Agreement Name San Juan 30-6 Unit
BURLINGTON RESOURCES OIL & GAS COMPANY		
	8.	Well Name & Number
3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700	9.	San Juan 30-6 Unit#49R API Well No.
4. Location of Well, Footage, Sec., T, R, M		30-039-20330 Field and Pool Blanco Mesaverde
1180'FNL 1615'FEL, Sec. 27, T-30-N, R-6-W, NMPM	11.	County and State Rio Arriba Co, NM
Type of Submission X Notice of Intent Subsequent Report Final Abandonment Abandonment Casing Repair Altering Casing X Other - tubing	Action Change of Pl New Construc Non-Routine Water Shut o Conversion t	ans tion Fracturing ff
13. Describe Proposed or Completed Operations		
It is intended to repair the tubing on the sub attached procedure.		ling to the
	DEC N	国V国D 2 0 1898
		16 0 17 17 18 18 18 18 18 18 18 18 18 18 18 18 18
14. I hereby certify that the foregoing is true and Signed May Willhard (MH) Title Regulator		Date 7/7/98

TLW (This space for Federal or State Office use)

San Juan 30-6 Unit # 49R

Mesa Verde 1180'N, 1615'E

Unit B, Section 27, T-30N-N, R-06-W Latitude / Longitude: 36° 47.25' / 107° 26.78'

DPNO: 69770 **Tubing Repair Procedure**

- Hold safety meeting. Comply with all NMOCD, BLM and Burlington safety and environmental 1. regulations. Test rig anchors and build blow pit prior to moving in rig. Notify BROG Regulatory (Peggy Bradfield 326-9727) and the appropriate Regulatory Agency prior to pumping any cement job. If an unplanned cement job is required, approval is required before the job can be pumped. If verbal approval is obtained, document approval in DIMS/WIMS. Allow as much time as possible prior to pump time in case the Agency decides to witness the cement job.
- 2. MOL and RU workover rig. Obtain and record all wellhead pressures. NU relief line. Blow well down and kill with 2% KCL water if necessary. NU BOP with stripping head. Test and record operation of BOP rams. Have wellhead and valves serviced as necessary. Test secondary seal and replace/install as necessary.
- Mesa Verde, 2 3/8", 4.7#, J-55 tubing is set at 5879'. Release donut, pick up additional joints of 3. tubing and tag bottom. (Record depth.) PBTD should be at +/- 5902'. TOOH with tubing. Visually inspect tubing for corrosion and replace any bad joints. Check tubing for scale build up and notify Operations Engineer.
- If fill, TIH with 3 7/8" bit and bit sub on 2 3/8" tubing and round trip to below perforations, 4. cleaning out with air/mist. NOTE: When using air/mist, minimum mist rate is 12 bph. If scale is present, TIH with mill through perforations. TOOH with mill.
- TIH with one joint of 2 3/8" tubing with an expendable check on bottom and a seating nipple one 5. joint off bottom then ½ of the 2 3/8" production tubing. Run a broach on sandline to insure that the tubing is clear. TIH with remaining 2 3/8" tubing and then broach this tubing. Replace any bad joints. CO to PBTD with air/mist. PU above the perforations and flow the well naturally, making short trips for clean up when necessary.

Land tubing at 5750'. ND BOP and NU WH. Pump off expendable check. Connect to casing 6. and circulate air to assure that expendable check has pumped off. Obtain pitot gauge up the tubing. If well will not flow on it's own, make swab run to SN. RD and MOL. Return well to production.

Recommended: M

Operations Engineer

Approved:

Bruch Bown 5-21-95
Drilling Superintendent

Mike Haddenham

Office - (326-9577)

Home - (326-3102)

Pager - (327-8427)

Production Foreman - Bruce Voiles

Office - (326-9571)

Pager - (326-8842)

MDH/ssv