submitted in lieu of Form 3160-5

UNITED STATES							
DEPARTM	ENT	OF	TH	E :	INTI	ERIC	R
BUREAU	OF	LAN	D :	MAI	NAGI	EMEN	ΙT

77.11	
Sundry Notices and Reports on Wells	59 JUL 15 PH 2
	5. Lease Number 8
	U/O F.SF+07.9002
1. Type of Well	6. If Indian, All. or
GAS	Tribe Name
Onb	
	7. Unit Agreement Name
2. Name of Operator	
RURI.INGTON	
RESOURCES OIL & GAS COMPANY	San Juan 30-6 Unit
<b>VII</b> • • • • • • • • • • • • • • • • • •	8. Well Name & Number
3. Address & Phone No. of Operator	San Juan 30-6 U #88A
PO Box 4289, Farmington, NM 87499 (505) 326-9700	9. API Well No.
	30-039-22211
4. Location of Well, Footage, Sec., T, R, M	10. Field and Pool
1535'FNL, 1660'FWL, Sec.7, T-30-N, R-6-W, NMPM	WC:30N6W7F Pict.Cliffs/
	Blanco Mesaverde
	11. County and State
	Rio Arriba Co, NM
THE PARTY OF MOREOTE DEPARTMENT OF MOREOTE D	DEM OWNED DATA
12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPO	ORT, OTHER DATA
Tipe of table of the second of	ange of Plans
	w Construction
	n-Routine Fracturing
Casing Repair Wat	ter Shut off
Final Abandonment Altering Casing Con	nversion to Injection
Other -	
13. Describe Proposed or Completed Operations	
It is intended to recomplete the subject well in the	Pictured Cliffs formation
according to the attached procedure and wellbo	ore diagram. The well will
then be dualled.	
then be dualica.	
$\epsilon$	
	3 E [ V E D ]
and 6	
9/2/	9 12 100g
	m 2 9 1800
$m_{l}$	Jor - Willo
W C	
	n Gwas
$\mathcal{N}(0)$	DISTO .
•	TELLO BILLO
the that the foregoing is true and corre	ot
14. I hereby certify that the foregoing is true and corre	CC.
Signed May Star hard (JLDOpps) Title Regulatory	Administrator Date 7/12/99
(This space for Federal or State Office use)	JUL 2 7 1999
APPROVED BY /S/ Duane W. Spencer Title Team Lead, Petroleum Me	napemante JUL &   1333
CONDITION OF APPROVAL, if any:	
**************************************	

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

District I PO Box 1980, Hobbs, NM 88241-1980 District II

PO Drawer DD, Artesia, NM 88211-0719

District III 1000 Rio Brazos Rd., Aztet, NM 87410

District IV PO Box 2088, Santa Fe, NM 87504-2088 State of New Mexico
Energy, Minerals & Natural Resources Department

OIL CONSERVATION DIVISION PO Box 2088 Santa Fe, NM 87504-2088

Form C-102 Revised February 21, 1994  $\frac{REOEINE}{\text{Appropriate District Office}}$  Submit to Appropriate District Office State Lease - 4 Copies Fee Lease - 3 Copies

AMENDED REPORT WELL LOCATION AND ACREAGE DEDICATION PLAT WORK, NM

<del></del>	API Number Q. Q. Pool Code					' Pool Na	me					
			96957 Pool Code 172319			WC:30N6W7F Pict.Cliffs/Blanco Mesaverde						
30-039		'Property Name					' Well Number					
* Property © 7469	ode	San Juan 30-6 Unit						8	88A			
		Operator Name						* Elevation				
'OGRID!	io.					•				Ì		51 CB
14538		B	urlin	gton R	esour	ces !	0il & Gas	Com	pany		<u> </u>	51 GR
					" Sur	rtace	Location				. 1:	1 Communication
UL or lot no.	Section	Township	Range	Lot Idn	Feet from	n the	North/South line	1 -	from the	East/Wes West		RA
F	7	30N	6W		1535		North	<u> </u>		West	<u>.</u>	
	·		11 Bot	tom Hol	e Locat	ion If	Different Fro	om S	urface			
UL or iot no.	Section	Township	Range	Lot Ida	Feet from		North/South line		from the	East/Wes	st line	County
OLU: AK BU.			-							1		
12 Dedicated Ac	_ il fains	or lafill 1 14	Consolidatio	n Code 1 15 (	Order No.							
PC - 160	)											
MV-W/320	VARIE	WILL DE	ASSIGNE	D TO TH	IS COM	PLETIC	ON UNTIL ALL	INT	RESTS F	IAVE BE	EN CC	NSOLIDATED
NO ALLO	WABLE	OR A	NON-ST	ANDARD	UNIT H	IAS BE	EN APPROVED	) BY	THE DIV	ISION		
			-	<del></del>		T					CER	TIFICATION
16									I hereby cen	ife that the i	n formatio	n contained herein is
<b>l</b>				i		1			true and con	nplese to the	best of m	y knowledge and belief
1 1		35		4		[						
		53		i				1	_		_	
11				1					/ <i>)</i> /	′ •	<b>⋞</b> ⋰	.
									20	Mu V	Kud	" pied
1		1							Signature	1		-
<b>H</b>	660	<del> </del> '				ļ			Peggy Printed Na	Brad	fiel	d
								ł			۸ ۵-	inistrator
				1 0	~i1	ות	L+		Regul Title			inistrator
				Uri	ginal	. rla	t from , Jr. 8-6	_79		11-1	2-	99
				Fre	u D.	VELI	, 51. 5-6	-, )	Date			
<u> </u>		<del> </del>							18STIR	VEYO	CEF	RTIFICATION
									I berein ce	rrife that the	well loca	tion shown on this plat
		1							was piotted	from field #	rotes of ec	tual surveys made by me
1				1				į	or under m	y supervision the best of m	n, and tha	u the same is true and
				1					correct to	ne oest oj m	, <del></del>	
11				1					Date of Si			
11				jl .					Date of Su	•	Profession	al Surveyer:
<del> </del>		-		_					3 Surmine	NEW JOSEP OF 1		. <del>.</del>
				ŧ,								
				1								
				Ï								
11									1			
		İ		1					Certificate	Number		
<b>#</b> }		1		11			1		H			

#### San Juan 30-6 Unit #88A

# Pictured Cliffs Recompletion Procedure Unit F, Section 7, T30N, R06W

Lat: 36°- 49.80468'/Long: 107° - 30.40926'

This well is currently completed in the Mesaverde. It is intended to recomplete the Pictured Cliffs interval and produce the well as a dual with a production packer set in the 7" casing, thereby producing the Pictured Cliffs up the annulus. The Pictured Cliffs will be completed in a single stage with 125,000 lbs 20/40 sand in a 70Q 20lb linear gel.

#### PRE RIG WORK

- 1. RU Halliburton mast truck. RU Halliburton logging truck and equipment.
- 2. Close master valve. RU lubricator. Open master valve. Flow well to sales line.
- Lower logging tool through tubing to zone of interest. Correlate logged GR to openhole GR. Adjust depth as necessary.
- 4. Run GR-TMDL across Pictured Cliffs interval from 3600-2600'.
- 5. Pull logging tool into lubricator. Close master valve. RD lubricator. Open master valve. Flow well to sales line.
- 6. RD logging truck. RD mast truck. Move off of location.

#### RIG WORK

- 7. Inspect location and test rig anchors. Comply with all NMOCD, BLM, Forestry & BR rules and regulations. Dig flowback pit or set flowback tank. Haul to location 3600', 1-1/2", 2.76 lb/ft, IJ tubing, 2 jts 2-7/8" N-80 tubing and 3-400 bbl frac tanks.
- 8. MIRU. Fill 400 bbl tanks with 2% KCL water. Run fluid tests on water. Filter water based upon stimulation company water analysis. Record and report SI pressures on tubing, casing and bradenhead. Lay blowdown line. Blow well down and kill with 2% KCL water as necessary. ND WH and NU BOP with flow tee and stripping head. Test operation of rams. NU blooie line and 2-7/8" relief line. Service wellhead for dual well service.
- 9. PU on 2-3/8" Mesaverde production string. Lower end of tubing to PBTD. Tag and record PBTD in DFW. TOOH with 2-3/8" Mesaverde production string set at 6039'. Visually inspect tubing, note and report any corrosion and/or scale in/on tubing. Replace bad joints as needed.
- 10. Run a gauge ring for 7", 20 lb/ft, J-55 casing to 4-1/2" liner top at 3600'. ND wireline company. If unable to run gauge ring to 4-1/2" liner top, PU 6-3/4" bit and 7", 20 lb/ft, J-55 casing scraper and round trip to liner top.
- 11. TIH with 7" tubing set RBP on 2-3/8" tubing. Set RBP at ~3550'. Release from RBP and fill casing with approximately 145 bbls 2% KCL. PUH to 3470'. Spot 5 bbls 15% HCL acid across Pictured Cliffs perforation interval (3410-3470'). TOOH.

All acid on this well to contain the following additives per 1000 gals.

2 gai	HAI-81M	Corrosion inhibitor
5 gal	FE-1A	Iron Control
5 gal	FE-2A	Iron Control
1 gal	SSO-21	Surfactant
1 gal	ClaSta XP	Clay control

- 12. NU wireline company. Run GR-CBL-CCL from PBTD to 200' above TOC behind 7" casing. Evaluate CBL. Good cement bond must exist from PBTD to 3300' to continue with the procedure.
- 13. TIH with 7" packer and 2 joints of 2-7/8" tubing for wellhead isolation. Set packer and pressure test casing to 3000 psi. Bleed off pressure. Release packer and TOOH.
- 14. Contact Jennifer L. Dobson for Pictured Cliffs perforation depths.
- 15. NU wireline. Perforate Pictured Cliffs with 28 holes using select fire HSC guns loaded with Owens HSC-3125 306T 12 gram charges set at 2 SPF (Av. perf diameter 0.30", Av. pen. -17.48" in concrete). ND wireline company.
- 16. TIH with 7" packer and 2-3/8" tubing. Set packer at 3200'.
- 17. Pressure test surface lines to 4600 psi. Hold tailgate safety meeting. Establish an injection rate into perfs with 2% KCL water observing a maximum pressure of 3600 psi. Once pressure has broken back and stabilized, shut pumps down and obtain an ISIP. Continue to breakdown Pictured Cliff perforations with 25 bbls 15% HCL. Drop 56 RCN 7/8" 1.3 specific gravity balls evenly spaced. Attempt to ball off to 3000 psi surface pressure. Use the same additives as in Step 11. ND stimulation company.
- 18. Bleed off pressure. Release packer. Lower packer to 3480' to knock balls off of perforations. TOOH. Stand back 2-3/8" tubing.
- 19. TIH with 7" packer and 2 jts 2-7/8" tubing for wellhead isolation. Set packer.
- 20. Maximum surface treating pressure is 3000 psi. Fracture stimulate the Pictured Cliffs with 125,000 lbs 20/40 Arizona sand in 1200 bbls 70Q 20 lb linear gel foam at 35 BPM constant downhole rate. Maintain a bottom hole frac gradient of 0.65 psi/ft throughout job. Tag sand with 3 radioactive tracers. When sand is in hopper and the concentration begins to drop, call flush. Maintain previous stage's slurry and N<sub>2</sub> rates. Quick flush to 100 ft above top perforation. Average surface treating pressure will be 2,359 psi. Perforation and casing friction is estimated to be 594 psi. Treat per the following schedule:

Stage	Downhole Foam Volume (gals)	Clean Gel Volume (gals)	N2 Volume (MSCF)	Sand Volume (lbs)
Pad	5,000	1,500	64.1	
1.0 ppg	7,500	2,250	96.0	7,500
2.0 ppg	11,875	3,563	151.9	23,750
3.0 ppg	11,250	3,375	143.8	33,750
4.0 ppg	15,000	4,500	191.7	60,000
Flush (100' above top perf)	5,529	2,256	59.9	0
Totals	56,154	17,443	707	125,000

Record ISIP, 5 minute, 10 minute and 15 minute SIP. RD stimulation company.

- 21. RU flowback line and choke manifold. Flow well back after 30 minutes to 1 hour. Open well to pit, starting with a 8/64" choke. If minimal sand is being produced, change to a larger choke size (10/64"). If choke plugs off, shut well in and remove obstruction from choke and return to flowback. Continue increasing choke size and cleaning well up until fluid returns are negligible.
- 22. When pressures allow, release packer and TOOH. LD 2-7/8" tubing and packer.
- 23. TIH with 7" RBP retrieving head on 2-3/8" tubing and clean out to RBP at 3550'. Alternate between natural flow and blow stages for clean up. When water rates are 3 BPH, obtain a Pictured Cliffs pitot gauge. When sand production allows, latch on to RBP. Release RBP and allow pressures to equalize. TOOH with RBP and LD.
- 24. If fill was encountered in Step 9, TIH with 3-7/8" bit on 2-3/8" and clean out any possible fill to PBTD at 6101'. TOOH.
- 25. TIH with an expendable check, one 2-3/8" joint, standard SN, approximately 80 joints of 2-3/8" EUE tubing, Baker 7" R-3 production packer with 1.9 ID and remaining 2-3/8" EUE tubing. Broach tubing. Set packer at approximately 3550'. Land end of 2-3/8" tubing as close to 6039' as possible. PU and TIH with one joint of 1-1/2", 2.76#, IJ tubing bull plugged with a perforated sub, aluminum pump off plug, and 1.375" seating nipple. TIH with remaining 1-1/2", 2.76#, IJ tubing. Broach tubing while RIH. Land 1-1/2" tubing at bottom perforation.
- 26. ND BOP. NU dual wellhead and manifold assembly. Ensure all connections on wellhead are tight. Pump off 2-3/8" expendable check. Flow well up 2-3/8" tubing. Pump off 1-1/2" expendable check. Flow well up 1-1/2" tubing. Shut in both stings and monitor pressure for packer leakage test. Open MV side and obtain stabilized pitot gauges at 15, 30, 45, and 60 min up the MV tubing string. Monitor Pictured Cliffs side for pressure communication. Open Pictured Cliffs side and obtain stabilized pitot gauges at 15, 30, 45, and 60 min up the Pictured Cliffs tubing string. Record on DFW report. RDMO. Contact Production Operations for well tie-in.
- 27. RU Protechnics. Run After-Frac log across Pictured Cliffs (3410-3470') through the Mesaverde 2-3/8" production string. RD Pro-Technics.

Recommended:	duction Engineer	Approved:	Approved:			
		Approved: Team Lead	<b>Eval</b> 7/6/99 der			
Contact:						
Jennifer Dobson	599-4026 (work)	564-3244 (home)	324-2461 (pager)			

# San Juan 30-6 Unit #88A

Unit F, Section 7, T30N, R6W Rio Arriba County, NM

Lat: 36° - 49.80468'/Long: 107° - 30.40926'

### **Current Schematic**

## **Proposed Schematic**

