| OIL CONSERVATION DIVISION DISTRIBUTION SANTA FE FILE SANTA FE, NEW MANGE 087501 SOURCE FILE OIL CON. D. Store Foreit C-103 Revised 10-1- SOURCE Store Free St | STATE OF NEW MEXICO ENERGY AND MINIERALS DEPARTMENT | | | |
|--|--|---|--------------------------------|---|
| SUNDRY NOTICES AND REPORTS ON WELLS SUNDRY NOTICES ON REPORTS ON WELLS SUNDRY NOTICES AND REPORTS ON WELLS SUNDRY NOTICES OF REAL PROPERTY OF THE WELLS SUBJECT OF SUPPLY OF THE WELLS OF | | | 5444 | |
| SUNDRY NOTICES AND REPORTS ON WELLS SUNDRY NOTICES ON REPORTS ON WELLS SUNDRY NOTICES AND REPORTS ON WELLS SUNDRY NOTICES OF REAL PROPERTY OF THE WELLS SUBJECT OF SUPPLY OF THE WELLS OF | | OIL CONSERVATION | MIXISION TO | · · |
| SUNDRY NOTICES AND REPORTS ON WELLS SUNDRY NOTICES ON REPORTS ON WELLS SUNDRY NOTICES AND REPORTS ON WELLS SUNDRY NOTICES OF REAL PROPERTY OF THE WELLS SUBJECT OF SUPPLY OF THE WELLS OF | SANTA FE | P. O. BOX 2010 | | Form C-103 Revised 10-1-7 |
| SUNDRY NOTICES AND REPORTS ON WELLS SUNDRY NOTICES AND REPORT OF S | FILE | SANTA FE, NEW MENT | -0 8/501 | |
| SUNDRY NOTICES AND REPORTS ON WELLS SUNDRY NOTICES AND REPORTS ON WELLS WE WAS ON THE TRANSPORTED TO THE TRANSPORT OF THE T | U.\$.G.\$. | . 8.7 | EF 51 5 1000 | Sa. Indicate Type of Lease |
| SUNDRY NOTICES AND REPORTS ON WELLS SUBJECT TO SUPPLY NOTICES AND REPORTS ON THE SUBJECT TO SUBJECT T | | · | JAM 2 - 1303 | State Fee K |
| Address of Operator Heyse Oil, Inc. R. W. (309 454-E078 Rio Chana Rio Chana 1. Unit Agreement Home Reyse Oil, Inc. R. W. (309 454-E078 Rio Chana Rio Litani Rio Lessina Rio Chana Rio Chana Rio Chana Rio Chana Rio Litani Rio Lessina Rio Chana Rio Chana Rio Chana Rio Litani Rio Lit | OPERATOR | | IL CON. DIV | 5, State Oil & Gas Lease No. |
| Name of Operator Heyse Oil, Inc. Address of Operator Heyse Oil, Inc. Address of Operator 10 Chama Richards Address of Operator 212 College Park Dr. #4, Normal, II 61761 11 | | | | |
| Name of Operator Heyse Oil, Inc. R.* (309 454-8098 Rio Chama Rio Chama Reddress of Operator 212 College Park Dr. #4, Normal, II 61761 10. Field and Pool, or Wildcon Wildcat District Wildcat District Wildcat District Wildcat District The East time, section 2 rowsenis 30N same 32 superiors Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: Subsequent Report of: Subsequent Report of: Appropriate Box To Indicate Nature of Notice, Report or Other Data Subsequent Report of: Subsequent Report of: Subsequent Report of: Subsequent Report of: Appropriate South Subsequent Report of: Subsequent Report of: Subsequent Report of: Appropriate South Subsequent Report of: Subseq | | | | 7. Unit Agreement Name |
| Heyse Oil, Inc. Address of Operator 212 College Park Dr. #4, Normal, II 61761 Location of Well Vall College Park Dr. #4, Normal, II 61761 Location of Well Vall College Park Dr. #4, Normal, II 61761 Location of Well Vall College Park Dr. #4, Normal, II 61761 Location of Well Vall College Park Dr. #4, Normal, II 61761 Location of Well Vall College Park Dr. #4, Normal, II 61761 Location of Well Vall College Park Dr. #4, Normal, II 61761 Location of Well Vall College Park Dr. #4, Normal, II 61761 Location of Well Vall College Park Dr. #4, Normal, II 61761 Location of Well Vall College Park Dr. #4, Normal, II 61761 Location of Well Location of Well College Park Dr. #4, Normal, II 61761 Location of Well Location of Well Location of Well College Park Dr. #4, Normal, II 61761 Location of Well Location of Well Location of Well Location of Mell College Park Dr. #4, Normal, II 61761 College Park Dr. #4, Normal, II 61761 Location of Well College Park Dr. #4, Normal, II 61761 Location of Well Location of Well Location of Mell College Park Dr. #4, Normal, II 61761 Location of Well Location of Mell Location of Mell College Park Dr. #4, Normal, II 61761 Location of Well College Park Dr. #4, Normal, II 61761 Location of Well Location of Mell College Park Dr. #4, Normal, II 61761 Location of Well Location of Mell College Park Dr. #4, Normal, II 61761 Location of Mell Location of Mell College Park Dr. #4, Normal, II 61761 Location of Mell College Park Dr. #4, Normal, II 61761 Location of Mell Loca | | OTHER- | | • |
| Heyse 011, Inc. Address of Operators 212 College Park Dr. #4, Normal, II 61761 Location of Well December of Well Location of Well Lo | Name of Operator | | | 8. Form or 1 ease lunns |
| 212 College Park Dr. #4, Normal, II 61761 Comparison of Well Comparison of Well Comparison of Market Park | Hevse Oil. Inc. | P. H (300) | USH dra | T |
| 2 TOWNSHIP CASHED TO SHOW WHETHER JAMES AND ARRADON TO SHOW MELLINE AND ARRADON THE SHOWLD IT SET TOWN THE SHOWLD IT SHOW THE SHOWLD IT SHOW THE SHOWLD IT SHOW THE SHOWLD IT SHOW WHETHER AND ARRADON THE SHOWLD IT SHOW THE SHOWLD IT | Address of Operator | | 757-8078 | |
| Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed or 7° surface casing which was cemented and circulated by Halliburton Services late the same day at 11 PM. 50 saks of class A cement with 2% Calcium Chloride and gel flush. Slurry volume was 59 cu. ft. The casing used was 17 lbs in weight. Approximate cement slurry temperature was 60 F. when mixed. 2. After lengthy repairs on rig, casing was tested to 700 psi with pressure drop to 650 psi in 45 minutes. This test was done on December 18, 1989 at Approximately noon cement having set about 36 hrs. Compressive cement strength was over 3,000 psi calculated. 3. Plug was drilled out at 6 pm. 12,18,1938 and 5 ft of new hole was drilled with 6½ bit when main engine on the rig failed. Operations | 212 Callers Paris | on #U Normal II 61761 | | 7. TELL NO. |
| The East line, section 2 youngelf 30N annee 3E will and profit of the Annual Profit and | Location of Well | 71. 74, NOTHAL, 11 01/01 | | <u>.</u> |
| Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: ACCOMMENCE DAILLINE DAYS. CHARGE PLANS CASING TEST LANG CEMERT JAS ACHIELIAN CASING CHARGE PLANS COMMENCE DAILLINE DAYS CASING TEST LANG CEMERT JAS ACHIELIAN CASING COMMENCE DAILLINE DAYS CASING TEST LANG CEMERT JAS ACHIELIAN CASING COMMENCE DAILLINE DAYS CASING TEST LANG CEMERT JAS ACHIELIAN CASING COMMENCE DAILLINE DAYS CASING TEST LANG CEMERT JAS ACHIELIAN CASING COMMENCE DAILLINE DAYS CASING TEST LANG CEMERT JAS ACHIELIAN CASING COMMENCE DAILLINE DAYS CASING TEST LANG CEMERT JAS ACHIELIAN CASING COMMENCE DAILLINE DAYS CASING TEST LANG CEMERT ACHIELIAN CASING COMMENCE DAILLINE DAYS CASING TORCH COMMENCE DAILLINE DAYS ACHIELIAN CASING COMMENCE DAILLINE DAYS ACHIELIAN CASING COMMENCE DAILLINE DAYS ACHIELIAN CASING COMMENCE DAILLINE | | 0 | 1 505 | |
| Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: ACCOMM REMIDIAL WORK CHANGE PLANS CHANGE PLANS COMMENCE DRILLING OPNS. CASING TEST AND COMMENCE DRILLING OPNS. CASING TOUR AND ABANDON TO THE PROPERTOR OF THE SHAPPONT OF THE REPORT OF THE SHAPPONT OF THE SHAPPON | UNIT LETTER | 10 FEET FROM THE SOUTH LINE AN | D 1, 525 PEET FROM | NIIdcat DAKS 74 |
| Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: **TORM REWIGHAL WORK** **COMMENCE PROPERTOR:** **TORM REWIGHAL WORK** **COMMENCE PROPERTOR:** **TORM REWIGHAL WORK** **COMMENCE DRILLING OPPS.** **COMMENCE DRILLING OPPS.** | | | | |
| Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PLUE AND ABANDON | THE East LINE, SECTION_ | 2 TOWNSHIP 30N RANG | 16 3E HMPM. | |
| Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PLUE AND ABANDON | | | | |
| Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: Subsequent Report of: | | | ₹, etc.) | 12. County |
| Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: Subsequent Report of: | | 7980 GL | ļ | Rio Arriba |
| NOTICE OF INTENTION TO: Subsequent Report of: | Check App | | | |
| PLUS AND ABANDON CHANGE PLANS CHANGE PLANS CHANGE PLANS CASING TEST AND CEMENT JOS X OTHER CHANGE PLANS CASING TEST AND CEMENT JOS X OTHER CHANGE PLANS CASING TEST AND CEMENT JOS X OTHER Shut Down For Rig Redairs ALTERINE CASING PLUG AND ABANDONHMENT CASING TEST AND CEMENT JOS X PLUG AND ABANDONHENT ALTERINE CASING PLUG AND ABANDONHMENT CASING TEST AND CEMENT JOS X PLUG AND ABANDONHMENT ALTERINE CASING PLUG AND ABANDONHMENT CASING TEST AND CEMENT JOS X ALTERINE CASING PLUG AND ABANDONHMENT CASING TEST AND CEMENT JOS X ALTERINE CASING PLUG AND ABANDONHMENT JOS X ALTERINE CASING PLUG AND ABANDONHMENT JOS X ALTERINE CASING PLUG AND ABANDONHMENT JOS X ALTERINE CASING CASING TEST AND CEMENT JOS X ALTERINE CASING PLUG AND ABANDONHMENT JOS X ALTERINE CASING ALTERINE CASING ALTERIA DAY CASING TEST AND CEMENT JOS X | NOTICE OF INTE | NTION TO: | | |
| Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) see nute 1703. 1. Commenced Drilling Dec. 16, 1988. Set 11 feet of 95/8" conductor pipe, did not cement conductor, then drilled 8 3/4 hole and set 249' feet of 7° surface casing which was cemented and circulated by Halliburton Services late the same day at 11 PM. 50 saks of class A cement with 2% Calcium Chloride and gel flush. Slurry volume was 59 cu. ft. The casing used was 17 lbs in weight. Approximate cement slurry temperature was 60 F. when mixed. 2. After lengthy repairs on rig, casing was tested to 700 psi with pressure drop to 650 psi in 45 minutes. This test was done on December 18, 1988 at Approximately noon cement having set about 36 hrs. Compressive cement strength was over 3,000 psi calculated. 3. Plug was drilled out at 6 pm 12,18,1988 and 5 ft of new hole was drilled with 6½ bit when main engine on the rig failed. Operations | | | SUBSEQUENT | REPORT OF: |
| Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) see nute 1703. 1. Commenced Drilling Dec. 16, 1988. Set 11 feet of 95/8" conductor pipe, did not cement conductor, then drilled 8 3/4 hole and set 249' feet of 7° surface casing which was cemented and circulated by Halliburton Services late the same day at 11 PM. 50 saks of class A cement with 2% Calcium Chloride and gel flush. Slurry volume was 59 cu. ft. The casing used was 17 lbs in weight. Approximate cement slurry temperature was 60 F. when mixed. 2. After lengthy repairs on rig, casing was tested to 700 psi with pressure drop to 650 psi in 45 minutes. This test was done on December 18, 1988 at Approximately noon cement having set about 36 hrs. Compressive cement strength was over 3,000 psi calculated. 3. Plug was drilled out at 6 pm 12,18,1988 and 5 ft of new hole was drilled with 6½ bit when main engine on the rig failed. Operations | | | () | |
| Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed or 7° surface casing which was cemented and circulated by Halliburton Services late the same day at 11 PM. 50 saks of class A cement with 2% Calcium Chloride and gel flush. Slurry volume was 59 cu. ft. The casing used was 17 lbs in weight. Approximate cement slurry temperature was 60 F. when mixed. 2. After lengthy repairs on rig, casing was tested to 700 psi with pressure drop to 650 psi in 45 minutes. This test was done on December 18, 1988 at Approximately noon cement having set about 36 hrs. Compressive cement strength was over 3,000 psi calculated. 3. Plug was drilled out at 6 pm 12,18,1988 and 5 ft of new hole was drilled with 6½ bit when main engine on the rig failed. Operations | Ħ | PLUG AND ABANDON AEMEDIAL | WORK | ALTERING CASING |
| Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) see note itos. 1. Commenced Drilling Dec. 16, 1988. Set 11 feet of 95/8" conductor pipe, did not cement conductor, then drilled 8 3/4 hole and set 249' feet of 7° surface casing which was cemented and circulated by Halliburton Services late the same day at 11 PM. 50 saks of class A cement with 2% Calcium Chloride and gel flush. Slurry volume was 59 cu. ft. The casing used was 17 lbs in weight. Approximate cement slurry temperature was 60 F. when mixed. 2. After lengthy repairs on rig, casing was tested to 700 psi with pressure drop to 650 psi in 45 minutes. This test was done on December 18, 1983 at Approximately noon cement having set about 36 hrs. Compressive cement strength was over 3,000 psi calculated. 3. Plug was drilled out at 6 pm 12,18,1988 and 5 ft of new hole was drilled with 6½ bit when main engine on the rig failed. Operations | = | COMMENCE | DRILLING OPHS, | PLUG AND ABANDISHMENT |
| Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) see nule 1703. 1. Commenced Drilling Dec. 16, 1988. Set 11 feet of 95/8" conductor pipe, did not cement conductor, then drilled 8 3/4 hole and set 249' feet of 7° surface casing which was cemented and circulated by Halliburton Services late the same day at 11 PM. 50 saks of class A cement with 2% Calcium Chloride and gel flush. Slurry volume was 59 cu. ft. The casing used was 17 lbs in weight. Approximate cement slurry temperature was 60 F. when mixed. 2. After lengthy repairs on rig casing was tested to 700 psi with pressure drop to 650 psi in 45 minutes. This test was done on December 18, 1988 at Approximately noon cement having set about 36 hrs. Compressive cement strength was over 3,000 psi calculated. 3. Plug was drilled out at 6 pm 12,18,1988 and 5 ft of new hole was drilled with 6½ bit when main engine on the rig failed. Operations | LL ON ALTER CASHE | | | |
| Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) see note 17°. 1. Commenced Drilling Dec. 16, 1988. Set 11 feet of 95/8" conductor pipe, did not cement conductor, then drilled 8 3/4 hole and set 249' feet of 7° surface casing which was cemented and circulated by Halliburton Services late the same day at 11 PM. 50 saks of class A cement with 2% Calcium Chloride and gel flush. Slurry volume was 59 cu. ft. The casing used was 17 lbs in weight. Approximate cement slurry temperature was 60 F. when mixed. 2. After lengthy repairs on rig, casing was tested to 700 psi with pressure drop to 650 psi in 45 minutes. This test was done on December 18, 1988 at Approximately noon cement having set about 36 hrs. Compressive cement strength was over 3,000 psi calculated. 3. Plug was drilled out at 6 pm 12,18,1988 and 5 ft of new hole was drilled with 6½ bit when main engine on the rig failed. Operations | | OTHER | Shut Down For | Rig Repairs x |
| Commenced Drilling Dec. 16, 1988. Set 11 feet of 95/8" conductor pipe, did not cement conductor, then drilled 8 3/4 hole and set 249' feet of 7° surface casing which was cemented and circulated by Halliburton Services late the same day at 11 PM. 50 saks of class A cement with 2% Calcium Chloride and gel flush. Slurry volume was 59 cu. ft. The casing used was 17 lbs in weight. Approximate cement slurry temperature was 60 F. when mixed. After lengthy repairs on rig, casing was tested to 700 psi with pressure drop to 650 psi in 45 minutes. This test was done on December 18, 1988 at Approximately noon cement having set about 36 hrs. Compressive cement strength was over 3,000 psi calculated. Plug was drilled out at 6 pm 12,18,1988 and 5 ft of new hole was drilled with 6½ bit when main engine on the rig failed. Operations | OTHER | OI | | |
| Commenced Drilling Dec. 16, 1988. Set 11 feet of 95/8" conductor pipe, did not cement conductor, then drilled 8 3/4 hole and set 249' feet of 7° surface casing which was cemented and circulated by Halliburton Services late the same day at 11 PM. 50 saks of class A cement with 2% Calcium Chloride and gel flush. Slurry volume was 59 cu. ft. The casing used was 17 lbs in weight. Approximate cement slurry temperature was 60 F. when mixed. After lengthy repairs on rig casing was tested to 700 psi with pressure drop to 650 psi in 45 minutes. This test was done on December 18, 1988 at Approximately noon cement having set about 36 hrs. Compressive cement strength was over 3,000 psi calculated. Plug was drilled out at 6 pm 12,18,1988 and 5 ft of new hole was drilled with 6½ bit when main engine on the rig failed. Operations | | | | |
| Commenced Drilling Dec. 16, 1988. Set 11 feet of 95/8" conductor pipe, did not cement conductor, then drilled 8 3/4 hole and set 249' feet of 7° surface casing which was cemented and circulated by Halliburton Services late the same day at 11 PM. 50 saks of class A cement with 2% Calcium Chloride and gel flush. Slurry volume was 59 cu. ft. The casing used was 17 lbs in weight. Approximate cement slurry temperature was 60 F. when mixed. After lengthy repairs on rig.casing was tested to 700 psi with pressure drop to 650 psi in 45 minutes. This test was done on December 18, 1988 at Approximately noon cement having set about 36 hrs. Compressive cement strength was over 3,000 psi calculated. Plug was drilled out at 6 pm 12,18,1988 and 5 ft of new hole was drilled with 6½ bit when main engine on the rig failed. Operations | Describe Proposed or Completed Operational SEE RULE 1 (03. | ons (Clearly state all pertinent desails, and giv | e pertinent dates, including e | stimated date of starting any proposed |
| did not cement conductor, then drilled 8 3/4 hole and set 249' feet of 7° surface casing which was cemented and circulated by Halliburton Services late the same day at 11 PM. 50 saks of class A cement with 2% Calcium Chloride and gel flush. Slurry volume was 59 cu. ft. The casing used was 17 lbs in weight. Approximate cement slurry temperature was 60 F. when mixed. 2. After lengthy repairs on rig, casing was tested to 700 psi with pressure drop to 650 psi in 45 minutes. This test was done on December 18, 1988 at Approximately noon cement having set about 36 hrs. Compressive cement strength was over 3,000 psi calculated. 3. Plug was drilled out at 6 pm 12,18,1988 and 5 ft of new hole was drilled with 6½ bit when main engine on the rig failed. Operations | | ing Dec. 16, 1988, Set | 11 feet of 95/ | 8" conductor pipe. |
| of 7° surface casing which was cemented and circulated by Halliburton Services late the same day at 11 PM. 50 saks of class A cement with 2% Calcium Chloride and gel flush. Slurry volume was 59 cu. ft. The casing used was 17 lbs in weight. Approximate cement slurry temperature was 60 F. when mixed. 2. After lengthy repairs on rig, casing was tested to 700 psi with pressure drop to 650 psi in 45 minutes. This test was done on December 18, 1988 at Approximately noon cement having set about 36 hrs. Compressive cement strength was over 3,000 psi calculated. 3. Plug was drilled out at 6 pm 12,18,1988 and 5 ft of new hole was drilled with 6½ bit when main engine on the rig failed. Operations | did not cement | conductor, then drilled | 1 8 3/4 hole an | d set 249' feet |
| Services late the same day at 11 PM. 50 saks of class A cement with 2% Calcium Chloride and gel flush. Slurry volume was 59 cu. ft. The casing used was 17 lbs in weight. Approximate cement slurry temperature was 60 F. when mixed. 2. After lengthy repairs on rig.casing was tested to 700 psi with pressure drop to 650 psi in 45 minutes. This test was done on December 18, 1988 at Approximately noon cement having set about 36 hrs. Compressive cement strength was over 3,000 psi calculated. 3. Plug was drilled out at 6 pm 12,18,1988 and 5 ft of new hole was drilled with 6½ bit when main engine on the rig failed. Operations | | | | |
| 2% Calcium Chloride and gel flush. Slurry volume was 59 cu. ft. The casing used was 17 lbs in weight. Approximate cement slurry temperature was 60 F. when mixed. 2. After lengthy repairs on rig casing was tested to 700 psi with pressure drop to 650 psi in 45 minutes. This test was done on December 18, 1988 at Approximately noon cement having set about 36 hrs. Compressive cement strength was over 3,000 psi calculated. 3. Plug was drilled out at 6 pm 12,18,1988 and 5 ft of new hole was drilled with 6½ bit when main engine on the rig failed. Operations | | | | |
| The casing used was 17 lbs in weight. Approximate cement slurry temperature was 60 F. when mixed. 2. After lengthy repairs on rig, casing was tested to 700 psi with pressure drop to 650 psi in 45 minutes. This test was done on December 18, 1988 at Approximately noon cement having set about 36 hrs. Compressive cement strength was over 3,000 psi calculated. 3. Plug was drilled out at 6 pm 12,18,1988 and 5 ft of new hole was drilled with 6½ bit when main engine on the rig failed. Operations | | | | |
| temperature was 60 F. when mixed. 2. After lengthy repairs on rig, casing was tested to 700 psi with pressure drop to 650 psi in 45 minutes. This test was done on December 18, 1988 at Approximately noon cement having set about 36 hrs. Compressive cement strength was over 3,000 psi calculated. 3. Plug was drilled out at 6 pm 12,18,1988 and 5 ft of new hole was drilled with 6½ bit when main engine on the rig failed. Operations | 2% Calcium Chic | pride and get flush. Siv | irry volume was | Jy cu. It. |
| After lengthy repairs on rig, casing was tested to 700 psi with pressure drop to 550 psi in 45 minutes. This test was done on December 18, 1988 at Approximately noon cement having set about 36 hrs. Compressive cement strength was over 3,000 psi calculated. Plug was drilled out at 6 pm 12,18,1988 and 5 ft of new hole was drilled with 6½ bit when main engine on the rig failed. Operations | The casing used | was 17 lbs in weight. | Approximate cer | ment slurry |
| pressure drop to 650 psi in 45 minutes. This test was done on December 18, 1988 at Approximately noon cement having set about 36 hrs. Compressive cement strength was over 3,000 psi calculated. 3. Plug was drilled out at 6 pm 12,18,1988 and 5 ft of new hole was drilled with 64 bit when main engine on the rig failed. Operations | | | | |
| December 18, 1988 at Approximately noon cement having set about 36 hrs. Compressive cement strength was over 3,000 psi calculated. 3. Plug was drilled out at 6 pm 12,18,1988 and 5 ft of new hole was drilled with 64 bit when main engine on the rig failed. Operations | 2. After lengthy | epairs on rig, casing wa | as tested to 70 | 0 psi with |
| December 18, 1988 at Approximately noon cement having set about 36 hrs. Compressive cement strength was over 3,000 psi calculated. 3. Plug was drilled out at 6 pm 12,18,1988 and 5 ft of new hole was drilled with 6½ bit when main engine on the rig failed. Operations | pressure drop t | o 650 psi in 45 minutes | . This test wa | s done on |
| 36 hrs. Compressive cement strength was over 3,000 psi calculated. 3. Plug was drilled out at 6 pm 12,18,1988 and 5 ft of new hole was drilled with $6\frac{1}{4}$ bit when main engine on the rig failed. Operations | | | | |
| 3. Plug was drilled out at 6 pm 12,18,1988 and 5 ft of new hole was drilled with $6\frac{1}{4}$ bit when main engine on the rig failed. Operations | | | | |
| drilled with $6\frac{1}{4}$ bit when main engine on the rig failed. Operations | | | | |
| | | | | |
| shut down for repairs until after holidays. | | | | ed. Operations |
| ••• | shut down for 1 | epairs until after holi | .days. | |
| | | • • • | | |
| | | <u>.</u> | | |
| | | | | |

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

TITLE Vice President December 25, 198

APPROVED BY Original Signed by FRANK T. CHAVEZ