submitted in lieu of Form 3160-5
UNITED STATES

| 011111 | | | |
|------------|-----|------|----------|
| DEPARTMENT | OF | THE | INTERIOR |
| BUREAU OF | LAN | ID M | NAGEMENT |

| | | | 5. | Lease Number |
|--|---|--|----------------------------|--------------------------------|
| | | | 6. | NMNM-012293 If Indian, All. or |
| . Type of Well GAS | | | • | Tribe Name |
| | | | 7. | Unit Agreement Nam |
| Name of Operator | | | | |
| BURLING | <i>TQN</i> | | | San Juan 30-6 Unit |
| RESOURCES OIL & GAS COMPANY . Address & Phone No. of Operator | | 8. 9. | | |
| | | | San Juan 30-6 U #7 | |
| PO Box 4289, Farmington, NM 87499 (505) 326-9700 | | | | |
| | | | 10 | 30-039-25424 Field and Pool |
| Location of Well | , Footage, S | ec., T, R, M T-30-N, R-7-W, NMPM | 10. | Blanco MV/Basin DK |
| 1850'FSL, 1650'F | EL, Sec.13, | 1-30-N, R-7-W, MHI | 11. | County and State |
| | | | | Rio Arriba Co, NM |
| | TO DOY TO IN | DICATE NATURE OF NOTICE | REPORT. OTHER | DATA |
| . CHECK APPROPRIA Type of Submissi | UD JR BOY IO IN | Type of Ac | tion | |
| _X_ Notice o | f Intent | Abandonment | Change of Pl | |
| | | Recompletion _ | New Construc | tion |
| Subseque | nt Report | Plugging Back Casing Repair | Non-Routine Water Shut o | fracturing ff |
| | _ | Casing Repair _ | Conversion t | o Injection |
| n: | andonment | Altering Casing | | |
| Final Ab | andonment | Aftering Casing _X_ Other - Commingle | | - |
| . Describe Prop | osed or Comp | | ording to the a | |
| . Describe Prop | osed or Comp | X Other - Commingle leted Operations | ording to the a | |
| . Describe Prop | osed or Comp | X Other - Commingle leted Operations | ording to the a | |
| . Describe Prop | osed or Comp | X Other - Commingle leted Operations | ording to the a | |
| . Describe Prop | osed or Comp | X Other - Commingle leted Operations | ording to the a | |
| . Describe Prop | osed or Comp | X Other - Commingle leted Operations | ording to the a | |
| . Describe Prop | osed or Comp | X Other - Commingle leted Operations | ording to the a | |
| . Describe Prop | osed or Comp | X Other - Commingle leted Operations | ording to the a | |
| . Describe Prop | osed or Comp | X Other - Commingle leted Operations | ording to the a | |
| . Describe Prop | osed or Comp | X Other - Commingle leted Operations | ording to the a | |
| . Describe Prop | osed or Comp | X Other - Commingle leted Operations | ording to the a | |
| Describe Prop | osed or Comp ed to comming n hole commi | X Other - Commingle leted Operations gle the subject well accorded application will be | ording to the a submitted. | |
| Describe Prop | osed or Comp ed to comming n hole commi | X Other - Commingle leted Operations | ording to the a submitted. | |
| Describe Prop It is intende A down | osed or Comp ed to comming n hole commi | X Other - Commingle sleted Operations gle the subject well accorded application will be seen foregoing is true and | correct. | attached procedure. |
| Describe Prop | osed or Comp ed to comming n hole commi | X Other - Commingle leted Operations gle the subject well accorded application will be | correct. | |

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

San Juan 30-6 Unit 71A Blanco Mesaverde /Basin Dakota 1850' FSL, 1650' FEL Unit J, Sec. 13, T-30-N, R-7-W

Latitude / Longitude: 36° 48.624' / -107° 31.13'

AIN: 3607201 MV / 3607202 PC Commingle Procedure 1/15/02

Summary/Recommendation:

San Juan 30-6 Unit 71A was drilled and completed as a Mesaverde and Dakota dual producer in 1994. The packer test indicates possible communication between the two formations. In order to meet regulatory compliance it is recommended to remove the packer, produce both zones up a 2-3/8" tubing string. The current 3-month averages are as follows: the Mesaverde is producing 172 MCF/D and the Dakota is producing 584 MCF/D.

NOTE: ALL DEPTHS ARE MEASURED FROM KB. KB to GL was 12'.

- 1. Comply with all NMOCD, BLM and Burlington safety and environmental regulations. Test rig anchors and build blow pit prior to moving in rig. Notify BROG Regulatory (Peggy Cole 326-9727) and the appropriate Regulatory Agency prior to pumping any cement job. If an unplanned cement job is required, approval is required before the job can be pumped. If verbal approval is obtained, document approval in DIMS/WIMS. Allow as much time as possible prior to pump time in case the Agency decides to witness the cement.
- 2. MOL and RU workover rig. Obtain and record all wellhead pressures. NU relief line. Blow well down and kill with 2% KCL water if necessary. ND WH and NU BOP with stripping head. Test and record operation of BOP rams. Have wellhead and valves serviced as necessary. (A single-tubing donut and WH for 2-3/8" tubing will be needed.) Test secondary seal and replace/install as necessary.
- 3. Set a plug with wireline in DK tubing FN at 7512'. Pick up 1-1/2" tubing and RIH to the top of the Model "D" packer @ 6000' to check for fill. TOOH with 1-1/2", 2.76#, J-55 Mesaverde tubing and LD if fill is not encountered. If fill is present, TOOH with tubing, remove perf'd joint and RIH with open ended tubing. Circulate fill off of the packer and TOOH laying down 1-1/2" tubing. Pick straight up on 1-1/2", 2.9#, N-80 Dakota tubing set at 7546' (F-nipple @ 7513') to release seal assembly (set @ 5999') from Baker Model "D" packer set at 6000'. TOOH and LD tubing and seal assembly. Visually inspect tubing for corrosion. Check tubing for scale and notify Operations Engineer and Drilling Superintendent if it is present.
- 4. PU and TlH with 2-3/8" tubing and Baker Model "CJ" packer milling tool to recover the 5-1/2" Baker Model "D" packer at 6000'. Mill on packer with air/mist using a minimum mist rate of 12 bph. TOOH and lay down packer.
- 5. PU 4-3/4" bit and bit sub on 2-3/8" tubing string and round trip to PBTD (7606'), cleaning out with air/mist. NOTE: When using air/mist, minimum mist rate is 12 bph. If scale is present, contact Operations Engineer and Drilling Superintendent to determine methodology for removing scale from casing and perforations.
- 6. TIH with an expendable check on bottom, seating nipple, one joint 2-3/8", 2' x 2-3/8" pup joint, then ½ of the 2-3/8" tubing. Run a broach on sandline to insure the tubing is clear. TIH with remaining 2-3/8" tubing and then broach this tubing. Replace bad joints as necessary. CO to PBTD with air/mist using a minimum mist rate of 12 bph. Alternate blow and flow periods at PBTD to check water and sand production rates.
- 7. Land tubing no lower than 7582'. ND BOP and NU single-tubing hanger WH. Pump off expendable check. Obtain final pitot gauge up the tubing. Connect to casing and circulate air to assure that the expendable check has pumped off. If well will not flow on its own, make swab run to seating nipple. During cleanout operations the reservoir may be charged with air. As a result of excess oxygen levels that may be in the reservoir and/or wellbore, contact the Lease Operator to discuss the need for determining oxygen levels prior to returning the well to production. RD and MOL. Return well to production.

Recommended:

Approved:

Drilling Manager /

Mike Wardinsky Office - (599-4045)

Pager - (327-8932) Cellular – (320-5113) Sundry Required: Approved:

Lease Operator: Specialist:

Foreman:

Rick Gerard Gabe Archibeque Bruce Voiles

Cell: 320-2553

Pager: 324-7684

Cell: 320-2478

326-8256 Pager:

Cell: 320-2448

Pager: 327-8937