

DIVISION APPROVED PLUGGING PROGRAM

F.B. Umbarger, Trustee
Davis Pooled Unit #1
I-27-29N-11W

- (1) Clean out hole to top of 5 1/2" casing stub at 960'.
- (2) Set cement plug from 960'-700' WOC at least 6 hours.
- (3) Go in hole with tubing and tag top of plug, if cement is 700' or above go to step 4. If cement is below 700' fill to 700'.
- (4) Set a cement plug 250'-50'. Watch fluid level for one hour. If fluid does not drop significantly go to step 5. If fluid level drops more than 20' WOC 6 hours and tag top of plug #2. If below 70' fill to 50'.
- (5) Set a top plug and erect dry hole marker with 10 sacks of cement.
- (6) Fill pits. Clean and level location.

All plugs will be Class A,B or C cement with or without an accelerator.

Note: This well is leaking gas around the base of the dry hole marker and may have to be killed..