	API	# (assigned by OCD)
		30-045-07831
www.of Woll	5.	Lease Number
1. Type of Well GAS		Fee
0/10	б.	State Oil&Gas Lease
2. Name of Operator	7.	Lease Name/Unit Na
MERIDIAN OIL		Mangum SRC
	8.	Well No. 5
3. Address & Phone No. of Operator	9.	Pool Name or Wildo
PO Box 4289, Farmington, NM 87499 (505) 326-9700	1.0	Basin Dakota Elevation: 5402 GR
4. Location of Well, Footage, Sec., T, R, M		Elevation: 5402 GR
1850'FSL, 890'FEL, Sec.29, T-29-N, R-11-W, NMPM, San Juan	councy	
Type of Submission Type of Action		
y Notice of Intent Abandonment Cha.	nge of Pl Construc	ans tion
Recompletion New	-Routine	Fracturing
Wat	er Shut o	ofi .
Final Abandonment — Altering Casing — Con	version (o injection
X Other - Bradenhead repa		
13. Describe Proposed or Completed Operations It is intended to repair the bradenhead of the subject attached procedure and wellbore diagram.	well acc	cording to the
It is intended to repair the bradenhead of the subject	well acc	cording to the
It is intended to repair the bradenhead of the subject		DECEIVE JAN 3 1 1996
It is intended to repair the bradenhead of the subject		DECEIVE JAN 3 1 1996
It is intended to repair the bradenhead of the subject		PECENE JAN 3 1 1996 OIL COM. DIV
It is intended to repair the bradenhead of the subject attached procedure and wellbore diagram. SIGNATURE (VGW2) Regulatory Admi	nistrator	JAN 3 1 1996 OLL COMO DIV DISTO 3
It is intended to repair the bradenhead of the subject attached procedure and wellbore diagram. SIGNATURE (VGW2) Regulatory Admi	nistrator	JAN 3 1 1996 OLL COMO DIV DISTO 3
It is intended to repair the bradenhead of the subject attached procedure and wellbore diagram. SIGNATURE (VGW2) Regulatory Admi	nistrator	JAN 3 1 1996 OLL COMO DIV DISTO 3
It is intended to repair the bradenhead of the subject attached procedure and wellbore diagram. SIGNATURE MAN MANNE (VGW2) Regulatory Admi	nistrator	JAN 3 1 1996 OLL COMO DIV DISTO 3

WORKOVER PROCEDURE - BRADENHEAD REPAIR

MANGUM #5
Basin Dakota
Sec. 29, T29N, R11W
San Juan Co., New Mexico
EPNO 43231

- 1. Comply to all NMOCD, BLM, and MOI regulations. Conduct daily safety meetings for all personnel on location.
- 2. Test location rig anchors and repair if necessary. Prepare blow pit. MOL and RU daylight pulling unit. Install a 400 bbl frac tank and an atmospheric blow tank. NU blooie line to blow pit, and relief line to atmospheric tank. Fill frac tank with 2% KCl water.
- 3. Rig up wireline and check tubing for plunger lift equipment or other obstructions. Blow down tubing (189 jts of 2 3/8", 4.7# set at 5946') to atmospheric tank. Control well with 2% KCI water as needed. ND wellhead and NU BOP's. Test and record operation of BOP's. Send wellhead to A-1 Machine or WSI for inspection.
- 4. TIH with tubing and tag fill. Record depth. PU on tubing and strap out of hole. Visually inspect tubing, and replace joints that are in bad condition. Note any buildup of scale, and notify Operations Engineer.
- 5. PU 3 7/8" bit, casing scraper (4 1/2", 9.5 and 11.6 ppf), and CO to below perfs. POOH and PU 4 1/2" RBP. TIH and set RBP at 5850'. Pressure test casing to 1000 psig. Spot one sack of sand on top of RBP. POOH.
- 6. RU wireline unit. Run CBL (with 1000 psig pressure) from DV tool at 1688' to surface. TOC @ 468' per temperature survey. Contact Operations Engineer for design of squeeze cement.
- 7. Perforate 4 squeeze holes as close to TOC as possible. TIH with 4 1/2" fullbore packer and set 250' above perforations. (If perforating at very shallow depth, do not pick up packer, but hang off one joint of tubing in pipe rams.) Establish rate into perforations with bradenhead valve open. Max pressure 1000 psig.
- 8. Mix and pump cement. If circulation to surface has been established, pump with turbulent flow behind pipe. Displace cement to packer. Squeeze cement into perforations.

 Maintain squeeze pressure and WOC 12 hours (overnite).
- 9. Release packer and POOH. TIH with 3 7/8" bit and drill out cement. Pressure test casing to 1000 psig. Test bradenhead valve for flow. Re-squeeze as necessary to hold pressure, or to stop fluid flow at surface.
- 10. TIH with retrieving tool and retrieve RBP. POOH and LD RBP.
- 11. TIH with production tubing (seating nipple one joint off bottom, and an expendable check on bottom). Rabbit tubing in derrick before running in hole. Tag PBTD, blow well clean, and land tubing at 6060'.
- 12. ND BOP's and NU wellhead. Pump check from tubing. Obtain final gauge.

•

Recommend: Care 1/25/91

Approve: Dea 1/25/96

Drilling Superintendent

Gaye White

326-9875

Operations Engineer

Contacts:

Mangum #5


Current -- 1/23/96

DPNO 46231

Basin Dakota

1850' FSL, 890' FEL

29, T29N, R11W, San Juan County le / Latitude: 108.008377 - 36.694534



<u>istory:</u> <u>Gas</u> <u>Oil</u> 95: 1.9 Bcf 17.8 Mbo of 11/95 73 Mcf/d 0 bo

Ownership: Pipeline:
GWI: 100.00000% Williams Field Services

NWI: 87.12500% SJBT: 75.00000%