

DIVISION APPROVED PLUGGING PROGRAM

Francis L. Harvey  
Pinkstaff Estate #2  
A-29-29N-10W

- (1) Go in 4 1/2" casing with tubing and a bit and tag bottom plug at 762'. Drill on plug long enough to establish that plug is in place. If well does not have a bottom plug clean out to 947' and set a plug 947'-750' inside the 4 1/2" casing. ~~750~~
- (2) Perforate casing at 400' and set a plug 400'-250' in and outside casing. WOC 6 hours and tag plug. If plug is in place go to step 3. If below 270' fill to 250'. ~~750~~ 300
- (3) Perforate casing at 150' and set a plug 150'-50' in and outside casing. If water flow is shut off go to step 4. If not, shut well in long enough for cement to set. If water flow is shut off go to step 4. If not continue recementing until flow is stopped. 40 50k
- (4) Set a top plug and erect dry hole marker. 10 ~~10~~
- (5) Fill pits. Clean and level location.

All plugs will be Class A,B or C cement with or without an accelerator.

Note: This well is flowing a large amount of fresh water up the 4 1/2" casing.

1/3/18

Waited on a 3 3/8" drill bit, then on a sub  
lost 1 joint, sub, + bit after first plug drilled out  
Drilled to 710' after fishing back lost joint  
Hit metal at 710'  
Pulled out of hole to perforate, lost 4 joints sub + bit  
Wait to fish for next day  
Fish out all joints ~~about 60' below plug~~ Drilled to 760' Perforate at 400 only  
Set middle plug WOC 4hrs. 7sk  
Tag plug at 60' Fill rest of casing with cement water almost shut off  
Check for plug next day can't find at 25' water flowing again Must squeeze  
later  
Squeeze broadhead 84 sks  
Squeeze casing 6sks