Submit 3 Copies to Appropriate District Office

DISTRICT | P.O. Box 1980, Hobbs, NM 88240

State of New Mexico Energy, Minerals and Natural Resources Department



Form C-103 Revised 1-1-89

CONDITIONS OF APPROVAL, IF ANY:

OIL CONSERVATION DIVISION

	WELL API NO.
	30-045-08640
5.	INDICATE TYPE OF LEASE
	STATE FEE 🔀

P.O. BOX 1900, FIODDS, NWI 60240	OIL CONSER	VAIR	ON DIVISION	30-045-0	08640	
DISTRICT II P.O. Box DD, Artesia, NM 88210 Santa Fe			co St. 5. INDICATE TYPE OF LEASE			
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410	Juliu .	o ,	0.000	6. STATE OIL	& GAS LEASE NO.	
SUNDRY NOTICE (DO NOT USE THIS FORM FOR PROPODIFFERENT RESEIVED (FORM C-1) 1. TYPE OF WELL: OIL WELL GAS WELL	OR PLUG BACK TO A	7. LEASE NAME OR UNIT AGREEMENT NAME FIFIELD 5				
2. NAME OF OPERATOR	OTHER [·		8. WELL NO.		
CONOCO INC.				#1		
3. ADDRESS OF OPERATOR					IE OR WILDCAT	
10 DESTA DR., SUITE 100W,	MIDLAND, TX 7970	5-4500		BASIN D	DAKOTA	
4. WELL LOCATION						
Unit Letter $\underline{N}: \underline{790}$ Feet From The Section $\underline{05}$ Township $\underline{29N}$ Ra				e		
Codion So Tombully 2014 Na			ner DF, RKB, RT, GR, etc.)			
	IU. ELEVATION (S	TOW WINCE	rei Dr., KND, K1, GK, etc.)			
		ndicate N	lature of Notice, Report, or			
NOTICE OF INTEN	ITION TO:	_	SUE	SSEQUENT RE	PORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON		REMEDIAL WORK		ALTERING CASING	
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRILLING OPNS		PLUG AND ABANDONMENT	
PULL OR ALTER CASING			CASING TEST AND CEMENT	JOBS 🗍		
OTHER:		\neg	отнея: Slimhole to rep	air casino fai	ilures	\boxtimes
12. DESCRIBE PROPOSED OR COMPLETED	OPERATIONS (Clearly state all	pertinent (
SEE ATTACHED SUMMARY) <u>(</u> () ()()	SEP 1 GONG	ONED O 1898 DIV.	
I hereby certify that the information above is true a SIGNATURE: TYPE OR PRINT NAME: SYLVIA JOHNS (This space for States for State	Johnson		and belief. AGENT FOR CONO TELEPHONE NO. (505)		date <u>9/10/98</u>	
(This space for State CARTS IN AL SIGNED BY CAPPROVED BY	HARLIE T. PERRIN	TITLE	DEPUTY OIL & GAS INSP	ECTOR, DIST. &	DATE SEP 10	1998
1						

CONOCO, INC. FIFIELD 5 - 1

API: 30-045-08640 790' FSL & 1450' FWL, UNIT 'N' SEC. 05, T29N - R11W

- 7/29/98 Csg = 520#, Tbg = 100#. MI RU. Bled down well & killed w/ 20 bbls 1% KCl down tbg & 20 bbls down csg. Unseated tbg hanger. NU WH. NU BOP. Release Pkr & start POOH w/ 2 3/8" tbg., standing back.
- 7/30/98 Continue to POOH w/ 206 Jts 2 3/8" tbg, tallying & standing back. LD 4 1/2" Hali. R-4 Pkr. PU 4 1/2" Hali. csg scraper. RIH to 6400', stroking in areas of old squeezes & where new Pkr will be set @ 6300'. POOH w/ tbg laying down. LD scraper. Haul 2 3/8" tbg to warehouse. Spot in 2 7/8" tbg.
- 7/31/98 Csg = 220#. Bled down well. Dump 10 sxs sand down well to cover 110' of perfs. PU muleshoe slimhole collar, 2 2 7/8" x 4' tbg subs, 6 Jts 2 7/8" tbg w/ slimhole collars, & Arrow completion sys. Watson 440 full bore Pkr. RIH w/ 198 Jts 2 7/8" EUE, 6.5#, 8RD, J55 tbg. Total tbg = 204 Jts. EOT @ 6480' KB. Left Pkr unset.
- 8/3/98 Csg = 450#. Bled down well. Set Pkr @ 6282'. Loaded well & circ. up 4 1/2" 90 bbls. Circ'd cap of tbg & tbg/csg annulus. MI RU BJ Services. Start w/ 10 bbls wtr w/ red dye, for flag. Pump 63 bbls (235sxs) 13#/gal Class H cement+4%bwoc Bentonite+0.4% bwoc FL-52+ 2% bwow Potassium Chloride + 78.1% Fresh water. 2 1/2 bpm @ 700#. SD wash out pump & lines. Dropped top" Omega" plug. Start 36.3 bbl displacement. 2 1/2 bpm Max TP 2000#. Bumped plug to 2500#. SI. ** Note, Returned 9 bbls red dye flag pad to surface. Calc TOC = 120'.
- Check press. 2 7/8"=2650#. 4 1/2"= 0#. Bled down well. NU spool & BOP for 2 7/8" Csg. Lay line to flow back tank & hook-up Weatherford air/foam pkg. Tally & RIH w/ 173 Jts 1 1/4' drill pipe to stage in w/ air comp. clean out. Air pkg. limited to 800#. Clean out to 5300'.
- 8/5/98 Check well press. = 0#. Continue staging in hole, cleaning out w/ air/foam. Tag 1st plug, drill out plug & cmt. Tag 2nd plug, drill out. RIH to clean out sand over perfs to 6500'. POOH to get back inside 2 7/8".
- 8/6/98 Csg = 125#. Bled down well. RIH w 1 1/4" drill pipe to tag fill @ 6500'. Clean out w/ air/foam to 6560'. Stopped making hole. Worked 6560' hard fill , unable to make hole. POOH w/13 Jts. Let well clean up. Caught some metal & rubber cuttings in returns.
- 8/7/98 Csg = 600#. Bled down well. RIH w/ 1 1/4" drill pipe to tag fill @ 6540'. Cleaned out sand to 6560'. Drilled on hard fill till noon. Made no noticeable hole. Caught more rubber cuttings @ return line. Have determined, fill is old Mod D Pkr that could not be fished in Feb. 1997. Will clean up wellbore to this point & consider new PBTD to be 6560' KB. Perfs 6560 to 6580' cannot be uncovered. Start POOH w/ 1 1/4" drill pipe , laying down & tallying to double check depth.
- 8/10/98 Csg = 750#. Bled down well. POOH laying down 1 1/4" drill pipe. ND BOP & spool. NU WH. Prep to move. RDMO.