

OIL CONSERVATION DISTRICT NO. 1  
1000 P.O. BOXING ROAD  
AZTEC, N. MEX.

October 21, 1960

Andersen-Pritchard Oil Corporation  
U.S. National Bank Building  
1740 Broadway  
Denver, Colorado

Attn: Mr. Charles M. Heard  
District Superintendent

Re: Casing Leak, Maddox Unit #1  
N-17-30N-8W, San Juan Co. N.M.

Dear Mr. Heard:

We are unable to determine from Form C-103 which was filed to report casing repair whether or not the defective casing has been successfully repaired.

You have stated that after completion of the final squeeze job, the well flowed lead oil and sulphur water and that a temperature survey showed an anomaly at 730 feet. It therefore appears likely that there is still a hole in the production casing. We therefore cannot approve Form C-103 filed on remedial work, and are hereby directing that further action be taken to repair the casing in this well.

Yours very truly

ECA:ks

cc: Mr. A. L. Porter  
OCC, Santa Fe, N.M.

Emery C. Arnold  
Supervisor, District #3

10-1-1950

October 1, 1950

Intercom-IT Office, 211 Corporation  
211, National Bank Building  
1940 Broadway  
New York, New York

Re: The matter of the  
the above experiment

Dear Sirs:  
The following is a summary of the results of the experiment conducted on October 1, 1950.

Very truly yours,

It was unable to determine from the 1-10 which was found to require  
and the results were not as satisfactory as the first  
consequently repeated.

Now there is a question after completion of the first experiment, the  
will show that all the equipment was that a temperature survey  
of each in advance of the test. It therefore appears likely that  
there is still a lack in the production of the first experiment.  
The first 1-10, which was used in the first experiment, was the best  
that could be obtained. It was found that the results of the first  
experiment were not as satisfactory as the first.

Very truly yours,

Henry G. Smith  
Department of Research

10-1-1950

10-1-1950  
10-1-1950