## UNITED STATES

	DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT			
	Sundry Notices and Reports on We	ells g. <sub>/ 3</sub>		
	$\sigma_{\mathcal{F}_{p_0}}$		5.	Lease Number
		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		NM-03561
1.	Type of Well GAS	* 1 N. A	6.	If Indian, All. or Tribe Name
	N		7.	Unit Agreement Nam
2.	Name of Operator			
	BURLINGTON RESOURCES OIL & GAS COMPANY			
		<del></del>	8.	
3.	Address & Phone No. of Operator	•		Grenier B #5
	PO Box 4289, Farmington, NM 87499 (505) 326-970	U	9.	<b>API Well No</b> . 30-045-20055
4	Location of Well, Footage, Sec., T, R, M	<del></del>	10	Field and Pool
• •	1710'FSL, 1040'FWL, Sec.6, T-29-N, R-10-W, NMPM		10.	Basin Dakota
	L		11.	County and State
	•			San Juan Co, NM
12.	CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTI	Action		
	_X_ Notice of Intent Abandonment	Change		
	Recompletion			
	Subsequent Report Plugging Back	Non-Rou	tine E	Fracturing
	Casing Repair Final Abandonment Altering Casing	Water Si		
	Aftering Casing X_ Other - Tubing		IOII CC	o injection
13.	Describe Proposed or Completed Operations			
	It is intended to repair the tubing in the sub according to the attached procedure and	-		
	according to the attached procedure and	wellbore di	.agram	·•
	<b>!</b>	DECES N APR 15		
				March 1997

I hereby certify that the foregoing is true and correct. Machueld (KM2) Title Regulatory Administrator Date 4/9/97\_\_\_\_ (This space for Federal or State Office use)
APPROVED BY S Duame W. Spencer Title Date APR 1 4 1997 \_\_\_\_Title \_ CONDITION OF APPROVAL, if any:

## PROCEDURE TUBING REPAIR / PLUNGER INSTALLATION

GRENIER B NO. 5
DP # 25664
Basin Dakota
1710' FSL, 1040' FWL
Unit L, Sec. 6, T29N, R10W, San Juan County, NM
Lat/Long: 36°45.11" - 107°55.79"

**Project Summary:** The Grenier B No. 5 is a Dakota well drilled in 1967 which has never been pulled. Earlier this year we attempted to operate a plunger on this well but were unsuccessful due to a hole in the tubing (we believe). We propose to repair the tubing and purchase a plunger lift for this well.

- 1. Test rig anchors, prepare blow pit. Comply to all NMOCD, BLM and BROGC safety regulations.
- 2. MIRU daylight PU with air package. Kill well with 2% KCI water. ND wellhead NU BOP. Drop in hole and tag fill. POOH with 2-3/8" tubing. Visually inspect tubing and replace any corroded joints.
- 3. If fill covers perforations then clean out to PBTD with air.
- 4. Hydrotest tubing in hole with expendable check, 1 joint 2-3/8" tubing, SN and 2-3/8" tubing to approximately 6720'. ND BOP, NU wellhead. Pump out plug and blow well in. Drop spring and plunger and kick well off. RDMO PU, turn well to production.

		Approve:	Coperations Engineer			
		Approve:	Drilling Su	perintendent		
		Concur:	Production	Superintendent		
Contacts:	Operations Engineer	Kevin Midkiff		326-9807 (Office) 564-1653 (Pager)		
	Production Foreman	John	ny Ellis	326-9822 (Office) 327-8144 (Pager)		

Spud: 1st Delivered:

Elevation:

4/18/67 8/18/67 5856' GL 5867' KB

4/97:

According to Lease


Operator, well may have hole in tubing.

## Grenier B #5

Current -- 4/4/97

DPNO: 25664 Dakota

1710' FSL, 1040' FWL Unit L, Sec. 6, T29N, R10W, San Juan County, NM Lat/Long: 36°45.11", 107°55.79"



TD @ 6875'

2nd Stage: 375 sxs Cl. C w/12% gel, 12-1/2# gil., 0.4% HR-7.

3rd Stage: 340 sxs Cl. C, 12% gel, 0.4% HR-7.

## Burlington Resources Well Data Sheet

PNO: 25664 Well Name: GRENIER B S  Footage: 1710' FSL & 1040' FWL Unit: L Sect: 06 Town	Meter #: 34 :: 029N Range: 010W		2005500 Formation: DK
Dual: NO Commingled: NO Curr. Compressor: No Install Date:	Prev. Compressor: Yes Last Chg Date: 02/97		
CASING:			
Hole Size: 12 /// 776	nediate Lor	ngstring / Liner	Longstring / Liner
Casing: $\frac{25}{2}$ $\frac{1}{2}$ $\frac{1}{2}$ $\frac{1}{2}$ $\frac{1}{2}$ $\frac{1}{2}$ $\frac{1}{2}$ $\frac{1}{2}$ $\frac{1}{2}$ $\frac{1}{2}$	- 20	<del></del>	
Hole Size: $12/U$ $77/8$ Casing: $8^{5/8} 2U^{2} J - 5^{5} J 4/2^{2} 10.5$ Casing Set @: $303'$ $6837$ Cement: $250 5 \times 5 $ class $e$ $DV Tooler$	/	stage -	
Cement: 250 5x5 class 1 DV Toole	2319'5 4026'	40 5x5 Cl. C	
w/ 270 CoCl, 12 stage	300 565 +		
	ally +062 Hobel-9 0	1230 ge/+	
2nd Stuge-	375 545 el. c		
+ 12% gel, 1	12/2 gilsonita		
+ 0.4% H			
TOC: Saif, By: Cire. TOC: Surf.		By:	TOC: By:
WELL HISTORY:		E	
		<u>Formatio</u>	
Orig. Owner: Azter 0:1860s Spud Date: 04/18/67	SJ	<del></del> !	сн 3800'
GLE: 5856' First Del. Date: 08/18/67	NA NA		MF
KB: <u>5867'</u> MCFD: 5543 TD: <u>6875'</u> BOPD:	AOF OA		PL 4525' GP 5754' GH 6504' GRRS 6558'
	- KT		GP 5754
PBD: 6750 BWPD: —	- FT		GH 6504'
Completion Treatment: 6810' 20'; Flac w/ 500	20/40 PC 2:	204'	GRRS 6558
sd. and 5000# 10/20 sd. w/ 22,900	CIBPOLISO CK		DK 6677'
Squeeze w/50 sx class C, set C	18F@ 8750 CK		
6623'-6710': Frac w/ 71,180 gal. and 50,000" 20/40 sd, 18,000"	Vater		
30,000 27,40 10, 18,000	128 30,		
CURRENT DATA:	T	ubing: 2 3/8 4	1.7 to 6703'x
Pers: 6810'-20' (2 SPF) - Squeeze ceme. 6623'-25', 6635'-37', 6678'-6710'	nted	Packer:	
0025 25, 8655 37, 8678 -8770		p Size:	
		String:	
	Nou :	oung.	
PULLING HISTORY / REMARKS:			
Last Rig Date: Last Rig AFE Type:	Last Workovei	r: I	ast WO AFE Type:
Remarks: None			
4/97 - According to lease Operator, w	(2)/ 2004 1004	a hole in	+1- +1
μ	- · · · · · · · · · · · · · · · · · · ·	a hole in	the tubing
Workover Required: No 165			
Prod Ops Project Type: - Tubing Repair Area Team Pro	· · · · · · · · · · · · · · · · · · ·	Reviewed	By: Houn Midkiff
Prod Ops Project Status: - Inventory Area Team Proj		Date Review	ved: 4/3/97
Date Submitted	I To Team:	Date Print	ted: 4/3/97