

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 100A-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☐ OIL WELL ☐ GAS WELL ☒ OTHER	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR TENNECO OIL COMPANY	8. FARM OR LEASE NAME MOORE
3. ADDRESS OF OPERATOR P.O. BOX 3249, ENGLEWOOD, CO 80155	9. WELL NO. 4A
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 960' FSL, 850' FEL	10. FIELD AND POOL, OR WILDCAT BLANCO MESAVERDE
	11. SEC., T., R., M., OR BLM. AND SURVEY OR AREA SEC 5, T30N, R8W
14. PERMIT NO.	15. ELEVATIONS (Show whether by TP, SP, etc.) 6521' GL
	12. COUNTY OR PARISH SAN JUAN
	13. STATE NM

RECEIVED

OCT 08 1986

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
(Other)

XX

PCLL OR ALTER CASING
MULTIPLE COMPLETE
ABANDON*
CHANGE PLANE

SUBSEQUENT REPORT OF:

WATER SHUT-OFF
FRACTURE TREATMENT
SHOOTING OR ACIDIZING
(Other)

REPAIRING WELL
ALTERING CASING
ABANDONMENT*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

TENNECO REQUESTS PERMISSION TO REPAIR THE REFERENCED WELL FOR A POSSIBLE CASING LEAK. SEE ATTACHED PROCEDURES.

RECEIVED
OCT 10 1986
OIL CON. DIV.
DIST. 2

18. I hereby certify that the foregoing is true and correct

SIGNED

[Signature]

TITLE

SR. ADMIN. ANALYST

DATE 10/2/86

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

ah 7

*See Instructions on Reverse Side
NMOCC

APPROVED

OCT 09 1986

DATE

[Signature]
AREA MANAGER
FARMINGTON RESOURCE AREA

425'

6001W/2/RJS

LEASE Moore

WELL NO. 4A

CASING:

9 5/8 "OD, 36 LB, K-55 CSG/W 400 SX

TOC @ surf . HOLE SIZE 12 1/4 DT: 2/13/77

REMARKS Circ cmt

7 "OD, 23 LB, K-55 CSG/W 625 SX

TOC @ surf . HOLE SIZE 8 3/4 DT: 2/15/77

REMARKS Circ. cmt.

4 1/2 "OD, 10.5 LB, K-55 CSG.W/ 250 SX

TOC @ TOL . HOLE SIZE 6 1/4 DATE 2/19/77

REMARKS Reversed cmt.

TUBING:

2 3/8 "OD, 4.7 LB, J-55 GRADE, 8 RD, EUE CPLG

LANDED @ 5554' . SN, PACKER, ETC. SN @ 5524'

 "OD, LB, GRADE, RD, CPLG

LANDED @ . SN, PACKER, ETC.

PUMP RODS ANCHOR

DETAILED PROCEDURE:

1. MIRUSU. Blow down tbg/csg. Kill well w/ 1% KCL wtr.
2. NDWH. NUBOP.
3. POOH w/tbg. ** TBG. may be stuck.*
4. RIH w/4-1/2" fullbore retrievematic pkr and Model "C" RBP in tandem. Set RBP @ $\pm 4700'$. Pull up 2 stands, set pkr, PT RBP to 1000 psi.
5. Release pkr. Pull up & set pkr @ $\pm 3375'$. P.T. below pkr to 1000 psi. PT backside to 1000 psi. If 4-1/2" csg tests ok, release pkr, POOH and procede to Step 6. If 4-1/2" csg leaks, spot 2 sx sd on RBP and squeeze as follows: isolate leak. Set pkr $\pm 600'$ above leak and squeeze w/150 sx Class b cmt w/2% CaCl. Upon achieving squeeze, check for flowback. Release pkr and reverse tbg. clean. Reset pkr and pressure squeeze to 1000 psi. SDON. Release pkr. POOH w/ tbg and pkr. RIH w/ 3-7/8" bit & DO cmt. POOH w/tbg & bit. Note: If leak in 7" csg was noted, RIH w/4-1/2" pkr and PT squeeze to 1000 psi. If 7" csg tested ok, Pt squeeze to 1000 psi. Resqueeze if necessary. Procede to Step 7.

3344'

3496'

Perfs:
4758'-
5551'

5554'

5663'

5674'

LEASE NAME: Moore WELL NUMBER: 4A

Dump 25x sd on RBP.

6. RIH w/ 7" fullbore pkr and isolate leak. Set pkr $\pm$ 250' above leak and squeeze w/ 150 sx Class B cmt w/ 2% CaCl. Upon achieving squeeze, check for flowback. Release pkr and reverse tbg clean. Reset pkr and pressure squeeze to 1000 psi overnight. Release pkr and POOH. RIH w/ 6-1/4" bit and D.O. squeeze. PT to 1000 psig. Resqueeze if necessary. POOH w/bit and tbg.
7. RIH w/ retrieving head on tbg. C/O w/nitrogen foam to RBP. Release RBP & POOH.
8. RIH w/ 2-3/8" tbg and SN 1 jt up. RIH past bottom perf @ 5551'. Call Denver if perfs are covered. Pull up and land tbg @ $\pm$ 5500'.
9. NDBOP. NUWH. Swab in MV.
10. RDMOSU. Return well to production.