UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT

Sundry Not	ces and Reports on Wells
1. Type of Well GAS	5. Lease Number SF-078716-A 6. If Indian, All. or Tribe Name
2. Name of Operator BURLINGTON RESOURCES OIL	JAN 2000 Unit Agreement Nam RECEIVED OIL CON DIV DIST 3
3. Address & Phone No. of Opera PO Box 4289, Farmington, NM 87	99 (505) 326-9700 9. API Well No.
4. Location of Well, Footage, S 1540'FNL, 1020'FEL, Sec.18,	
	ICATE NATURE OF NOTICE, REPORT, OTHER DATA
Type of Submission _X_ Notice of Intent	Type of Action Abandonment Change of Plans Recompletion New Construction
Subsequent Report	Plugging Back Non-Routine Fracturing Water Shut off
Final Abandonment	Altering Casing Conversion to InjectionX_ Other - Tubing Repair
13. Describe Proposed or Comp It is intended to repair procedure.	eted Operations he tubing in the subject well according to the attached
14. I hereby certify that the Signed Signed Old	foregoing is true and correct.

Hubbell 3E

Mesa Verde/Dakota Commingle 1540 FNL and 1020' FEL Unit H, Section 18, T29N, R10W

Latitude / Longitude: 36° 43.7347'/ 107° 55.1807'
DPNO: 3432601/3432602
Tubing Repair Procedure

Project Summary: The Hubbell 3E was drilled in 1980. The tubing was pulled in 9/98 when the Mesa Verde zone was added. We propose to pull the tubing, check for fill and replace any worn or scaled tubing. This well is currently not producing. A recent attempt at swabbing this well showed that the tubing is plugged. Combined estimated uplift is 150 MCFD. Cumulative production is 725 MMCF for the Dakota and 52 MMCF for the Mesa Verde.

- 1. Hold safety meeting. Comply with all NMOCD, BLM and Burlington safety and environmental regulations. Test rig anchors and build blow pit prior to moving in rig. Notify BROG Regulatory (Peggy Bradfield 326-9727) and the appropriate Regulatory Agency prior to pumping any cement job. If an unplanned cement job is required, approval is required before the job can be pumped. If verbal approval is obtained, document approval in DIMS/WIMS. Allow as much time as possible prior to pump time in case the Agency decides to witness the cement job.
- 2. MOL and RU workover rig. Obtain and record all wellhead pressures. NU relief line. Blow well down and kill with 2% KCl water if necessary. NU BOP with stripping head. Test and record operation of BOP rams. Have wellhead and valves serviced as necessary. Test secondary seal and replace/install as necessary.
- 3. The Mesa Verde/Dakota tubing is 2-3/8", 4.7#, J-55 set at 6550'. Release donut, pick up additional joints of tubing and tag bottom (record depth.) PBTD should be at +/- 6624'. TOOH with tubing. Visually inspect tubing for corrosion and replace any bad joints. Check tubing for scale build up and notify Operations Engineer.
- 4. If fill covers any perforations then TIH with 3-7/8" bit and a watermelon mill on 2-3/8" tubing to below perforations, cleaning out with air/mist. PU above the perforations and flow the well naturally, making short trips for clean up when necessary. TOOH with tubing. NOTE: When using air/mist, minimum mist rate is 12 bph.
- 5. TIH with one joint of 2-3/8" tubing with an expendable check on bottom and a seating nipple one joint off bottom. Run a broach on sandline to insure that the tubing is clear. Land tubing at approximately 6550'. ND BOP and NU WH. Pump off expendable check. Connect to casing and circulate air to assure that expendable check has pumped off. If well will not flow on its own, make swab run to SN. RD and MOL. Return well to production.

Recommended:

Drilling Superingendent

Jbe Michetti
Office - 326-9764

Pager - 564-7187